



FALCON-AIR

ONG KIM BENG  
BLK 519A TAMPINES CENTRAL 8 #08-09  
SINGAPORE 521519

Attention : Motor Claim Department  
Contact : 82002838

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D  
GST REG. NO.: 19-9501140-D

Estimate : ES003490

Date : 10/07/2019  
Vehicle Num. : SLS981B  
Make/Model : MAZDA 3 SKYACTIV  
Chassis/Eng# : JM6BN22A8H0167625  
Accident Date : 09/07/2019  
Claim No. :  
Reference : TP NTUC VS AXA  
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LIST ITEMS :		
1.	1	REAR BUMPER		1,048.00
2.	1	REAR BUMPER TOW COVER		18.50
		List TotalS\$ :		1,066.50
		20.00% Discount S\$ :		213.30
				853.20
		LABOUR :		
		TO REMOVE/REFIX REVERSE SENSOR & CHECK WIRING		80.00
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER		400.00
		TO REPAIR INNER PANEL INCLUDES KNOCKING & REPLACEMENT OF PARTS		300.00
		Labour Total S\$ :		780.00

SingDollars : One Thousand Six Hundred Thirty-Three & Cents Twenty Only

E. & O.E.

Total S\$ : 1,633.20



for FALCON AIR AUTO SERVICES PTE LTD

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ▪ No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg