



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 22/04/2020

Survey Details:

Date of loss	7-Jul-19
Date of appointment	11-Jul-19
Date of survey	11-Jul-19
Location of survey	96 MOTORSPORTS PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKQ 3387U
Make and Model	TOYOTA COROLLA AXIO(1496cc)
Date of registration	11/21/2014
Excess	
Market Value	\$47,000
Parf Rebate	\$40,108
Nett Loss	\$6,892

Repair details:

Initial Estimate	\$ 8,517.30
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 515.25
Check items (estimate)	\$ -
Labour	\$ 450.00
Total	\$ 965.25
Lump Sum(if applicable)	\$ 750.00
Number of days for repair	3



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

OID rear ended third party.

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 802.50	\$ 802.50
Loss of use (4days x \$60.00)	\$ 240.00	NIL
Loss of rental (4days x \$100)(w/GST)	NIL	\$ 428.00
Loss of income	NIL	NIL
LTA search fees	\$ 7.45	\$ 7.45
Others	NIL	NIL
Proposed Total	\$ 1,049.95	\$ 1,237.95