

2nd Accident 08/01/02.

#119.



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

Page No. 1

Vehicle No. SLV1136C TOYOTA CHR

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	FRONT FENDER RH		733.980.00	bt/
1	FRONT FENDER SPLASH SHEILD RH		121.50 253.00	de/
1	FRONT FENDER ARCH RH		220.00	de/
1	FRONT BONNET		2550.00	Rx
1	FRONT BONNET HINGE LH & RH @ \$110.00		220.00	x NN
1	FRONT BUMPER		1236.70 1850.00	de/
2	FRONT BUMPER SIDE RETAINER LH & RH @ \$120.00		240.00	de/ R4 de/
1	FRONT BUMPER FOG LAMP GRILLE RH		125.00	de/ CUT
1	FRONT BUMPER FOG LAMP RH		540.00	de/ NN
1	FRONT BUMPER CENTRE CHROME GRILLE		315.00	x NN
1	FRONT BUMPER LOWER MOULDING		318.00	cut/
1	FRONT BUMPER LOWER SPOILER		200 + 600 980.00	de/ 800
1	FRONT BUMPER SIDE LAMP		240.00	cut/
1	FRONT WASHER TANK W/MOTOR		342.00	x NN
1	FRONT HEADLAMP RH		1310.00	cut/
1	FRONT DOOR RH		NN 1320.00	x
1	FRONT INNER DOOR BOARD RH		590.00	x NN
1	FRONT DOOR LOWER MOULDING RH		242.00	x NN
1	FRONT DOOR UPPER MOULDING RH		211.00	x NN
1	FRONT DOOR GLASS RUN CHANNEL RH		142.00	x NN
1	FRONT DOOR LOWER TRIM COVER		342.00	x NN
1	FRONT DOOR BLACK TAPE		25.00	x NN
1	FRONT DOOR LOCK RH		520.00	x NN
1	FRONT DOOR POWER WINDOW REGULATOR RH		NN 585.00	x
1	REAR DOOR RH		NN 1420.00	x
1	REAR INNER DOOR BOARD RH		490.00	x NN
1	REAR DOOR GLASS RUN CHANNEL RH		142.00	x NN
1	REAR DOOR LOWER MOULDING RH		242.00	x NN
1	REAR DOOR UPPER MOULDING RH		211.00	x NN
1	REAR DOOR LOWER TRIM COVER RH		342.00	x NN
1	REAR DOOR BLACK TAPE RH		25.00	x NN
1	REAR DOOR POWER WINDOW REGULATOR RH		NN 585.00	x NN
1	REAR FENDER ARCH RH		NN 210.00	x
1	FRONT ROCKER PANEL RH		NN 645.00	x
1	FRONT SHOCK ABSORBER RH		456 592.00	bt/
1	FRONT LOWER ARM RH		298.00	bt/
1	FRONT TIE ROD RH		145.00	x NN
1	FRONT WHEEL BEARING RH		278.00	bt/
1	FRONT KNUCKLE ARM RH		398.00	bt/
			20483.00	
		less 25%	5120.75	25%
			15362.25	

445 + 6329.20

5080.65

4746.90

6774.20

5080.65

SPECIAL NETT ITEMS				
1 SET	FRONT FENDER INNER SHEILD CLIPS		80.00	20 new ✓
1 SET	FRONT BUMPER CLIPS		120.00	30 new ✓
1	FRONT FENDER " HYBRID " EMBLEM		85.00	new ✓
5	FRONT DOOR SMALL STICKER @\$35.00		175.00	100 new X NN
1	FRONT BODY BIG STICKER		300.00	X NN
1	FRONT FENDER GRILLE RH		310.00	new ✓
1 SET	DOOR VISOR		280.00	X NN
1	FRONT 18" TYRE RH		350.00	X NN
1	FRONT SPORT RIM RH		980.00	500. + 100
Total Parts			18042.25	

1045

945 + 100



ACE AUTOLUTION PTE LTD
 13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
 Singapore 417807
 Tel: 6702 4282 Fax: 6702 4202

Page No. 2

Vehicle No. SLV1136C TOYOTA CHR

S/N	DESCRIPTION	REPAIRER'S ESTIMATE	OUR ASSESSMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	2200.00	700 + 100 ⁸⁰⁰
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1800.00	700 + 100 ⁸⁰⁰
3	To remove, refix wiring system at accident damage areas and check for proper function	150.00	30.
4	To perform anti-rust treatment on affected areas	180.00	40.
5	To check wiring and focus headlamp beam	150.00	30.
6	To clear fault code with diagnostic computer and reset to specification.	250.00	100.
7	To remove and replace / refix front & rear door inner parts fitting etc rhs	150.00	X ^{NN}
8	To conduct computerised wheel alignment test	120.00	80.
9	To remove and replace front undercarriage parts rhs	350.00	✓ 150? ^{1830 + 100 + 100}
Labour Total :		5350.00	
TOTAL (PARTS & LABOUR):		23392.25	2030

Tan Kah 97495740 WP
 12/7/19 06 days
 Lumpsum
 Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be approved by LKK
- Is subject to final approval by Insurance Company

Acknowledged by Repairer

Signature:

Date:

5080.65

1045

2030

8155.65

L/S\$6500

7 DAYS #

~~1741.90~~ ~~XXXXXXX~~

~~945~~ ~~XXXX~~

~~1830~~ ~~XXXX~~

~~7521.90~~ ~~XXXXXXX~~

~~4/5/6500~~ ~~XXXXXXX~~

~~XXXXXXX~~ ~~6 days~~