

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC
 Mr Jessen Johann Heinrich
 9A Swiss Club Road

Singapore 288146

Closed by : Patricia Kueh Anak S
 Svc Consultant :
 Remarks : Mr Jessen Johann Hei

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 1
 Inv.date. : 11/07/2019
 WIP No. . : 24771
 Veh.In/Out:
 *Tel.No. . : Mobile: 91715159
 Reg.No. . : SMK6558G
 Reg.date . : 18/04/2019
 Mileage .. : 0
 Chassis No: SADHA2A11K1F72749

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE FRT DOOR LH, REAR DOOR LH,REAR BUMPER, FRT DOOR MOULDING LH, REAR DOOR MOULDING LH,ETC	0	3150.00	0	3,150.00	S	2700
800	TO PUTTY SPRAYPAINT ON FRT DOOR LH, REAR DOOR LH, REAR BUMPER,ETC	0	2800.00	0	2,800.00	S	2400
802	TO TRANSFER FRT DOOR LH PARTS	0	500.00	0	500.00	S	✓
802	TO TRANSFER REAR DOOR LH PARTS	0	500.00	0	500.00	S	✓
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	510.00	0	510.00	S	✓
0031	TO REPLACE REAR RIM LH	0	50.00	0	50.00	S	✓
419	WHEEL ALIGNMENT	0	280.00	0	280.00	S	✓
	PANEL-DOOR FRT LH <i>TOH</i>	1.0 EA	3354.40		3,354.40	S	✓
	PANEL-DOOR REAR LH <i>bu</i>	1.0 EA	3321.70		3,321.70	S	✓
	MOULDING DOOR FRT LH <i>sch</i>	1.0 EA	448.60		448.60	S	✓
	MOULDING DOOR REAR L <i>sch</i>	1.0 EA	714.10		714.10	S	✓

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC

Mr Jessen Johann Heinrich
9A Swiss Club Road

Singapore 288146

Closed by : Patricia Kueh Anak S
Svc Consultant :
Remarks : Mr Jessen Johann Hei

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 2
Inv.date. : 11/07/2019
WIP No. . : 24771
Veh.In/Out:
*Tel.No. . : Mobile: 91715159
Reg.No. . : SMK6558G
Reg.date. : 18/04/2019
Mileage . : 0
Chassis No: SADHA2A11K1F72749

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount G
	MOULDING-BODY SIDE ?	1.0 EA	341.90			341.90 S
	FINISHER LHF ?	1.0 EA	169.50			169.50 S
	FINISHER LOWER LHF ?	1.0 EA	158.50			158.50 S
	FINISHER LOWER LHR ?	1.0 EA	148.70			148.70 S
	FINISHER UPPER LHR ?	1.0 EA	495.50			495.50 S
	SEAL-DOOR FRT ne /	1.0 EA	176.10			176.10 S
	SEAL-DOOR REAR ne /	1.0 EA	177.00			177.00 S
	WHEEL-ROAD-ALLOY sea /	1.0 EA	5644.90			5,644.90 S
	LINER-WHEELARCH sea /	1.0 EA	158.20			158.20 S
	COVER-BUMPER REAR repair	1.0 EA	1887.40			1,887.40 S
	PANEL-VALANCE X	1.0 EA	878.00			878.00 S
	MOUNTING-BRACKET X	1.0 EA	811.60			811.60 S
	BRACKET-BUMPER X	1.0 EA	177.50			177.50 S
	BRACKET-BUMPER X	1.0 EA	177.50			177.50 S
	MOUNTING-BRACKET X	1.0 EA	113.70			113.70 S
	MOUNTING-BRACKET X	1.0 EA	113.70			113.70 S
	BRACKET-BUMPER X	1.0 EA	56.80			56.80 S

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC
 Mr Jessen Johann Heinrich
 9A Swiss Club Road

Singapore 288146

Closed by : Patricia Kueh Anak S
 Svc Consultant :
 Remarks : Mr Jessen Johann Hei

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 3
 Inv.date. : 11/07/2019
 WIP No. . : 24771
 Veh.In/Out:
 *Tel.No. . : Mobile: 91715159
 Reg.No. . : SMK6558G
 Reg.date. : 18/04/2019
 Mileage . : 0
 Chassis No: SADHA2A11K1F72749

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BRACKET-BUMPER <i>X</i>	1.0 EA	56.80			56.80	S
	PATCH-TAPE <i>m</i>	1.0 EA	30.30			30.30	S
	BODY PANEL SEALANT <i>XX</i>	1.0 EA	883.20			883.20	S
	ADHESIVE SEALER FL2 <i>m</i>	1.0 EA	669.10			669.10	S
	SOUND DEADENING PAD <i>m</i>	2.0 EA	250.00			500.00	S

Resul
Hp 900 10068
8 days
12/07/19 @ 1400
Resin before paint

Labour Total 7,790.00
 Parts Total 21,664.70
 Package Total 0.00

Gross Total. 29,454.70
 Net..... 29,454.70
 GST @ 7.0% 2,061.83
 Total..... 31,516.55
 Paid..... 0.00
 Please Pay.. 31,516.55

GST: S=StdRated; O=OutOfScope; Z=ZeroRated