

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : JESSICA WONG HUI TING
 21 FERNVALE CLOSE
 22-03 RIVERTREES RESIDENCES
 SINGAPORE 797460
 TEL: 91112823
 ATTN:

Estimate No: **MC1900524**
 Date: 11 Jul 2019
 Policy No: PNPV2019-00004194
 Veh Reg No: **SLX7431A**
 Make/Model: VOLKSWAGEN GOLF
 TSI TL

Your Ref No: SLX7431A
 Claim Type: Third Party *AG*
 Accident Date: 14/06/2019
 TP Veh Reg No: SBX622E

LKIC
2-4

Not Authorised
Resurvey By paint
2 days

Estimate Repair Cost to Vehicle No :SLX7431A

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BUMPER	<i>Buclw</i> 1 PC	1,056.55	✓
2 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	96.30	X
3 REAR BUMPER CLIPS	12 PC	30.00	✓
4 NO PLATE LAMP	2 PC	58.50	X
5 REAR BUMPER TOW COVER	1 PC	23.65	X
		1,265.00	
	Less 10%	126.50	1,138.50
Special Nett			
6 NUMBER PLATE	1 PC	<i>PL</i> 35.00	X
7 REVERSE SENSOR	1 SET	200.00	7
		235.00	235.00
LABOUR			
8 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>101</i>
9 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	<i>501</i>
10 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD. TO KNOCK & REPAIR REAR END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00	<i>200</i>
11 TO SPRAY REAR BUMPER	1 PC	400.00	<i>200</i>
		900.00	900.00

Total S\$ 2,273.50

Add GST @ 7% 159.15

Total Amount Payable S\$ 2,432.65

TOTAL: SINGAPORE DOLLAR TWO THOUSAND FOUR HUNDRED THIRTY TWO AND CENTS SIXTY FIVE ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Third party survey is on a "Without Prejudice" basis
- No legal modification is allowed

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE