



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19012375/Apa3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KIAN CHUAN			Date : 20-03-2020	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YP 2127A	Veh. Inspected	SLP 1287G
	Policy No.		Coverage (\$)	0.00
	Claim No.	S9M01TQ3	Excess (\$)	0.00
	Assign From	KIAN CHUAN	Assign Date	12/07/2019
2. Vehicle Particulars & Condition				
	Make & Model	SUBARU FORESTER	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JF1SJGK85HG089248	Colour	BLACK
	Odometer	21804	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm
	L/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm
	R/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm
	L/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/07/2019	Inspection Date	12/07/2019
	Survey held at	8 KAKI BUKIT AVE 4 #08-46 PREMIER		
	Repairer	SK AUTOMOBILE PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	