

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(VL: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT YES / NO ; TP GIA REPORT YES / NO

Insured Liability: % Final ? Yes / No

SPE 18 C



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

5

If NO or B 28, Ass. Lia:

Repair Cost: (-/651)

SS 4930.30

Loss of Rental (LOR):

SS 500.00

(

5

days) x \$100

Loss of Use (LOU):

SS -

(\$

x

days)

Loss of Income (LOI):

SS -

(\$

x

days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 5432.30

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 5432.30

Name 1:

Premium Automobiles Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: \$320

Surveyor

REF:

AG

12420/Ad

-Su- DINE

ASSIGNMENT

From: _____ Date: 17/7/19

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SFE18C

at Workshop m/s

Prantrum

of

Upi

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 18.8 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SFE18C Yr Regn: 2017, Nov

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 SB. cc 999.

Colour: Black. A/C: Insured / Std / NI / NA

Sp. Reading: 31362 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU2228VAJA041060.

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16.

R: 205/55R16.

BS / DUN / EXNOVA ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 17/09/19

Survey held at Premium.

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TPA/G.
	PIP - \$4607.76 (Red \$8590.24/651)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos _____

Others _____

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____

☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0856/2019/GW
Date	:	16-Jul-19

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	ALAN KOH TRADING CO
Driver's name	:	Mr. Koh Joo Ling
Address	:	33A Jalan Malu Malu
	:	Singapore 769694
Telephone	:	HP +65 81261398
Type of Claim	:	Third Party Claims
Policy No.	:	1700078024
Vehicle No	:	SFE 18 C
Model Code	:	Audi A3 SB 1.0 TF
Model / Year	:	14/11/2017
Engine No	:	CHZ 571093
Chassis No	:	WAUZZZ8V9JA041060
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	12-Jul-19
Place of Accident	:	Hougang Ave 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFE 18 C

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To remove and transfer rhs front door's multi-lock system and power window devices.	S/N \$ 280.00 X	
3	To dismantle and renew front bumper, rhs front fender and rhs front door. Reinstall all parts removed.	\$ 2,800.00 500	
4	To respray front bumper, rhs front fender, rhs front door and rear doors. ✓ ✓ <i>Rear Fender</i>	\$ 3,300.00 2750	
5	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓	
6	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>7,212.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFE 18 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Regis</i>	\$ 1,698.00	+
2	FRONT BUMPER GUIDE SECTION-RH <i>new</i>	\$ 35.00	+
3	FRONT FENDER-RH <i>Regis</i>	\$ 778.00	+
4	FRONT FENDER BRACKET-RH <i>3 new</i>	\$ 43.00	+
5	FRONT FENDER BRACE-RH	\$ 88.00	+
6	FRONT DOOR-RH <i>Regis</i>	\$ 2,073.00	+
7	FRONT DOOR OUTER SEAL-RH <i>new</i>	\$ 146.00	+
8	BONDING AGENT <i>new</i>	\$ 45.00	+
9	FRONT DOOR CATCH-RH <i>2 new</i>	\$ 96.00	+
10	DATE PLATE FOR TYRE PRESSURE	\$ 26.00	+
11	FRONT RIM-RH <i>let</i>	\$ 651.00	520.00
12	RUBBER VALVE <i>new</i>	2 \$ 7.00	+
13	SUNDRIES <i>Net</i>	\$ 300.00	4.96.
TOTAL SPARE PARTS CHARGES		:	\$ 5,986.00
TOTAL LABOUR CHARGES		:	\$ 7,212.00
GRAND TOTAL		:	\$ 13,198.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lij*
Surveyed Date : *17/07/19.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 05 days.*

LRK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0856/2019/GW
Date	:	16-Jul-19

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian,

5 days - ok - Jy - 02 Sep 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	ALAN KOH TRADING CO
Driver's name	:	Mr. Koh Joo Ling
Address	:	33A Jalan Malu Malu
	:	Singapore 769694
Telephone	:	HP +65 81261398
Type of Claim	:	Third Party Claims
Policy No.	:	1700078024
Vehicle No	:	SFE 18 C
Model Code	:	Audi A3 SB 1.0 TF
Model / Year	:	14/11/2017
Engine No	:	CHZ 571093
Chassis No	:	WAUZZZ8V9JA041060
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	12-Jul-19
Place of Accident	:	Hougang Ave 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFE 18 C

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
2	To remove and transfer rhs front door's multi-lock system and power window devices.	S/N	\$ 280.00	
3	To dismantle and renew front bumper, rhs front fender and rhs front door. Reinstall all parts removed.		\$ 2,800.00	\$ 500.00
4	To respray front bumper, rhs front fender, rhs front door and rear doors.		\$ 3,300.00	\$ 2,750.00
5	To renew rhs front rim and carry out wheel alignment.	S/N	\$ 280.00	\$ 280.00
6	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 7,212.00	\$ 4,082.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFE 18 C

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,698.00	
2	FRONT BUMPER GUIDE SECTION-RH	\$ 35.00	
3	FRONT FENDER-RH	\$ 778.00	
4	FRONT FENDER BRACKET-RH	\$ 43.00	
5	FRONT FENDER BRACE-RH	\$ 88.00	
6	FRONT DOOR-RH	\$ 2,073.00	
7	FRONT DOOR OUTER SEAL-RH	\$ 146.00	
8	BONDING AGENT	\$ 45.00	
9	FRONT DOOR CATCH-RH	\$ 96.00	
10	DATE PLATE FOR TYRE PRESSURE	\$ 26.00	
11	FRONT RIM-RH	\$ 651.00	\$ 520.80
12	RUBBER VALVE	2 \$ 7.00	
13	SUNDRIES	\$ 300.00	\$ 4.96
TOTAL SPARE PARTS CHARGES		\$ 5,986.00	\$ 525.76
TOTAL LABOUR CHARGES		\$ 7,212.00	\$ 4,082.00
GRAND TOTAL		\$ 13,198.00	\$ 4,607.76

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

View Received Message

This mail is associated with :

***SFE18C (9664834824SG)
[SMF1646U]**

TP
ALAN KOH TRADING CO
Jul 12 2019 4:00PM
[SANIAH BINTE AHMAD]
Premium Automobiles Pte Ltd

Reply	Reply All	Mark as Unread	Print Message	Delete Message	Forward
-------	-----------	----------------	---------------	----------------	---------

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 15/07/2019 15:38 PM.
To LKK_HQ
Subject No OI GIA Report

Hi,

Please be informed that no OI GIA report received till date.
Please find OI details below for your further action.

OI name: SANIAH BINTE AHMAD

Address:
19b Hillview Park #01-01
Singapore 669555

Contact No: 91717583

Regards,
Wah Xin

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG19012420/da3

16 July, 2019

SANIAH BINTE AHMAD

19B Hillview Park

#01-01

Singapore 669555

Dear Sirs,

ACCIDENT INVOLVING SMF 1646U AND SFE 18C ON 12/07/2019 ALONG/ AT HOUGANG AVE 1

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a **THIRD PARTY** claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Carlor Chan

Claims

Tel : 6841 5792

Fax: 6741 4108

Email : Jiale@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

View Received Message

This mail is associated with :

***SFE18C (9664834824SG)
[SMF1646U]**

TP
ALAN KOH TRADING CO
Jul 12 2019 4:50PM
[SANIAH BINTE AHMAD]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 30/12/2019 11:37 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5432.30) - SFE18C - Claim Handler: Syed-Yusoff, Saliha

Approved:5432.30:mandate approval is subject to final repair bill & ATA

DOCUMENTS SUMMARY

There are no documents.

Date: 23/8/2019

To: Premium Automobiles Pte Ltd

Dear Sir / Madam,

Authorization Letter for issue rental charges to Ms. Koh Joo Ling

Vehicle No: SFE18C

We, Alan Koh Trading Co. Pte. Ltd authorize to issue the Rental Charges to Ms. Koh Joo Ling
For accident happen on 12/7/2019.

Thank You.

ALAN KOH TRADING CO. PTE LTD



Name: Alan Koh Trading Co. Pte. Ltd.



益隆貿易私人有限公司

ALAN KOH TRADING CO PTE LTD

22 Yio Chu Kang Road #02-21 Highland Centre
Singapore 545535. Tel: 62889066 / 32983008 Fax: 62852676

BREAKDOWN OF PAYMENT

Vehicle No: SFE18C

Accident on 12/7/2019 at HOUGANG AVE 1

Involving vehicle/s SMF1646U

1) Repair cost \$ 4,930.30 Payable to: Premium Automobiles Pte Ltd

2) GIA/LTA search fee \$ 2.00 Payable to: Premium Automobiles Pte Ltd

3) Loss of Use or Rental Car \$ 500 Payable to: KOH JOO LING

4) Medical fees \$ _____ Payable to: _____

5) Others \$ _____ Payable to: _____



The following ~~is~~ described on this Cover Note is hereby **HELD COVERED** as the terms and conditions of the policy issued to the E

Vehicle No. : SFE-18C
Cover Note No. : 1700078024
Endorsement No. :
Issued Date : 13 Nov 2017

Make/Model	AUDI A3 Sportback 1.0 TFSI S tronic				
Engine Capacity/Tonnage	999.00 CC	Sum Insured	Market Value	First Year of Registration	2017
Driver Restriction	NA	Off Peak Car	No	Insuring with COE/PAF	Yes

This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Flycatcher's business

This Policy does not cover use for hire or reward, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered imperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 199) and Section 90 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - 10

Windscreen : \$100

Named Driver and Excess (where applicable)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR PLAINS RELATED REPAIRS)

1 Audi Customer Service Center, Add: 55, Ulu Road 1 Singapore 408660 63961352

For better Approved Reporting Centre (ARC) Authorized Reporters, please contact our 24-hour incident emergency hotline at +65 8338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception date stated on this cover note, please contact AIG immediately. Furthermore, certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 109), Part IV of the Road Transport Act, 1967 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia). For Corporate Policies, this Cover Note is valid for 90 days from the commencement date of the period of insurance.

0504125264

PREMIUM LEASING - OKT

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159238

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE Office of Open Year

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jul 2019 Edit Reg		17 Jul 2019 00:00 Edit Adj Rpt	S\$4,607.76 Edit Estimates	S\$4,607.76 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: SANIAH BINTE AHMAD , ID: S1412200A									
Main Claimant: ALAN KOH TRADING CO , Co. Reg. No.: 198303683Z									
Vehicle Reg. No.: SFE18C		Date of Loss: 12/07/2019 16:00 - :59 19 Months and 28 Days From LTA Reg Date (Man Yr)							
Claim Type: TP / 9664834824SG		Policy/Cover Note No.: 1800120434 (Comprehensive)							
Vehicle Reg. No. (Insured): SMF1646U		Policy No. (Claimant): 1700078024							
Excess:									
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 24/07/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (30/12/2019): Alert - Adj Mandate Approved (S\$5432.30) - SFE18C - Claim Handler: Syed-Yusoff, ... - AIG_SG_EXPRESS (22/11/2019): Alert - Adj Mandate Maintained - SFE18C - Claim Handler: Syed-Yusoff, Saliha - AIG_SG_EXPRESS (15/11/2019): Alert - Adj Mandate Maintained - SFE18C - Claim Handler: Syed-Yusoff, Saliha - AIG_SG (15/07/2019): No OI GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFE18C (9664834824SG)
[SMF1646U]
TP
ALAN KOH TRADING CO
Jul 12 2019 4:50PM
[SANIAH BINTE AHMAD]
Premium Automobiles Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Video

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/07/19 19:28	Video - Accident TP VIDEO	Load MP4	

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/11/19 14:01	Adjuster Immediate Advice	Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/10/19 09:22	General View	Load JPG	☒
2	23/10/19 09:22	General View	Load JPG	☒
3	23/10/19 09:22	General View	Load JPG	☒
4	23/10/19 09:22	General View	Load JPG	☒
5	23/10/19 09:22	General View	Load JPG	☒
6	23/10/19 09:22	General View	Load JPG	☒
7	23/10/19 09:22	General View	Load JPG	☒
8	23/10/19 09:22	General View	Load JPG	☒
9	23/10/19 09:22	General View	Load JPG	☒
10	23/10/19 09:22	General View	Load JPG	☒
11	23/10/19 09:22	General View	Load JPG	☒
12	23/10/19 09:22	General View	Load JPG	☒
13	23/10/19 09:22	General View	Load JPG	☒
14	23/10/19 09:22	General View	Load JPG	☒
15	23/10/19 09:22	General View	Load JPG	☒
16	23/10/19 09:22	General View	Load JPG	☒
17	23/10/19 09:22	General View	Load JPG	☒
18	23/10/19 09:22	General View	Load JPG	☒
19	23/10/19 09:22	General View	Load JPG	☒

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/07/19 08:37	TP GIA REPORT	Load PDF	
2	16/07/19 08:17	Non reporting letter	Load PDF	
3	18/07/19 10:22	TP ESTIMATE-MARKED	Load PDF	
4	12/11/19 14:13	GIA SEARCH FEE	Load PDF	
5	12/11/19 14:13	LOD	Load PDF	
6	12/11/19 14:13	RENTAL RECEIPT	Load PDF	
7	15/11/19 11:58	TP ESTIMATE - MARKED (FINAL)	Load PDF	
8	22/11/19 10:02	TP MARKED ESTIMATE (INDICATED CALCULATION)	Load PDF	
9	08/01/20 09:24	WORKSHOP INVOICE	Load PDF	
10	08/01/20 09:24	AUTHORISATION TO ACT FORM	Load PDF	
11	08/01/20 09:24	Release Voucher	Load PDF	
12	08/01/20 09:24	LETTER TO OI	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/07/19 10:05	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMF1646U (Insd veh)	Model:	AUDI A3 999CC TFSI S
	SFE18C (TP veh)		TRONIC (LED) (A)
Date of Accident:	12/07/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	14,121.86
Final Repair Cost	:	\$	4,930.30
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	500.00 5 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	5,432.30

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: 5

BOLA Liability: 100 (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	:	\$ 5,432.30
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

08 Jan
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19012420/ADA3Q2

Date: 08/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800120434
 Claimant: SFE18C Insured Vehicle No: SMF1646U
 Vehicle No: SFE18C
 Date of Loss: 12/07/2019 Nature of Claim: TP Claim No: 9664834824SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFE18C
 Make & Model: AUDI A3, 999cc TFSI S TRONIC (LED) (A) Engine No: CHZ571093
 Reg. Date: 14/11/2017 (Man. Year: 2017) Chassis No: WAUZZZ8V9JA041060
 Colour: Black Odometer: 31362 km
 Engine Capacity: 999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,986.00	525.76	5,460.24	91.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,212.00	4,082.00	3,130.00	43.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,198.00	4,607.76	8,590.24	65.09
+ GST 7.00/7.00% (S\$)	923.86	322.54	601.32	65.09
Nett Amount (S\$)	14,121.86	4,930.30	9,191.56	65.09
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,432.30		

INSPECTION

Date of Assignment: 17/07/2019
 Date Inspected: 17/07/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
 55 Ubi Road 1
 Singapore 408699
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,698.00 FS	*- FS
2	1		*FRONT BUMPER GUIDE SECTION -RH	Not Necessary	35.00 FS	*- FS
3	1		*FRONT FENDER -RH	Repair	778.00 FS	*- FS
4	1		*FRONT FENDER BRACKET -RH	Not Necessary	43.00 FS	*- FS
5	1		*FRONT FENDER BRACE -RH	Not Necessary	88.00 FS	*- FS
6	1		*FRONT DOOR -RH	Repair	2,073.00 FS	*- FS
7	1		*FRONT DOOR OUTER SEAL -RH	Not Necessary	146.00 FS	*- FS
8	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
9	1		*FRONT DOOR CATCH -RH	Not Necessary	96.00 FS	*- FS
10	1		*DATE PLATE FOR TYRE PRESSURE	Not Necessary	26.00 FS	*- FS
11	1		*FRONT RIM -RH	Cut	651.00 FS	*520.80 FS
12	2		*RUBBER VALVE	Not Necessary	7.00 FS	*- FS
13	1		*SUNDRIES	Necessary	300.00 FS	*4.96 FS
Total Parts (\$\$)					5,986.00	525.76

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES	New	280.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND RHS FRONT DOOR .REINSTALL ALL PARTS REMOVED	New	2,800.00	500.00
4	TO RESPRAY FRONT BUMPER ,RHS FRONT FENDER ,RHS FRONT DOOR AND REAR DOORS	New	3,300.00	2,750.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			7,212.00	4,082.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >