



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC19003121/Etd3s2-1

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 22-07-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 6275T	Veh. Inspected	FBJ 4211E
Policy No.	Z/18/VC00/101370	Coverage (\$)	0.00
Claim No.	18/19/19/VC00/021385	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	15/07/2019

2. Vehicle Particulars & Condition

Make & Model	BAJAJ PULSAR 200 NS	c.c	200
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	MD2A36FZ1ECL57093	Colour	RED
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	110/80-17	PIRELLI	7 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70-17	PIRELLI	7 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	28/01/2019	Inspection Date	20/02/2019
Survey held at	UNIVERSAL MOTORS PTE LTD BLK 1006 BUKIT MERAH LANE 2 #01-04 SINGAPORE 159762		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------