



FASTECH AUTO PTE LTD  
 BLK1 KAKI BUKIT AVE 6  
 #01-46,48,50 AUTOBAY  
 SINGAPORE 417883

not Authorized  
 date  
 15/7/19  
 1/5 @ 10,050  
 John

VEHICLE NO: JSR 1131

QTY	PARTICULAR				
1 PCS	BOOTLID	486.30			
1 PCS	BOOTLID 'VIOS' EMBLEM	57.50		Seat/Buc	\$845.30
1 PCS	BOOTLID 'G' EMBLEM			rec	\$60.80
1 PCS	BOOTLID 'X' EMBLEM			rec	\$45.50
1 PCS	BOOTLID REAR LOGO			rec	\$45.50
1 PCS	BOOTLID OUTER CHROME MOULDING			rec	\$48.00
2 PCS	BOOTLID HINGES @\$105.00			11	\$420.10
1 PCS	BOOTLID WEATHERSTRIP			11	\$210.00
1 PCS	BOOTLID INNER LOCK	199.50		11	\$288.20
1 PCS	REAR BUMPER	481.30		11	\$299.50
1 PCS	REAR BUMPER LOWER SKIRTING	650.00		11	\$650.60
2 PCS	REAR BUMPER SIDE RETAINERS @\$85.00			11	\$950.00
2 PCS	REAR BUMPER PDC SENSORS @\$250.00			11	\$170.00
1 PCS	REAR BUMPER REINFORCEMENT	312		shold	\$500.00
2 PCS	REAR BUMPER REFLECTORS @\$185.00	95x2=190		DD	\$422.10
1 PCS	REAR END PANEL	581.10		CRD	\$370.00
1 PCS	REAR END PANEL TOP GARNISH	220.00		Body	\$666.80
2 PCS	TAILLAMP @\$485.10	328x2=650		11	\$305.00
2 PCS	TAILLAMP HOUSING PANELS @\$350.00			CRD	\$970.20
2 PCS	REAR FENDERS @\$977.10			11	\$700.00
1 SET	REAR FENDER INNER TRIM CLIPS			11	\$1,954.00
1 PCS	REAR FLOOR PANEL			11	\$60.00
1 PCS	REAR FLOOR PANEL TOP BOARD	380.60		11	\$911.20
2 PCS	REAR FLOOR PANEL SIDE SPONGES @\$420.10	311x2=622		11	\$488.50
2 PCS	REAR FENDER INNER TRIMS @\$465.00			11	\$840.20
1 PCS	REAR REVERSE CAMERA			11	\$930.00
1 PCS	FRONT BUMPER	469.10		11	\$385.00
1 PCS	FRONT BUMPER CENTRE GRILLE	350.50		11	\$820.00
1 PCS	FRONT BUMPER LOWER SKIRTING	650.00		11	\$411.10
2 PCS	FRONT BUMPER SIDE REATINERS @\$65.00			11	\$950.00
1 SET	FRONT BUMPEER CLIPS			11	\$130.00
2 PCS	FRONT BUMPER LAMPS @\$305.00	205x2=410		11	\$60.00
1 PCS	FRONT BUMPER CAMERA	420.00		11	\$610.00
1 PCS	FRONT BUMPER TOW COVER			11	\$450.00
2 PCS	FRONT BUMPER PDC SENSORS @\$255.00	195x2=390		11	\$30.00
2 PCS	FRONT BUMPER FOG LAMPS @\$409.10			11	\$510.00
1 PCS	FRONT GRILLE	325.60		11	\$818.20
1 PCS	FRONT GRILLE LOGO			11	\$688.20
2 PCS	HEADLAMPS @\$1480.00	858.80x2=1717.60		11	\$68.50
2 PCS	AIR CON SIDE GARNISHS @\$212.00			11	\$2,960.00
1 PCS	AIR CON CONDENSOR	988.00		11	\$424.00
1 PCS	FRONT BRACE PANEL			11	\$1,280.00
1 PCS	FRONT SUPPORT PANEL			11	\$88.50
1 PCS	RADIATOR			11	\$799.10
1 PCS	RADIATOR FAN ASSY			11	\$1,480.00
1 PCS	FRONT BUMPER reinforcement			11	\$595.00
				DD	\$250.00

(252)

1 PCS	FRONT SUPPORT PANEL TOP GARNISH		11	\$199.00	X
1 PCS	BONNET		11	\$645.10	X
2 PCS	FRONT FENDERS@\$480.10	252	11	\$960.20	X
1 PCS	BONNET INNER LOCK		11	\$105.00	✓
				\$28,868.40	
	S.NETT				
1 PCS	REAR END PANEL SEALANT		11	\$50.00	✓
1 PCS	REAR LICENECE PLATE W/HOLDER		11	\$50.00	X
	LABOUR CHARGES:				
	TO CHECK WIRING			\$80.00	30
	TO DISMANTLE & REPLACING PDC SENSOR			\$80.00	50
	TO TRANSFER BOOTLID MECHANISM			\$100.00	60
	TO DISMANTLE & REFIX REAR EXHAUST		11	\$100.00	X
	TO DISMANTLE & REPLACING REVERSE CAMERA			\$80.00	40
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY			\$120.00	80
	TO SPRAY RUST PROOFING			\$120.00	80
	TO REFILL AIR CON GAS			\$150.00	100
	LABOUR FOR PANEL BEATING & REPLACING PARTS			\$1,800.00	1400
	TO PUTTY & SPRAY PAINTING			\$2,200.00	1800
				\$28,868.40	
			TOTAL	\$33,798.40	1800

3690

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

11 862.30  
 252  
 8896.72