

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

15/07/2019 12:41

JOB-NO: 50111837

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHC7067B

TRANS: AUTO

CHASSIS: KMHLB41UMGU086822

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4DFDU606406

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRIAGHTEN & PANEL BRAT REAR PORTION (4 DAYS)	1.00	1,600.00	0.00	1,600.00		Y	<u>200</u>
2 PUTTY & RESPRAY REAR BUMPER (3 PANEL)	1.00	750.00	0.00	750.00		Y	<u>200</u>
3 CHECK WIRING	1.00	150.00	0.00	150.00		Y	<u>X</u>
4 CHECK WIRING & LIGHTING SYSTEM & DIAGNOSTIC (CLEAR FAULT CODE)	1.00	120.00	0.00	120.00		Y	<u>X</u>
5 R&R SPARE TYRE / BOARD / TRIM / CARPET & ETC	1.00	180.00	0.00	180.00		Y	<u>X</u>
6 RESPRAY END PANEL (INNER&OUTER)	1.00	300.00	0.00	300.00		Y	<u>X</u>
TOTAL:		3,100.00	0.00	3,100.00			
<u>MATERIALS</u>							
1 Rear Bumper <i>repair ?</i>	1.00	699.58	139.92	559.66	L	Y	
2 REAR BUMPER REINFORCEMENT	1.00	484.40	96.88	387.52	L	Y	
3 REAR BUMPER REINFORCEMENT ARMS (L) <i>X</i>	1.00	98.63	19.73	78.90	L	Y	
4 REAR BUMPER REINFORCEMENT ARMS (R) <i>X</i>	1.00	98.63	19.73	78.90	L	Y	
5 REAR BUMPER SPONGE <i>?</i>	1.00	89.62	17.92	71.70	L	Y	
6 REAR BUMPER RETAINER (L) <i>X</i>	1.00	42.63	8.53	34.10	L	Y	
7 REAR BUMPER RETAINER RH <i>X</i>	1.00	42.63	8.53	34.10	L	Y	
8 REAR BUMPER REFLECTOR LHS <i>X</i>	1.00	43.85	8.77	35.08	L	Y	
9 REAR BUMPER RETAINER RHS <i>X</i>	1.00	43.85	8.77	35.08	L	Y	
10 REAR BUMPER LOWER SPOILER <i>de</i>	1.00	228.40	45.68	182.72	L	Y	
11 REAR END PANEL <i>X</i>	1.00	629.95	125.99	503.96	L	Y	
12 REAR BUMPER TOP PROTECTOR PAD <i>X</i>	1.00	150.00	0.00	150.00	S	Y	
13 REVERSE SENSOR <i>X</i>	1.00	300.00	0.00	300.00	S	Y	
14 REAR BUMPER ADS STICKER <i>m</i>	1.00	150.00	0.00	150.00	S	Y	
TOTAL:		3,102.17	500.45	2,601.72			
TOTAL PARTS & LABOUR :		6,202.17	500.45	5,701.72			

EXCESS/LOADING:\$ 0.00

No. Of Day: 2 days

RE-SURVEY: BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY: 15 / 07 / 19 P1555

SURVEYED BY: 157 Ryan

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

CONTACT NO: 90010018 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002
Ding Auto User 2

ESTIMATOR
STA AUTOCENTRE
TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: