

TO :

FAX NO:

ESTIMATE REPORT

1ST Quotation

15/07/2019 12:58

JOB-NO: 50111834

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHA9222S

TRANS: AUTO

CHASSIS: KMHLB41UMGU079761

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4DFU553157

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,800.00	0.00	1,800.00		Y	700
2 RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00		Y	200
3 RESPRAY LHS FENDER	1.00	250.00	0.00	250.00		Y	200
4 RESPRAY FRONT LHS DOOR	1.00	350.00	0.00	350.00		Y	200
5 RESPRAY FRONT LHS SIDE MIRROR ASSY	1.00	100.00	0.00	100.00		Y	80
6 R&R FRONT LHS DOOR COMPONENT	1.00	200.00	0.00	200.00		Y	60
7 CHECK WIRING & LIGHTING SYSTEM & DIAGNOSTIC (CLEAR FAULT CODE)	1.00	150.00	0.00	150.00		Y	60
8 CALIBRATION OF FRONT LHS POWER WINDOW	1.00	80.00	0.00	80.00		Y	X
TOTAL:		3,180.00	0.00	3,180.00			
<u>MATERIALS</u>							
1 FRONT BUMPER <i>repair de</i>	1.00	699.68	139.94	559.74	L	Y	
2 FRONT BUMPER RETAINER LH <i>22.22</i>	1.00	42.32	8.46	33.86	L	Y	
3 FRONT LHS FENDER <i>bt</i>	1.00	759.60	151.92	607.68	L	Y	
4 FRONT INNER SHIELD LHS <i>X</i>	1.00	186.12	37.22	148.90	L	Y	
5 SIDE MIRROR LH <i>bro</i>	1.00	518.40	103.68	414.72	L	Y	
6 SIDE MIRROR GLASS LHS <i>bro</i>	1.00	62.40	12.48	49.92	L	Y	
7 FRONT LHS DOOR ASSY <i>bt</i>	1.00	2,256.83	451.37	1,805.46	L	Y	
8 FRONT LHS DOOR GLASS CHROME Moulding Outer <i>at</i>	1.00	180.00	36.00	144.00	L	Y	
9 FRONT LHS INNER SHIELD CLIPS <i>re</i>	1.00	35.00	0.00	35.00	S 25	Y	
10 FRONT BUMPER ADS STICKER <i>re X</i>	1.00	150.00	0.00	150.00	S	Y	
11 FRONT LHS ADS STICKER <i>re</i>	1.00	120.00	0.00	120.00	S 80	Y	
12 FRONT DOOR ADS STICKER LH <i>re</i>	1.00	150.00	0.00	150.00	S 120	Y	
TOTAL:		5,160.35	941.07	4,219.28			
TOTAL PARTS & LABOUR :		8,340.35	941.07	7,399.28			

EXCESS/LOADING:\$ 0.00

No. Of Day:

*5 days*RE-SURVEY: BEFORE AFTER PAINTING
PART-BY-PART OR LUMP SUM \$DATE OF SURVEY: 15/07/19 01550

SURVEYED BY:

Rafael

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

CONTACT NO: 900 0068 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: