


Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:36

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014338 Date : 09/10/2019 Order : SKF6691D Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SKF6691D (V 12909) Regn Date: 03/12/2010 Mileage: 182886 WIP No.: 59963

Model: A4 1.8T FSI MU 8K202H Chassis: WAUZZZ8K6AA174865 Engine: CDH095109 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1200.00	1.00	-1,200.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW BONNET AND LHS HEADLIGHT. REPAIR FRONT BUMPER. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND BONNET	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8K0853651 1QP	GRILLE (LAST) Less 020%	1.00	644.50	515.60
X	A8K0941029AK	LED HEADLAMP Less 020%	1.00	994.00	795.20
X	A8K0823029D	HOOD (LAST) Less 020%	1.00	1788.00	1,430.40
X	A8T0823126D	EDGING Less 020%	2.00	24.90	39.84
X	A8K0853037	COVER (LAST) Less 020%	1.00	52.10	41.68
X	A4G0010515	STICKER Less 020%	1.00	17.50	14.00
X	A8K0010520A	PLATE Less 020%	1.00	12.20	9.76

Parts 2,846.48
Labour 0.00
Sublet 2,902.00
Menus 0.00
Lubricant 0.00

Sub-Total 4,548.48

7% GST 318.39

Grand Total 4,866.87



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKF 6691 D

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0822/2019/GW
26 July 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 1.8TFSI MU (A)
Vehicle Chassis No. : WAUZZZ8K6AA174865
Vehicle Regn No. : **SKF 6691 D**
Vehicle Mileage : 182886 KM
Vehicle Owner : M/S Premium Leasing Pte Ltd
Certificate No : 999994451/100759904-00000
Own Damage Excess : \$1,284.00 (Incl. 7% GST)
Accident Date : 28 June 2019
Place : Car Park at 1 Pasir Ris Rise #07-03
Repair Cost : \$ 4,866.87
WIP No. : 59963
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.



Owner / Insured Signature : _____
Time : _____
Date : 31/7/19