

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL STREET #05-00
 IOB BUILDING SINGAPORE 049711

Attention : Motor Claim Department
 Contact : 63476100 Fax No. : 62244174

Estimate : TP19/038

Date : 24/07/2019
 Vehicle Num. : SFD 5142Z
 Make/Model : MAZDA 3-2018
 Chassis/Eng# : JM6BN22A8H0158976/P520451583
 Accident Date : 13/07/2019
 Claim No. :
 Reference : LYB/SFD5142Z/III/tp/sl
 Policy No. :

S/N Quantity Particular Unit Price Amount S\$

1.	1	NETT ITEMS :
2.	1	REAR DOOR/LH
3.	1	REAR DOOR WINDOW OUTER CHANNEL/LH
4.	1	REAR DOOR WINDOW FRAME GARNISH/LH
5.	1	REAR DOOR WINDOW TOP FRAME GARNISH/LH
6.	1	REAR DOOR WINDOW OUTER TRIANGULAR GARNISH/LH
7.	1	REAR DOOR RUBBER/LH
8.	2	REAR DOOR HINGES
9.	1	REAR DOOR STOPPER/LH
10.	1	REAR FENDER/LH
11.	1	REAR RIM/LH
12.	1	REAR W/SCREEN MLDG

Nett Total S\$:

1.	1	SPECIAL NETT ITEMS :
2.	1	REAR W/SCREEN SEALANT
3.	1	REAR W/SCREEN INNER SEAL

Special Nett Total S\$:

LABOUR :
 LABOUR TO REMOVE & REFIX REAR W/SCREEN

LABOUR TO REMOVE REAR LEFT INTERIOR FITTING, TRIMS

1.	1	1,049.40	✓
2.	1	147.00	X
3.	1	79.00	X
4.	1	79.00	✓
5.	1	50.90	✓
6.	1	126.80	X
7.	1	96.60	X
8.	2	38.60	X
9.	1	1,233.00	X
10.	1	432.60	✓
11.	1	123.00	X
12.	1	3,455.90	

1.	1	60.00	X
2.	1	50.00	X
3.	1	110.00	

1.	1	150.00	X
2.	1	150.00	80

CONTINUE / ...

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL STREET #05-00
 IOB BUILDING SINGAPORE 049711

Attention : Motor Claim Department
 Contact : 63476100 Fax No. : 62244174

Estimate : TP19/038

Date : 24/07/2019
 Vehicle Num. : SFD 5142Z
 Make/Model : MAZDA 3-2018
 Chassis/Eng# : JM6BN22A8H0158976/P520451583
 Accident Date : 13/07/2019
 Claim No. :
 Reference : LYB/SFD5142Z/III/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO CHECK WIRING FUNCTIONS	60.00	201
		TO COMPUTERISE WHEEL ALIGNMENT	120.00	601
		TO REMOVE TYRE ENABLE TO REPAIR RIM & FIX SAME	150.00	201
		TO TRANSFER REAR DOOR MECHANISM TO NEW DOOR	120.00	601
		TO CHECK WATER SEEPAGE	60.00	X
		TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS	120.00	301
		TO REPAIR, PANEL BEAT ON LEFT FRT AFFECTED DOOR, LEFT LOCKER PANEL, ALIGN ON AFFECTED REAR BUMPER. TO CUT & WELD ON REAR FENDER & LABOUR TO REPLACE ABOVE PARTS	1,200.00	601
		TO PUTTY, PRIMER & SPRAY PAINT ON LEFT FRT DOOR, REAR DOOR, REAR FENDER, REAR BUMPER & LEFT LOCKER PANEL USING 2K PAINT	1,300.00	8801
		Labour Total S\$:	3,430.00	



E. & O.E.

Total S\$: 6,995.90
 =====

for LIM YEW BOO SPRAY PAINT CO.