

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/AMK

Claim Type: Third Party

Accident Date: 13/07/2019

TP Veh Reg No: SHD9886K

Estimate No: ES1991744/AMK

Date: 15 Jul 2019

Policy No: MT110110

Veh Reg No: SCW1666R

Make/Model: MERCEDES BENZ E250

Chassis No: WDD2120472A525596

Engine No: 27186030356668

Reg. Date: 14/12/2011

Estimate Repair Cost to Vehicle No :SCW1666R

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 REAR LH DOOR	2,233.00	1 PC	2,233.00	✓
2 REAR LH DOOR INNER RUBBER	256.00	1 PC	256.00	50% ✓
3 REAR LH DOOR CHROME MOULDING	100.00	1 PC	100.00	✓
4 REAR LH RIM	750.00	1 PC	750.00	✓
			3,339.00	
		Less 10%	333.90	3,005.10
Labour				
5 REMOVE & REFIX REAR LH WHEEL;KNOCKING & REPAIR REAR LH FENDER,REAR LH DOOR & REALIGN THE SAME	500.00	1 LA	500.00	400 ✓
6 PUTTY & RESPRAY REAR BUMPER,REAR LH FENDER,REAR LH DOOR & ALL AFFECTED AREAS	700.00	1 LA	700.00	600 ✓
7 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	80.00	1 PC	80.00	60 ✓
8 REMOVE & REFIX REAR LH DOOR WINDOW GLASS & RESET CENTRAL LOCKING	60.00	1 LA	60.00	✓
9 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,370.00	1,370.00
			Total	SS 4,375.10
			Add GST @ 7%	306.26
			Total Amount Payable	SS 4,681.36

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: