

ASS. REC. BY:

REF: CS/FCI 19012559/Av4372

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Henry Kao of FCI Date/Time: 16/7/2019

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBB 8608K Insured: SHB 35676

at Workshop m/s Liang Hec Motor. Tel: 67474416

of 1 Kaki Bukit Ave 6 #01-62

Policy No: Claim No: D19004600 MESH

Sum Insured: Excess:

Make of Veh: D.O.A. 12/7/19
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 16/7 Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction
	Adrian ✓
	GBB 8608K X
	SHB 3567A X
17/7/19	Informed FCI pending workshop est by email
13/8/19	Adrian confirmed LS \$ 4000 (Ref 8552, 6890)

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: G888608K Yr Regn: 2010 / June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Pennzoel Partner c.c. 1560Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 386532 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF37F94XC9J24X170Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 16/07/19Survey held at Liang Hee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cp.13/8/19 Email preli revised to FCI

RECEIVED 13 AUG 2019

Note: MV: 7K
PV: 2.8K
Nett: 4.2K

Date/Time, File Pass to?

Date/Time, File Return to?

1) 13/8 - typst

2)

3)

4)

5)

6)

Preli. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date: 2X15=30

Basic & Add.

S+RS. SI

Photos

Others

TOTAL

170+305050+5063413



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref: D19004600MFSH

Our ref: CS/FC119012559/Avf3

Date: 13/8/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. GBB 8608K


We thank you for your instruction on 16/7/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16/7/2019 at the premises of M/s LIANG HEE MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$12,552.00
Revised Estimate Amount	: S\$4,000.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	15-07-2019	Our Ref No. D19004600MFSH
Accident Date	12-07-2019	Claim Type. Third Party
Insured Vehicle	SHB3567G	Third Party Vehicle. GBB8608K
Survey Location	1 KAKI BUKIT AVE 6 #01-62	
Contact Person.	DAVID	
Contact No.	67474416/ 97527252	Fax No. 67472935
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LIANG HEE MOTOR WORKSHOP	Attention. NIL
Cc : TP Solicitor	JUSEQUITY LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Adrian

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 13 August 2019 12:19 PM
To: 'CWS Motor Claims'; SUR
Cc: 'Henry Kao Cai Jié'
Subject: RE: SURVEY ASSESSMENT - D19004600MFSH/1, GBB 8608K
Attachments: GBB 8608K PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle GBB 8608K
Date of survey: 16/7/2019
Number of days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 17 July 2019 12:11 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19004600MFSH/1, GBB 8608K

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBB 8608K on 16/7/2019.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 16 July, 2019 2:04 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004600MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 17 July 2019 12:11 PM
To: 'CWS Motor Claims'; SUR
Cc: 'Henry Kao Cai Jie'
Subject: RE: SURVEY ASSESSMENT - D19004600MFSH/1, GBB 8608K

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBB 8608K on 16/7/2019.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 16 July, 2019 2:04 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004600MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



Bidded Car Plate Number for sale

Looking for auspicious numbers?

Browse our list of hottest bidded car plate numbers for sale.



Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Renewal Coe Toyota Altis 1.6A



3.18% p.a Low Interest@Gv
Finance, 2 Years
Warranty.\$2000 Down Monthly
From \$558
GV Credit Pte Ltd StarAd



Lake View
Credit Pte Ltd

view our cars

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category

Save Search

Print

Sort by Date Posted

20 results/page

2 vehicles

Search partner

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection	partner	Any	Any	2010	Any	Any	Any	Available
------------------	---------	-----	-----	------	-----	-----	-----	-----------



Peugeot Partner 1.6A HDi
SWB

\$6,800

\$7,190 /yr

28-Jun-2010

1,560 cc

-

Van

Available

Fuel Type: Diesel

6/10 Peugeot Partner 1.6 Selling Cheap, High Trade In.

Think One Automobile & Trading

Posted: 20-Jun-2010

Tags: 2010 Peugeot Partner, 2010 peugeot partner, Peugeot Partner, peugeot partner, Peugeot, Partner, partner, used Peugeot



Peugeot Partner 1.6M HDi
LWB

\$11,800

\$11,930 /yr

14-Jul-2010

1,560 cc

-

Van

Available

Fuel Type: Diesel

Please Call To Arrange For Viewing, Thanks.

Posted: 21-May-2010

Tags: 2010 Peugeot Partner, 2010 peugeot partner, Peugeot Partner, peugeot partner, Peugeot, Partner, partner, Used Peugeot

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used partner, partner Singapore, used partner Singapore, used vehicles Singapore or even buy used partner, Singapore. We have new car dealers comprising parallel importers, leatherized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com



About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

SHORTLISTED HISTORY

Compare [2]

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	311Z
Vehicle Details	
Vehicle No.:	GBB8608K
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Jul 2019
Vehicle Make:	PEUGEOT
Vehicle Model:	PARTNER 1.6 VAN (LWB) EXTN
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	10JBCB0058620
Chassis No.:	VF37F9HXC9J244170
Maximum Power Output:	-
Open Market Value:	\$21,373.00
Original Registration Date:	25 Jun 2010
First Registration Date:	25 Jun 2010
Transfer Count:	1
Actual ARF Paid:	\$1,069.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jun 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$30,189.00
COE Rebate Amount:	\$2,826.00
Total Rebate Amount:	\$2,826.00

The information contained herein is correct as at 17 Jul 2019

OK

TP 1st Cap.
Veron.

GBB8608K
Peugeot Partner
VF37F9HX09J244170

Rees Number Plate	Bent	30(SN) ✓
Rees Number Plate Holder	Deformed	30(SN) ✓
Rees Number Plate Lamp x 02	^{HP} New	48 x 2 = 96 +
Rees Bumper	Distorted	580 ✓
Rees Bumper Clips	New	30 ✓
Rees Bumper Side Holder x 02	New	65 x 2 = 130 ✓
Rees Bumper Reinforcement	Bent	520 ✓
Rees Bumper Side Garnish x 02		^{HP} New 280 x 2 = 560 ✓
Reverse Sensor	Damaged	280(SN) 200(SN)
Rees End Panel Outer	Rips	595 +
Rees End Panel Sealant	New	60(SN) +
Taillamp x 02	cracked	280 x 2 = 560 ✓
Rees LH Door	Dented	1320 —
Rees LH Door Lock	Joined	294 —
Rees LH Door Weatherstripe	cut	249 —
Rees LH Door Zines Trim Board	^{HP} New	54 +
Rees LH Door Glass Sealant	New	50(SN) ✓

GB88608K

Rear LH Door Advertisement Sticker	new	120(SN) 80(SN)	
Peugeot Wording	new	123	✓
Rear RH Door	Dented	1295	✓
Rear RH Door Lock	Jammed	294	✓
Rear RH Door Weatherstripe	at	249	✓
Rear RH Door Glass Sealant	new	50(SN)	✓
Partner Wording	?	95	✓
5 Pax Sticker	new	10(SN)	✓
70km/h Sticker		10(SN)	✓
Rear Exhaust Pipe	new	795	+
Rear Exhaust Mounting	new	35	+
Spare Tyre Holder Bracket	Best	298	✓

GBB8608K

Panel Beating
Spray Painting.
Wiring.

To undexent

To remove reverse sensor

To remove upholstery.

To transfer new LH and RH door fittings.

To remove new LH and RH door glasses.

To remove exhaust pipe

~~1400~~ 700
~~1200~~ 600

~~50~~ 30.

150 X

~~100~~ 50

~~150~~ 50

~~300~~ 120.

~~240~~ 120.

150 X.

12,552

hist: 6597

Un 10%: 5537.30

SN: 460

Labour: 1670

total: 8067.30

L/S: 4K (Nett Value)

05 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19012559/Avf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 14-08-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3567G	Veh. Inspected	GBB 8608K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004600MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	16/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	PEUGEOT PARTNER	c.c	1560	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	VF37F9HXC9J244170	Colour	GREY	
Odometer	386532	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	TOYO	6 mm	
L/H Front Tyre	195/65 R15	TOYO	6 mm	
R/H Rear Tyre	195/65 R15	TOYO	6 mm	
L/H Rear Tyre	195/65 R15	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/07/2019	Inspection Date	16/07/2019	
Survey held at	LIANG HEE MOTOR WORKSHOP 1 KAKI BUKIT AVE 6 #01-62 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 8608K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	REAR NUMBER PLATE LAMP @\$48.00	NOT NECESSARY	96.00	-
1	REAR BUMPER	DISTORTED	580.00	580.00
1	REAR BUMPER CLIPS	NECESSARY	30.00	30.00
2	REAR BUMPER SIDE HOLDER @\$65.00	NECESSARY	130.00	130.00
1	REAR BUMPER REINFORCEMENT	BENT	520.00	520.00
2	REAR BUMPER SIDE GARNISH @\$280.00	TORN	560.00	560.00
1	REAR END PANEL OUTER	TO REPAIR SEE LABOUR	595.00	-
2	TAILLAMP @\$280.00	CRACKED	560.00	560.00
1	REAR LH DOOR	DENTED	1,320.00	1,320.00
1	REAR LH DOOR LOCK	JAMMED	294.00	294.00
1	REAR LH DOOR WEATHERSTRIPE	CUT	249.00	249.00
1	REAR LH DOOR INNER TRIM BOARD	NOT NECESSARY	54.00	-
1	PEUGEOT WORDING	NECESSARY	123.00	123.00
1	REAR RH DOOR	DENTED	1,295.00	1,295.00
1	REAR RH DOOR LOCK	JAMMED	294.00	294.00
1	REAR RH DOOR WEATHERSTRIPE	CUT	249.00	249.00
1	PARTNER WORDING	NECESSARY	95.00	95.00
1	REAR EXHAUST PIPE	NOT NECESSARY	795.00	-
1	REAR EXHAUST MOUNTING	NOT NECESSARY	35.00	-
1	SPARE TYRE HOLDER BRACKET	BENT	298.00	298.00
	LESS 10% DISCOUNT		-	-659.70
			8,172.00	5,937.30
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	BENT	30.00	30.00
1	REAR NUMBER PLATE HOLDER (SN)	DEFORMED	30.00	30.00
1	REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	60.00	-
1	REAR LH DOOR GLASS SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR LH DOOR ADVERTISEMENT STICKER (SN)	NECESSARY	120.00	80.00
1	REAR RH DOOR GLASS SEALANT (SN)	NECESSARY	50.00	50.00

Report Ref No. CS/FCI19012559/Avf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	5 PAX STICKER (SN)	NECESSARY	10.00	10.00
1	70KM/H STICKER (SN)	NECESSARY	10.00	10.00
			640.00	460.00
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL OUTER.		1,400.00	700.00
	SPRAY PAINTING.		1,200.00	600.00
	WIRING.		50.00	30.00
	TO UNDERSEAL.	NOT NECESSARY	150.00	-
	TO REMOVE REVERSE SENSOR.		100.00	50.00
	TO REMOVE UPHOLSTERY.		150.00	50.00
	TO TRANSFER REAR LH AND RH DOOR FITTINGS.		300.00	120.00
	TO REMOVE REAR LH AND RH DOOR GLASSES.		240.00	120.00
	TO REMOVE EXHAUST PIPE.	NOT NECESSARY	150.00	-
			3,740.00	1,670.00
	GRAND TOTAL		12,552.00	8,067.30

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00
---	--	--	-----------------

Report Ref No. CS/FC119012559/Avf3n2

MARKET VALUE: \$7,000.00 (EST)-PAPER VALUE: \$2,800.00=NETT VALUE: \$4,200.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.