

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0022746
Teo Chuan Cheng Nick

Page 1 of 4
Your ref. TP-SLK 7873B AXA
Job No. 70683
Our ref. 19.07.29
Payment
Date 16/7/2019

Attn

Vehicle No SJH 900S
Vehicle Model : Mercedes Benz S300L
Accident on ... 10/7/2019

Not Authorized
7/16/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
1.00	Pc	Front headlamp RH	3,920.00		3,920.00 ✓
1.00	Pc	Front bumper	1,865.00		1,865.00 ✓
1.00	Pc	Front bumper washer jet cover with bracket RH	92.00		92.00 X
1.00	Pc	Rear bumper	2,010.00		2,010.00 ✓
1.00	Pc	Rear bumper inner part RH	67.00		67.00 ✓
1.00	Pc	Rear bumper side beam RH	99.00		99.00 ✓
1.00	Pc	Rear bumper chrome moulding RH	120.00		120.00 ✓
1.00	Pc	Rear bumper reinforcement	758.00		758.00 ✓
1.00	Pc	Rear bumper tow hook cover	56.00		56.00 ✓
1.00	Pc	Rear bumper parking sensor inner LH	297.00		297.00 ✓
1.00	Pc	Rear bumper parking sensor outer LH	297.00		297.00 ✓
1.00	Pc	Rear tail lamp RH	1,030.00		1,030.00 ✓
1.00	Pc	Rear fender RH	5,925.00		5,925.00 ✓
1.00	Pc	Rear boot lid side covering LH	40.00		40.00 ✓
10.00	Pcs	Rear boot lid side covering clips	8.00		80.00 ✓
1.00	Pc	Rear boot lid weatherstrip	138.00		138.00 50.00
1.00	Pc	Rear fender inner trim RH	570.00		570.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供多种形式的车身及给予快速与准确的测量方式和大铁修理除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0022746
Teo Chuan Cheng Nick

Page 2 of 4
Your ref. TP-SLK 7873B AXA
Job No. 70683
Our ref 19.07.29
Payment
Date 16/7/2019

Attn

Vehicle No SJH 900S
Vehicle Model : Mercedes Benz S300L
Accident on ... 10/7/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount	
1.00	Pc	Rear exhaust chrome tip RH	830.00		830.00	✓
1.00	Pc	Rear exhaust box	2,380.00	SVC	2,380.00	✗
1.00	Pc	Rear exhaust box connector RH	96.00	SVC	96.00	✗
1.00	Pc	Rear windscreen with moulding	2,560.00	mtg m	2,560.00	✓
1.00	Pc	Rear boot lid hinge LH	198.00	n	198.00	✗
1.00	Pc	Rear boot lid hinge RH	198.00	0.7	198.00	✓
1.00	Pc	Rear G Tronic emblem	85.00	m	85.00	✓
1.00	Pc	Rear S300 emblem	90.00	m	90.00	✓
1.00	Pc	Rear Mercedes logo emblem	50.00	m	50.00	✓
1.00	Pc	Rear boot lid chrome moulding	183.00	D. 1	183.00	✓
4.00	Pcs	Rear number plate screw rivets	8.00	m	32.00	✓
1.00	Pc	Rear tail lamp LH	1,030.00	cm	1,030.00	✓
1.00	Pc	Rear bumper chrome moulding LH	120.00	m	120.00	✓
1.00	Pc	Rear bumper beam LH	99.00	SVC	99.00	✗
1.00	Pc	Rear bumper inner part LH	67.00	SVC	67.00	✗
Special nett item:						
1.00	Pc	Rear number plate with casing	80.00		80.00	✓

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0022746
Teo Chuan Cheng Nick

Page: 3 of 4
Your ref.: TP-SLK 7873B AXA
Job No.: 70683
Our ref: 19.07.29
Payment:
Date: 16/7/2019

Attn

Vehicle No: SJH 900S
Vehicle Model : Mercedes Benz S300L
Accident on ...: 10/7/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		Labour & Misc:			
1.00		To dismantle + refix rear windscreen	180.00		180.00 <i>120L</i>
1.00		To supply sealant	40.00		40.00 ✓
1.00		To dismantle + refix rear cushion assy, rear speaker board and renew parts	180.00		180.00 <i>120</i>
1.00		To dismantle + renew front headlamp RH + front bumper, etc	300.00		300.00 <i>250</i>
1.00		To cut exhaust pipe + renew rear exhaust muffler box RH	120.00	NN	120.00 ✗
1.00		To straighten rear body including cutting and welding, to knock dents on rear fender LH, floor side panel RH and renew of parts	2,200.00		2,200.00 <i>2000</i>
1.00		To spray paint (front bumper only)	350.00		350.00 <i>300</i>

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 記) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No : EST0022746
Teo Chuan Cheng Nick

Page : 4 of 4
Your ref. : TP-SLK 7873B AXA
Job No. : 70683
Our ref. : 19.07.29
Payment :
Date : 16/7/2019

Attn :

Vehicle No : SJH 900S
Vehicle Model : Mercedes Benz S300L
Accident on : 10/7/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To spray paint (rear portion)	2,000.00		2,000.00 ¹⁵⁰⁰

Sub-Total 30,832.00
GST 7.00% 2,158.24
Total S\$ 32,990.24

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."