ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	17:10HRS
ACCIDENT DATE	15-Jul-19
BUS CAPTAIN NAME	MASRAWI BIN MASJUAY
EMPLOYEE NUMBER	

BUS REGISTRATION NUMBER	SBS6307C	
BUS TYPE (SD/DD)	SD	
BUS ROUTE NUMBER		
BUS ADVERTS (Y/N)	N	

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

Part No.		Part or Item Description	Quantity	Total Cost	
	77200892	ENTRANCE DOOR ASSY NO. 1	ged /	1 \$9,800.0	
	77015457	RUBBER SEAL FRONT DOOR BOTTOM	at/	1 \$162.3	
	77200902	STEP EDGE FRONT DOOR	ut 1	1 \$129.2	
	77201348	COVERING TO SWIVEL BAR	repair	1 \$1,456.0	
	77200121	N/S/F BUMPER	>u/	1 \$1,207.0	
				11,298.6	
			7% GST	\$892.8	
			FINAL TOTAL COST	\$13,647.4	

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)		TOTAL COST
TO REMOVE AND REPLACE DAMAGED PARTS	3 DAYS	1300 \$1,950.00
SPRAY PAINTING	2 DAYS	500 \$1,000.00
		1800
		/
1		
	7% GST	\$227.50
	FINAL TOTAL COST	\$3,477.50

PAGE :

ESTIMATED ACCIDENT REPAIR COST



SECTION 3: REPAIRS TO BUS ADVERTISMEN	T VINYLS/PANELS	(ADVERTISEMENT COS	T)
---------------------------------------	-----------------	--------------------	----

TOTAL ADVERTISEMENT REPAIR COST

SECTION 4: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST

SECTION 5: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

Date In For Repairs **Date Out From Repairs** Number of Days Under Repair

BUS TYPE (SD / DD) LOSS OF USE COST

\$1,800.00

sum	MARY
SECTION NO.	COST
1	\$13,647.44
2	\$3,477.50
3	-
4	-
5	\$1,800.00
ESTIMATED ACCIDENT REPAIR COST (1+2+3+4+5)	\$18,924.94

Rasme Hp 90010068 4 days Plp 43 17/07/09 P1545

11,298.62 677 120 325 100 14,100.82 10% 12,690 45-12,600

4 days

SUPPLEMENTARY ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	17:10HR	S	3	BUS REGISTRATION NUMBER		SBS6307C	
ACCIDENT DATE	15-Jul-19]	BUS TYPE (SD/DD) BUS ROUTE NUMBER	SD		
BUS CAPTAIN NAME MASRAWI BIN		IN MASJUAY					
EMPLOYEE NUMBER				BUS ADVERTS (Y/N)		N	
SECTION 1: PARTS &	cONSUMABLE ITEMS (I	MATERIAL COST)				
	Part No.		Part or Item Description	1		Quantity	Total Cost
- 1	77201203	SEAL	ING FRAME WITH R	UBBER	1 SET	diss	\$677.20
							677.20
						7% GST	\$47.40
					FIN	AL TOTAL COST	\$724.60
SECTION 2: ASSESSN	MENT / REPAIR / SPRAY	PAINT (LABOUR	COST)				
	LABOUR ITEM (PL	EASE SPECIFY IF ITS	ASSESSMENT, REPAIR OR	SPRAY PAINT)			TOTAL COST
	TO RE	MOVE AND REP	LACE DAMAGED PAR	RTS	1 DAY	325	\$650.00
						328	
			,				
						7% GST	\$45.50
						FINAL TOTAL COST	\$695.50
		7	aufili	TOTAL SU	PPLEMEN'	TARY FINAL COST _	\$1,420.10