

ESTIMATE TO REPAIR

VEHICLE NO. : SMM 319 J
 MAKE : HONDA
 MODEL : FREED HYBRID 1.5G AUTO
 YEAR : 2019
 CHASSIS NO : GB71093057

SURVEYOR NAME :
 DATE OF SURVEY : 29th July 2019
 TIME OF SURVEY :

DATE : 16-Jul-19
 DATE OF ACCIDENT : 12-Jul-19
 THIRD PARTY REF : SML 1561 Z / AXA

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Tailgate				\$ 1,100.00
1 pc	FREED Emblem				\$ 55.00
1 pc	HYBRID Emblem				\$ 75.20
1 pc	H Emblem				\$ 32.50
1 pc	Rear Windscreen Moulding				\$ 120.00
					\$ 1,382.70
	Less 20%				\$ 276.54
					\$ 1,106.16
1 tube	Rear Windscreen Sealant	S.Nett			\$ 40.00
	To putty and spray painting				\$ 500.00
	To transfer tailgate fittings				\$ 80.00
	To remove and refix rear windscreen glass				\$ 120.00
	To anti-rust				\$ 50.00
	Labour Charges				\$ 400.00
					2000
					Not Withstand Rehmy Bepain 3 days
TG/RA-	Total				\$ 2,296.16

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@lrm.sg

Website: www.lrm.sg

Co.Reg No.199307277D

GST Reg No.M21019086-001

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: