

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 834K

MAKE :


MODEL : HYUNDAI i40

China Taiping (LTS) TS

DATE 17/7/2019

LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>okk</i>			\$ 2,174.90
	Boot Lid Lock Upper <i>X me</i>			\$ 102.60
	Boot Lid Lock Lower <i>X me</i>			\$ 31.70
	Boot Lid 'H' Emblem <i>- me</i>			\$ 28.70
	Boot Lid CRDI Plate <i>- me</i>			\$ 27.90
	Rear Bumper <i>- Pshud</i>			\$ 553.00
	Rear Bumper Clip 10 pcs <i>- me</i>			\$ 22.00
	SUB TOTAL			\$ 2,940.80
	LESS 20%			\$ 588.16
	DISCOUNTED TOTAL			\$ 2,352.64
	Boot Lid City Cab Logo & Tel No. Sticker <i>- me</i>			\$ 30.00
	Rear Bumper Reverse Sensor <i>X me</i>			\$ 135.70
				\$ 165.70
	Labour Charge			
	Panel Beating			<i>200</i>
	Spray Painting Charge			\$ 400.00
	Wiring Charge			\$ 600.00 <i>400</i>
	Tuff Kote			\$ 50.00 <i>30</i>
	Remove/Refix Reverse Sensor			\$ 50.00 <i>30</i>
				\$ 80.00 <i>20</i>
	TOTAL LABOUR			\$ 1,180.00
	ESTIMATE TOTAL			\$ 3,698.34
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				



Kalin 1/1/19

17/7/19 10404
3 Days
43
After Repair p LK