

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Friday, 25 October 2019 5:54 PM  
**To:** Ngian, Kelvyna; Reports (LKKAUTO)  
**Cc:** SUR  
**Subject:** RE: Survey Report & Invoice of Vehicle SKP 218A Ref: CLMOMVC000003689

Dear Kelvyna,

According to surveyor, it is related to the accident. Once the tailgate replaced, it is necessary to replaced the rear windscreen, rear windscreen formed part of tailgate assembly.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Thursday, 24 October 2019 4:46 PM  
**To:** Ngian, Kelvyna <kelvyna.ngian@sg.gaig.com>; Reports (LKKAUTO) <report@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: Survey Report & Invoice of Vehicle SKP 218A Ref: CLMOMVC000003689

Dear Kelvyna,

Will check and revert.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ngian, Kelvyna <[kelvyna.ngian@sg.gaig.com](mailto:kelvyna.ngian@sg.gaig.com)>  
**Sent:** Thursday, 24 October 2019 4:38 PM  
**To:** Reports (LKKAUTO) <[report@lkkauto.com](mailto:report@lkkauto.com)>; Admin-D (LKKAUTO) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: Survey Report & Invoice of Vehicle SKP 218A Ref: CLMOMVC000003689

Dear all,

Need advice. The damage to the third party is seemingly minor, however we noted that there is a rear windscreen replacement? Is this related to the accident?

Thanks  
Kelvyna  
68046059

---

**From:** Reports (LKKAuto) <[report@lkkauto.com](mailto:report@lkkauto.com)>  
**Sent:** Tuesday, August 6, 2019 3:26 PM  
**To:** Ngian, Kelvyna <[Kelvyna.Ngian@sg.gaig.com](mailto:Kelvyna.Ngian@sg.gaig.com)>; Motor Claims <[MotorClaims@sg.gaig.com](mailto:MotorClaims@sg.gaig.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** [External] Survey Report & Invoice of Vehicle SKP 218A Ref: CLMOMVC000003689

Dear Sir / Madam,

Enclose Survey Report of SKP 218A.

Thank you.

Best Regards,

**Elaine | Reports**  
**LKK Auto Consultants Pte.Ltd.**  
Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: [report@lkkauto.com](mailto:report@lkkauto.com)  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.