

Khanchana

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

FINALIZATION FORM

ATTN TO:

LKK-STEVE

Surveyor Name and Company

Date of Accident : 13/7/2019

BILL TO:

ERGO

TP Insurer

VEHICLE REG. NO.

SLU635R

TYPE OF CLAIM:

TP

Make / Model :

XJ 5.0L AT ABS D/AB 2WD 4DR GA

COST OF CLAIMS

Parts Cost / List : \$ 7,360.04

Supp. Parts : \$ -

Special Nett : \$ 120.00

Total Parts : \$ 7,112.04

Total Labour : \$ 1,150.00

TOTAL REPAIR COST : \$ 8,262.04

Total Parts Cost/List : \$ 7,360.04

Plus / Less : 5% \$ 368.00

Total : \$ 6,992.04

Lump Sum Discount : 20% \$ 1,652.41

Lump Sum Amount: \$ 6,609.63

Final Lump Sum Amount : \$ 6,600.00

Submitted by / Date : MINOKO

No. of Repair Days: 5

Confirmed by / Date :

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLU635R**
 Vehicle Reg. Date: **7/7/2011**
 Make / Model : **JAGUAR XJ 5.0L AT ABS D/AB 2WD 4DR GAS,**
 Engine No. : **11032918333508PN**
 Chassis No. : **SAJAC22F5BLV20478**

Steve (LKK) *WHL ANL* *17/7/19*
4 days *1.45pm*
L/S
Reg AC Spg

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	FRONT BUMPER / <i>CUT</i>		\$ 3,000.30		\$ 3,000.30
2	1	FRONT BUMPER SIDE RETIANER RH / <i>DR</i>		\$ 94.50		\$ 94.50
3	1SET	FRONT BUMPER CLIPS RH / <i>MPC</i>		\$ 86.00		\$ 86.00
4	1SET	FRONT BUMPER RIVERT / <i>MPC</i>		\$ 97.00		\$ 97.00
5	1	FRONT BUMPER FOLAMP GARNISH RH <i>X</i>		\$ 272.88		
6	1	FRONT BUMPER FOGLAMP CHROME GARNISH RH / <i>CUT</i>		\$ 473.44		\$ 473.44
7	1	FRONT PARKING SENSOR RH / <i>Short</i>		\$ 428.00		\$ 428.00
8	1	HEADLAMP RH / <i>CUT</i>		\$ 3,180.80		\$ 3,180.80
9	1	HEADLAMP NOZZLE COVER RH <i>X</i>		\$ 71.60		
10	1	HEADLAMP LOWER BRACKET RH <i>X</i>		NO USE		
11	1	HEADLAMP PANEL RH <i>X</i>		NO USE		
12	1	FRONT FENDER RH <i>X R</i>		\$ 1,505.30		
13	1	FRONT FENDER INNER SHIELD RH <i>X</i>		\$ 348.60		
14	1	FRONT FENDER INNER SHIELD CLIPS <i>X</i>		\$ 86.00		
15	1	FRONT FENDER AIR DUCT RH <i>X</i>		NO USE		
16	1	FRONT FENDER EMBLEM RH <i>X</i>		\$ 388.10		
17	1	FRONT FENDER STICKER RH <i>X</i>				
18	1	FRONT RIM RH <i>X R (Local repair) cut</i>		\$ 1,826.60	\$ 120.00	100/
19	1	FRONT TYRE RH <i>X</i>			\$ -	
20	1	FRONT LOWER ARM RH <i>X</i>		\$ 1,091.40		
21	1	FRONT SHOCK ABSORBER RH <i>X</i>		\$ 852.60		
22	1	FRONT WHEEL BEARING RH <i>X</i>		\$ 561.20		
23	1	FORNT WHEEL HUB RH <i>X</i>		\$ -		
24	1	FRONT KNUCKLE ARM RH <i>X</i>		\$ 507.10		
25	0	0				
26	0	0				
27	0	0				
28	0	0				
29	0	0				
30	0	0				
31	0	0				
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

2500/

40/

30/

30/

230/

280/

2600/

5710

-10%

5139

+100

5239

L/S - 5111.20

= 5100

P - 5239

L - 1150

6389

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]

Steve Chen (LKK Auto)

From: ezel.t@vermogen-group.com
Sent: Wednesday, August 28, 2019 12:41 PM
To: Steve Chen (LKK Auto); 'Minoko Chan'
Subject: RE: REMINDER: SLU635R FINALISE

Dear Steve,

We confirm the revise finalise amount to \$5100.00 in 4 repair days.

Thank you.

Best Regards,

Ezel Tejano

Vermogen Ace Pte Ltd
Operation Address:
60 Jalan Lam Huat # 03-35/36
Carros Centre Singapore 737869
Tel: 6904 4596
Fax: 6694 4929

Mailing Address:
1 Bukit Batok Crescent #04-54
Wcega Plaza Singapore 658064

From: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Sent: Wednesday, August 28, 2019 9:41 AM
To: 'Minoko Chan' <minoko@vermogen-group.com>
Cc: ezel.t@vermogen-group.com
Subject: REMINDER: SLU635R FINALISE

Dear Minoko,

Our finalize is \$5100 (L/S, before GST). 4 repair days.

Kindly confirm.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)