

## **WTS Engineering Pte Ltd**

: SHA3441R

**OUR REF** 

: JW/0719/426

India International Insurance Pte Ltd C/O **LKK Auto Consultants Pte Ltd** Blk 51, Paya Ubi Industrial Park,

Ubi Avenue 1, #02-25 | S(408933)

Attention

: Motor Claims Department

WITHOUT PREJUDICE

Dear Sir

## ACCIDENT INVOLVING SHA3441R WITH OUR VEHICLE PA5660S ON 16/07/2019

We refer to the above accident and understand that you are the insurer of SHA3441R

From our investigation, we are of opinion that the accident arose as a result of your insured's negligent driving.

Our loss in this connection comprises the following:

Cost Of Repair

11,716.50

10 Days Loss Of Use \$

3,500.00

Total

15,216.50

Please let us know whether you are prepared to admit liability and reimburse our loss in full within the next two weeks on receipt of this letter otherwise we will proceed the matters legally which we will recourse the costs incurred to you.

Please acknowledge receipt of the above letter.

Thank you.

Yours faithfully,

Kenji Lee

Claims Department

Direct Line

6559 8954

Facsimile

Email

6898 2394

kenjilee@woodlandstransport.com.sg

WTS Engineering Pte Ltd

8, Gul Circle, Singapore 629564 Tel: 6 559 8988 Fax: 6 898 2394

URL:www.woodlandstransport.com.sg

Company Registration Number: 200505706E





## WTS Engineering Pte Ltd

From : Workshop Department

M/S: Woodlands Transport Service Pte Ltd

No 8 Gul Circle Singapore 629564 Date:

4-Oct-19

No:

1019/1050

S/n	Description	Unit	Amount
	Repair cost of PA5660S		
	Accident Date: 16/07/2019		141
	Repair works took 10 days		
	Lumpsum repair inclusive of labour charges and spray painting		\$ 10,950.00
	Add 7% GST		\$ 766.50
	SGD: Eleven Thousand Seven Hundred Sixteen & Cents Fifty Only		
		Total	\$ 11,716.50

**Authorised Signature** 



8, Gul Circle, Singapore 629564 Tel: 6 559 8988 Fax: 6 898 2394 URL:www.woodlandstransport.com.sg

Company Registration Number : 200505706E



