(N)	REF: C	TP.0 1901	135 NC	Special Instruction
STEED BY	Kamaliah Kamis on	SSIGNMEN	[(Oilice)	DuterTime .20/6/2019
			33 to:	
Estimated Cost: OD FFF+WS!	TPRES ! OD RES ! EVA!	TMA 1 WA 1 C2		Insured:
To Inspect Velo	ole No: FBD DREIS			_ Tol:
at Workshop m	ls			TP/19/25947/2019
Policy No. MHASPF 06000030157			Excess: _	
Sum insued:				D.O.A 21 4 2019
Make of Veh: (Client's Record				H.O.D. Endorsement:
A Company of the Company	REP. / REV 24 HRS	son Contacted:		Vehicle INLOUT
Date/Time	Action/Instruction () Estimate		
	PBD 23819 - X			
72-14-75				1 1/9
				100
				1
14 4				

Case IAFP-IB-20190614 - Mechanical Inspection of Motorcycle, FBD2381S (TP/IP/25947/2019)

Case IAFP-IB-20190614 - Mechanical Inspection of Motor Lorry, XB8413U (TP/IP/25947/2019) 1)

On 21 April 2019 (Sunday) at about 2 pm., the Deceased was riding his motorcycle together with his pillion, on Lane 4 of 6 lanes along Marina Coastal Expressway (MCE) towards Kallang Paya Lebar Expressway (KPE). Somewhere before the exit of Marina Gardens Drive (0.2km mark), the Deceased did not realise that there was a breakdown lorry ahead of him on Lane 4 and collided head-on onto the said stationary lorry. Driver informed that he had already been stationary at scene, for about 10 minutes, due to a punctured front right tyre when he felt an impact from the rear of his motor lorry. As a result of the accident, the Deceased sustained head injuries and multiple fractures. He was pronounced dead at scene by Paramedic Sgt Kumar at 2.15pm

Vehicles to be inspected: FBD23815 - Rider (Deceased)

XB8413U - Involved Party

10 In-Charge: SIO Saleha

m) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Taxi, SHA12065 (TP/IP/33067/2019)

n) Case IAFP-IB-20190614 - Mechanical Inspection of PMD (TP/IP/33067/2019)

On 25 May 2019, sometime before 10.49 p.m., the Involved Party driving taxi (SHA1206S) was travelling along Punggol Way towards Seletar North Link and at the junction of Punggol Central, involved party collided with PMD rider who was approaching from taxi's right to left. As a result of the RTA, the PMD rider was conveyed unconscious to KTPH.

Vehicles to be inspected: SHA1206S - Involved Party

PMD - Defendant

10 In-Charge: SIO Yus Mastari

Case IAFP-IB-20190612 - Mechanical Inspection of Motorcar, SLA1567C (TP/IP/35751/2019)

On 5 June 2019 (Wednesday) at about 8.51 p.m., the Potential Defendant was driving his motor car on lane 2 of the 2 lanes of Jurong East Avenue 1 towards Toh Guan Road when the Deceased ran across the signalised pedestrian crossing, from his right to left. The traffic light signal was green for the Potential Defendant at the time. The Potential Defendant was unable to brake in time and collided onto the Deceased. As a result of the accident, the Deceased was conveyed by ambulance to the Ng Teng Fong General Hospital however, he succumbed to his injuries and was pronounced dead in hospital on the same day, at 10.44 p.m. by Dr Leon.

Vehicles to be inspected: SLA1567C (Potential Defendant)

10 In-Charge: SIO Clarence Lim

p) Case IAFP-IB-20190614 - Mechanical Inspection of Motorcycle, FBG3955P (TP/IP/26131/2019)

On 22 April 2019 at about 1.01pm, the Deceased was riding his motorcycle on the left lane of 2 lanes, along Hougang Avenue 9 towards Yio Chu Kang Road, when B1 ran across the road from his right to left. As B1 was crossing halfway, the Deceased collided onto B1 before landing on the left kerb. The Deceased was conveyed to Tan Tock Seng Hosptial and was pronounced dead at 1.55 pm by Dr Praseetha.