(Catherine )

## View Received Message

This mail is associated with:

#### \*SCK6781X (7363603847SG)

OD
Jul 7 2019 12:00PM
[NG KOK YANG]
Premium Automobiles Pte Ltd

Reply Reply All Mark as Unread Print Message Delete Message Forward

From AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on 22/07/2019 15:45 PM.

LKK\_HQ
Subject Alert - Adj Mandate Approved (S\$4746.00) - SCK6781X - Claim Handler: Yap, Weijoe

Approved: 4746.00: All hidden and check item require damage parts photo taken by SURVEYOR.

#### **DOCUMENTS SUMMARY**

There are no documents.

## Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Monday, 22 July 2019 5:36 PM

To:

Chang Chee Sing

Cc:

SUR

Subject:

SCK 6781X / OD / AIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle SCK 6781X (Excess \$1000/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

AIG Asia Pacific Insurance Pte. Ltd. To:

AIG Building

78 Shenton Way #08-16 Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Nadaraja, Deeban

Date:

19 Jul 2019

## Preliminary Advice

Vehicle No

: SCK6781X

Accident Date

: 07/07/2019

Make

: AUDI A3

Policy No.

: 2100506744-02

Assignment Date

Excess

:S\$

: \$\$0.00

Date of Inspection

: 19/07/2019 : 18/07/2019

Est. Duration of Repair

: 3.00

Inspection At

: PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1

SINGAPORE 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,503.00
Revised Amount	:S\$	4,746.00
Check Items (Estimated)	:S\$	570.00
Total	:S\$	5,316.00

Lump Sum Repair

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	83,000.00
COE / PARF Rebate	:S\$	55,618.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,382.00

## Remarks

) Other comments :

(	X		The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(		)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aruresaru.	
	ACCIDENT STATEMENT
Date Of Report	13/07/2019 12:04
Date Of Accident	07/07/2019 12:15
Exact Location Of Accident	ALONG NAPIER ROAD TOWARDS FARRER ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SCK6781X
Insured/Policyholder	
Name Of Registered Owner	NG KOK YANG
NRIC No	S2681169D
Email Address	NKYANG@OUTLOOK.COM
Mobile Phone No	(LOCAL) +65-96488761
Alternative Phone No	OFFICE-96488761
Vehicle Particulars	
Manufacturer	AUDI
Model	A3 1.0 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100506744-02
Cover Note Number	
Driver	

Name of Driver NG KOK YANG NRIC No S2681169D Date Of Birth 14/11/1967 Occupation INDOOR Date Of Driving Pass 03/06/1993

**Driving Experience** 26 YEARS AND 1 MONTH

Gender MALE

Mobile Number (LOCAL) +65-96488761

Fax Number

Contact Number OFFICE-96488761

EMail Address NKYANG@OUTLOOK.COM

25 WEST COAST RISE Address

#12-06

Postcode 127468

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

2

NO

1

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by NO

ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

#### **Details of Police Action**

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

NO

If Yes, against whom?

#### Circumstances of Accident

SUDDDEN BRAKE/STOP OF THE PREMIER TAXI IN FRONT ALONG NAPIER ROAD, ABOUT 50-60KM/HR. MR CAR HIT THE REAR PORTION OF TAXI

#### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

## **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

SHC6193B

Vehicle Make/Model/Colour

KIA SILVER COLOUR

**Details Of Properties** 

Vehicle Category

TAXI

Name of Driver

TAN KOCK SENG

NRIC/Passport Number

Contact Number

98141496

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Sketch Plan

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wiful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents/including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed.
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time

Driver's Signature (if driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature NRICHIN No.

6-SUDICITY

### Sketch Plan #2

SKETCH PLAN

	□- # SHC61931B □- SCK6781X	
DESCRIBE CIRCUMSTANCE SUPPEN		PREMIER TAXI IN FO
My c	AR HIT REAR PORTION	OP TAXI
ECLARATION We declare the foregoing particula	WOVE 19001430	Control of the contro
Sextologics Signature Ite & Time 13, 0 7, 2019	Oriver's Signature Iff driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: Say Freq NRICAIN No.

Name: Try Freq NRIC/FIN No.: Gr 2040/67 (

## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	169D
Vehicle No.:	SCK6781X
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jul 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED & NAV)
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	CHZ318576
Chassis No.:	WAUZZZ8V1H1057165
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$27,479.00
Original Registration Date:	17 Apr 2017
First Registration Date:	17 Apr 2017
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$20,471.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Apr 2027
PARF Rebate Amount:	\$15,353.00
Intended COE Rebate Details	
COE Expiry Date:	16 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,000.00
COE Rebate Amount:	\$40,265.00
Total Rebate Amount:	\$55,618.00

The information contained herein is correct as at 19 Jul 2019



# CERTIFICATE OF INSURANCE

## AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder

: NG KOK YANG

Period of Insurance

: 17 Apr 2019 To 16 Apr 2020

Engine No.

: CHZ318576

Chassis No. : WAUZZZ8V1H1057165 Vehicle No.

: SCK6781X

Policy No.

: 2100506744-02

Endorsement No.

**Issued Date** 

: 09 Apr 2019

#### ABOUT THE COVER

Make/Model

: AUDI A3 Sedan 1.0 TFSI S tronic

Engine Capacity/Tonnage: 999.00 CC

Sum Insured : Market Value

First Year of Registration : 2017

Driver Restriction

: NA

Off Peak Car : No

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive\*:

a) The Policyholder

a) The Policy will indemnify the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as: "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition

: 40 years old and above

Limitation as to use\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1967 (Melaysia), are not to be included under these headings.

#### **EXCESS**

Fire - \$0 Own Damage - \$1000 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

NG KOK YANG - \$1000 (Own Damage)

## APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other: Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

#### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

å AIG Asia Pacific

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

### Telefax

 Estimate
 : Accident Repairs

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference : PA/OD/0857/2019/NS

Date : 16-Jul-19

Vehicle IN workshop. Kindly arrange for survey.

#### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR Ng Kok Yang Address : 25 West Coast Rise

#12-06

Singapore 127468

Telephone : (HP) +65 96488761
Type of Claim : Own Damage Claim
Policy No. : 2100506744-02
Vehicle No : SCK 6781 X

Model Code : Audi A3 Sedan 1.0 TFSI

Model / Year : Apr-17
Engine No : CHZ 318576

: WAUZZZ8V1H1057165

Mileage : Date In : Liability : - Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 7-Jul-19

Place of Accident : Along Napier Road Towards Farrer Road

# Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

## Telefax

## Estimated Labour Charges for Accident Vehicle. SCK 6781 X

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensore and headlight washer assy.	S/N	\$ 360.00	/ /
2	To dismantle and renew front bumper assy. Reorganise front crash management components. Reinstall all parts removed.		\$ 1,050,06	500 /
3	To respray front bumper.		\$ 900,00	550
4	To carry out diagnostic check.	5 / N	\$ 192.00	/ /
	TOTAL LABOUR CHARGES	: .	\$ 2,502.00	

# Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

## Telefax

# Material List for Accident Vehicle Regn No. SCK 6781 X

S/N	Parts Description	Damaged Parts 8 S/Nett	& Prices Remark
11.000			<del>-</del>
1	FRONT BUMPER COVER Sel	1,830.00	1464
2	FRONT BUMPER FIXING PARTS 2 5	170.00 +	0721
3	FRONT BUMPER CLOSING ELEMENT - LH	270.00 2	*.
4	RADIATOR GRILLE (m/Ld 5	1,301.00	1040-30
5	RADIATOR GRILLE CLOSING ELEMENT A ~ S	174.00 4.	
6	CAUTION' SIGN New \$	13.00	976
7	REINFORCEMENT BEAM COVER PMC 5	111.00 +	
8	FOAM FILLER PIECE 3	172.00 +	
9	REINFORCEMENT BEAM S	660.00 *	
10	SUNDRIES HAR NOC ' 5	300.00 → 🗴	
	TOTAL SPARE PARTS : \$	5,001.00	
	TOTAL LABOUR CHARGES \$	2,502.00	
	GRAND TOTAL \$	7,503.00	
		7543*	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

## Telefax

: Adrian Lig : 18/07/197 Name

Surveyed Date **Authorised Date** 

**Excess Cost** 

Liability

: Not Authorised, 03 8 mgs Remarks

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager

Allan Wu Claims Consultant

# **Premium Automobiles Pte Ltd**

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

## Supplementary Estimate 1

GST Reg No. 19-9902271-W

8 Shenton 07-16 AIG ingapore 0 attn: Mr. Ac	Building	Estimate No. Date Service Advisor Pages Regn No Model No	15-Aug Glory 1 1 of 1 SCK 6	Γan		
Quantity	Description	N. Committee	Un	it Price	A	mount
Parts 1	Front number plate New		\$	40.00	\$	40.00
			\$	40.00	\$	40.00

TOTAL

For Premium Automobiles Pte Ltd

40.00

40.00 \$

Authorised Signature

\$

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

### Telefax

Estimate

Accident Repairs
Ubi Road 1

Workshop Contact No Fax No

6366 2323 6841 1183

Reference

PA/OD/0857/2019/NS

Date

16-Jul-19

Vehicle IN workshop. Kindly arrange for survey.

#### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120 Hi Adrian

3 days - ok - jb - 13 Sep 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

MR Ng Kok Yang

Address

25 West Coast Rise

#12-06

Singapore 127468 : (HP) +65 96488761 : Own Damage Claim : 2100506744-02

Policy No. Vehicle No

Type of Claim

Telephone

SCK 6781 X

Model Code

: Audi A3 Sedan 1.0 TFSI

Model / Year

: Apr-17

Engine No

CHZ 318576

WAUZZZ8V1H1057165

Mileage

Date In

.

Liability

: -

**Excess Cost** 

: -

Estimated By

Johnny Boo / Allan Wu

Accident Date

7-Jul-19

Place of Accident

: Along Napier Road Towards Farrer Road

# Premium Automobiles 55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

## Telefax

# Estimated Labour Charges for Accident Vehicle. SCK 6781 X

S/n	Nature of Jobs		Estimated Charges	urveyor's mmendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensore and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
2	To dismantle and renew front bumper assy. Re- organise front crash management components. Reinstall all parts removed.		\$ 1,050.00	\$ 500.00
3	To respray front bumper.		\$ 900.00	\$ 550.00
4	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
	TOTAL LABOUR CHARGES	:	\$ 2,502.00	\$ 1,602.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

## Telefax

# Material List for Accident Vehicle Regn No. SCK 6781 X

	**			Damaged Pa	rts & P	rices
S/N	Parts Description		S/Nett		Remark	
<u> </u>						
1	FRONT BUMPER COVER		\$	1,830.00	\$	1,464.00
2	FRONT BUMPER FIXING PARTS		\$	170.00		
3	FRONT BUMPER CLOSING ELEMENT - LH		\$	270.00		
4	RADIATOR GRILLE		\$	1,301.00	\$	1,040.80
5	RADIATOR GRILLE CLOSING ELEMENT		\$	174.00		
6	CAUTION' SIGN		\$	13.00	\$	9.76
7	REINFORCEMENT BEAM COVER		\$	111.00		
8	FOAM FILLER PIECE		\$	172.00		
9	REINFORCEMENT BEAM		\$	660.00		
10			\$	40.00	\$	40.00
11	SUPPLEMENTARY		\$	300.00		
.145	SUNDRIES TOTAL SPARE PARTS	:	\$	5,041.00	\$	2,554.56
			\$	2,502.00	\$	1,602.00
	TOTAL LABOUR CHARGES		<del>\$</del>	7,543.00	<u> </u>	4,156.56
	GRAND TOTAL		Þ	7,543.00	9	4,100.00

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Motor Claims Dept

Yr Ref: SCK 6781 X

Norah Khai 6768 9911 6841 1183 Nora.khai@premiumauto.com.sg Body & Paint Dept

PA/OD/0857/2019/NH

Telephone +65-Telefax +65-EMail Our department Our Ref Your Ref

Date

total pages

24 October 2019

Dear Sir,

RE: INSURANCE CLAIM FOR SCK 6781 X, Audi A3 SEDAN 1.0 TFSI.

With reference to the above-mentioned vehicle, no. SCK 6781 X, claimant, Mr. Ng Kok Yang, please find the related document per attached.

- A copy of the Original invoice no. 85014397 S\$ 3,377.52.
- 2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encl AIG – SCK 6781 X Premium Automobiles Pte Ltd Showroom 9 Leng Kee Road Singapore 159090

Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323 Telefax (65) 684 11183

# Premium Automobiles Pte Ltd



Audi Centre Singapore 281 Alexandra Road Singapore 159938 Main Telephone 6836 2223 Main Telefax 6471 3733

Alexandra Service Centre 281 Alexandra Road Singapore 159938 Main Telephone 6388 2223 Main Telefax 6475 1023

**Ubi Service Centre** 55 Ubi Road 1 Singapore 408699 Main Telephone 6388 2323 Main Telefax 6841 1183

**Customer Service** Service Appointment 6366 2323 24-hour Breakdown Service 9828 1233 Email customer.care@premiumauto.com.sg

#### INS TAX INVOICE

Page

1

10:59

Company Reg. No. 199902271W GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT

AIG BUILDING

78 SHENTON WAY #07-16

SINGAPORE 079120 079120

Invoice No: 85014397

Account: A0006

(T

AIG ASIA PACIFIC INSURANCE PTE LTD

0)

Date : 24/10/2019

Order : SCK6781X

AIG BUILDING

MOTOR CLAIM DEPT

78 SHENTON WAY #07-16

Term : 30

SINGAPORE 079120

WIP No.: 60461

Regn No: SCK6781X

(V

33230)

Regn Date: 17/04/2017

Mileage: 38591

Model: A3 SEDAN 1.0 TFSI 8VMANG (NAV, Chassis: WAUZZZ8V1H1057165

Engine: CHZ 318576

Dept: U

You have been assisted by :- UB-Tony Foong

(33)

		Details		Qty	Unit Price	Amount
1000	SUBLET	M:		40.00	1.00	40.00
	EXC	TO SUPPLY VEHICLE NUMBER PLATE M: 8888	1	-1000.00	1.00	-1,000.00
	BODYWORK	Insurance Excess/Liability  M:  TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER		360.00	1.00	360.0
	BODYWORK	ASSY  M: TO DISMANTLE AND RENEW FRONT BUMPER ASSY. REORGANISE FRONT CRASH MANAGEMENT COMPONE	NTS.	500.00	1.00	500.0
	BODYWORK	REINSTALL ALL PARTS REMOVED M:		550.00	1.00	550.00
	BODYWORK	TO RESPRAY FRONT BUMPER M: TO CARRY OUT DIAGNOSTIC CHECK		192.00	1.00	192.0
	A8V3853651AA3FZ A8V5807065R GRU A8K0010520A	COVER Le	ess 020% ess 020% ess 020%	1.00 1.00 1.00	1301.00 1830.00 12.20	1,040.8 1,464.0 9.7
					Sub-Total	

Parts 2,514.56 Labour 0.00 Sublet 1,642.00 Menus 0.00 Lubricant 0.00

Sub-Total 3,156.56 220.96 7% GST 3,377.52 **Grand Total** 

Received by

For & on behalf of Premium Automobiles Pte Ltd

## Telefax

4 4 1

to AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120 Motor Claims Dept Yr Ref: SCK6781X Norah Khai 6768 9828 from Telephone +65-

6841 1183

Telefax +65-Mobile +65-

Body Repair Our department

PA/OD/0857/2019/TF 15 Aug 2019 Your Claim Ref Our Ref

Premium Automobiles Pte Ltd

Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres

Telephone (65) 6366 2323 Telefax (65) 6841 1183

total pages

Date

Showroom

9 Leng Kee Road Singapore 159090

55 Ubi Road 1 Singapore 408699

RE: CLAIM - OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : A

Audi A3 SEDAN 1.0 TFSI

Vehicle Chassis No. :

WAUZZZ8V1H1057165

Vehicle Regn No.

SCK6781X

Vehicle Mileage

37226KM

Vehicle Owner

Mr. Ng Kok Yang

Certificate No

2100506744-02

Own Damage Excess:

\$1070.00 (Including 7% GST)

Accident Date

07/07/2019

Place

Along Napier Road towards Farrer Road

Repair Cost

\$ 3377.52

WIP No.

: 60461

:

Repairer's Name

Premium Automobiles Pte Ltd

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature

Time

Date

16 08 2010)

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

	BFOLDER TRA	-			1	1.		Ta.	-	
Case	Notified	Est Submitted		Adj Rpt	Adj Sub	mitted I	ns Auth'ed	Status		
Main	18 Jul 2019		19 Jul 2019 09:46 Edit Adj Rpt	S\$4,156.5	production of	DESCRIPTION AND ADDRESS OF THE PERSON AND AD		Report Cancel C		vey
	Main	1	Reference		Claim Details		Document	s	5	Show All
CLAIM S	UBFOLDER DI	TAILS		ALCOHOLD STATE OF		[Created	by insurer]			
Insured:	NG KOK	ANG, ID: 526	81169D, Tel: +6	596488761,	Email: NKYAN	G@OUTLOOK	с.сом			
Vehicle Re No.:	scK678	1X			Date of Loss:		9 12:00 - :59 s and <b>20</b> Days Fr	rom LTA Reg	Date (I	Man Yr)]
Claim Typ	e: <b>OD</b> / 73	<b>OD</b> / 7363603847SG				2100506744 (Comprehensive)				
					Excess:	S\$1,000.0	0			
Repairer:	Premium	Automobiles	Pte Ltd (UBI) 55 (	Jbi Road 1, 4	08699 Ubi - Tel	: 67689828/	9827/9911			
Handling Insurer:			nce Pte. Ltd. (SG)					1	7	
Adjuster:	LKK Auto	Consultants F	te Ltd (HQ) - Tel:	6256-3561 .	[Handled by	ADRIAN LI	NG] [Final R	Rpt due 30	0/07/2	019]
Driver/Cu dian:	sto NG KOK Y	ANG (51 / Male	, NRIC: S26811	69D, Tel: +	6596488761 E	mail: NKYAN	G@OUTLOOK.CO	М		
ASSOCIA	ATED MAIL RE	CEIVED					,	/iew All	Compose	Case Mai
		: Alert - Adj M	andate Approved andate Maintaine OD / 07/07/201	d - SCK678	X - Claim Har	ndler: Yap,		ijoe		
AIG_Sc	SOCIATED TAS	sks <sup>©</sup>	sk Group Sub	iect Hand	Her Assim	View All	Search Tasks	Create Nev	w Task	Complete

## Claim Documents

\*SCK6781X (7363603847SG) OD Jul 7 2019 12:00PM [NG KOK YANG] **Premium Automobiles Pte Ltd** 

-		and Photos Compose New Letter Upload Video Upload Audio	200	View in Brow	1
Ass	essment Reports		1 per	page 🔻	•
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/07/19 10:45	Adjuster Immediate Advice	0	Load HTM	
Pho	otos/Images		3 per	page ▼	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/07/19 10:17	General View	0	Load JPG	•
2	19/07/19 10:17	General View	0	Load JPG	•
3	19/07/19 10:17	General View	0	Load JPG	•
4	19/07/19 10:17	General View	0	Load JPG	•
5	19/07/19 10:17	General View	0	Load JPG	•
6	19/07/19 10:17	General View	0	Load JPG	•
7	19/07/19 10:17	General View	0	Load JPG	•
8	19/07/19 10:17	General View	0	Load JPG	•
9	19/07/19 10:17	General View	0	Load JPG	•
10	19/07/19 10:17	General View	0	Load JPG	•
11	19/07/19 10:17	General View	0	Load JPG	•
12	19/07/19 10:17	General View	0	Load JPG	Ø
Doc	cumentation		1 per	page ▼	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/07/19 10:16	Driver's Driving License and NIRC	0	Load PDF	
2	19/07/19 10:16	Certificate of Insurance	0	Load PDF	
3	19/07/19 10:16	Singapore Accident Statement	0	Load PDF	
4	19/07/19 10:16	Estimate	0	Load PDF	
5	06/11/19 15:25	AUTHORISATION TO ACT	0	Load PDF	1
6	06/11/19 15:25	SUPPLEMENTARY	0	Load PDF	
7	06/11/19 15:25	WORKSHOP INVOICE	0	Load PDF	

## **Linked Accident Report Documents**

		View	View in Brow	ser ▼	
Ass	Assessment Reports		1 per	page 🔻	<b>2</b>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	13/07/19 12:44	Accident Statement	0	Load HTM	
Pho	otos/Images		3 per	page 🔻	•
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	13/07/19 12:43	Accident Photo	0	Load JPG	
2	13/07/19 12:43	Accident Photo	0	Load JPG	•
3	13/07/19 12:43	Accident Photo	0	Load JPG	•
4	13/07/19 12:43	Accident Photo	0	Load JPG	•
5	13/07/19 12:43	Accident Photo	0	Load JPG	•
6	13/07/19 12:43	Accident Photo	0	Load JPG	•
7	13/07/19 12:43	Accident Photo	0	Load JPG	•
8	13/07/19 12:43	Accident Photo	0	Load JPG	•
9	13/07/19 12:43	Accident Photo	0	Load JPG	•

Assessment Reports		1 per s	page 🔻	•	
No	Finalized On	ed On Premium Automobiles Pte Ltd (UBI) Thumbn		Thumbnail	Print
Doc	cumentation		1 per p	page v	•
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	13/07/19 12:33	Sketch Plan	0	Load JPG	•
2	13/07/19 12:33	Sketch Plan #2	0	Load JPG	•

## **Documents Checklist**

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer  Note: Remarks are private unless you show it to other parties.	

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way #08-16

Our File No:

CC3/AIG19012739/ATF3S2

Singapore 079120

Date:

06/11/2019

REFERENCE

Date of Loss:

Insured/Claimant:

NG KOK YANG

07/07/2019

Policy No: Nature of Claim: 2100506744

OD

Claim No:

7363603847SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SCK6781X

Make & Model:

AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A)

Engine No:

CHZ318576

Reg. Date:

17/04/2017 (Man. Year: 2017)

Chassis No: Odometer:

WAUZZZ8V1H1057165

Colour:

Silver 999 cc

Market Value/New Car Price:

\$\$83,000.00

35526 km

Sum Insured (S\$):

Engine Capacity:

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good

Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

225/45 R17

Rear Tyre Size:

225/45 R17

Front Left Side: Front Right Side: Goodyear 6 mm Goodyear 6 mm Rear Left Side: Rear Right Side: Goodyear 6 mm Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,041.00	2,554.56	2,486.44	49.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,502.00	1,602.00	900.00	35.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,543.00	4,156.56	3,386.44	44.90
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	6,543.00	3,156.56	3,386.44	51.76
+ GST 7.00/7.00% (S\$)	458.01	220.96	237.05	51.76
Nett Amount (S\$)	7,001.01	3,377.52	3,623.49	51.76

INSPECTION

Date of Assignment:

19/07/2019

Inspected At:

Premium Automobiles Pte Ltd (UBI)

Date Inspected:

18/07/2019

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair:

3.0 days

Adjuster: ADRIAN LING Manager:

DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Recommended Parts

No.	Qty Pa	rt No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Deformed	1,830.00 FS	*1,464.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	170.00 FS	*-FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	270.00 FS	*-FS
4	1		*RADIATOR GRILLE	Cracked	1,301.00 FS	*1,040.80 FS
5	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	174.00 FS	*-FS
6	1		*CAUTION SIGN	Necessary	13.00 FS	*9.76 FS
7	1		*REINFORCEMENT BEAM COVER	Not Necessary	111.00 FS	*-FS
8	1		*FOAM FILLER PIECE	Not Necessary	172.00 FS	*-FS
9	1		*REINFORCEMENT BEAM	Not Necessary	660.00 FS	*-FS
10	1		*SUNDRIES	Not Necessary	300.00 FS	*-FS
11	1		*FRONT NUMBER PLATE	Necessary	40.00 FS	*40.00 FS
F=Fr	anchise part.	. S=SpcNe	ett.	-		
				Total Parts (S\$)	5,041.00	2,554.56

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recom	men	hah	Lahour	
Recom	HIEL	lueu	Labour	

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ASSY. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	1,050.00	500,00
3	TO RESPRAY FRONT BUMPER.	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
	Gross Labou	r Cost (S\$)	2,502.00	1,602.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >