

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 14:08

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014755 Date: 17/01/2020 Order: SKL2813P Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SKL2813P (V 37613) Regn Date: 20/06/2018 Mileage: 30392 WIP No.: 60004

Model: A4 SEDAN 2.0 TFSI 8W2ADG (NAV, Chassis: WAUZZZF45JA165160 Engine: CVK 061169 Dept: U

You have been assisted by :- UB-Kelvin Khoo (138)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR ASSY.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHT	280.00	1.00	280.00
S	BODYWORK	M: TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.ALIGN TO POSITION.REORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER AND REAR LID.	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8W0807521A 9B9	(A) (SK) SPOILER 25/7/	Less 020%	1.00	226.50
X	A8W0807900D	STRIP	Less 020%	1.00	203.00
X	A5Q0919275B GRU	SENSOR	Less 020%	1.00	231.00
X	A8W5827025J	LID (LAST)	Less 020%	1.00	2470.00
X	A8D0853419F	PACKING	Less 020%	1.00	17.40
X	A8W5853742 2ZZ	AUDI SIGN (LAST)	Less 020%	1.00	112.50
X	A8H0853741 2ZZ	INSCRIPTION 'A4' (LAS	Less 020%	1.00	86.60
X	A8X0853737A 2ZZ	INSCRIPTION 'TFSI'	Less 020%	1.00	86.60
X	A8W5807067A GRU	COVER	Less 020%	1.00	2015.00

Parts 4,358.88
Labour 0.00
Sublet 2,932.00
Menus 0.00
Lubricant 0.00

Sub-Total 7,290.88

7% GST 510.36

Grand Total 7,801.24



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref:SKL 2813 P

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0855/2019/EH*
16 August 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

1

total pages

Make & Model : Audi A4 SEDAN 2.0 TFSI
Vehicle Chassis No. : WAUZZZF45JA165160
Vehicle Regn No. : **SKL 2813 P**
Vehicle Mileage : 30394KM
Vehicle Owner : Mr. Kwauk Yu Tang Andrew
Certificate No : 1800071600-01
Own Damage Excess : WAIVED
Accident Date : 09/07/2019
Place : Tanjung Katong Rd/Mountbatten Rd towards ECP
Repair Cost : \$ 7801.24
WIP No. : 60004
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :



16/8
