

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

AIG

Owner : Cheong Chee Boon Jeff

Accident Date : 12-Jul-19

Vehicle No : FBJ 9121 Z

Vehicle Model : Daelim SV125

Estimated Repair Costs

Qty	Description	Amount S(\$)
	List Items	
1	Front fork assy	\$ 1 780.00 X
1	Front brake disc	\$ 11 180.00 X
1	Front rim shaft	\$ 11 52.00 X
1	Top cowling inner panel	\$ C17 95.00 —
1	Windshield	\$ C17 248.00 —
1	Headlamp	\$ S12 295.00 —
2	Side mirrors	\$ 0/SBA 152.00 PC
1	Handle-bar	\$ 98.00 ?
1	Hand grip (1 set)	\$ 90.00 ?
2	Brake levers	\$ 0/S 50R 76.00 PC
1	Front cowling inner panel	\$ C17 150.00 —
1	Front signal	\$ C17 60.00 —
1	Top footstep panel	\$ C17 155.00 —
1	Bottom footstep panel	\$ C17 120.00 —
1	Exhaust assy	\$ S12/121 680.00 —
1	Exhaust protector	\$ S12 48.00 —
1	Exhaust link-pipe cover	\$ C17 28.00 —
1	Rear taillamp	\$ C17 185.00 —
1	Rear fender	\$ C17 80.00 —
2	Rear footrests	\$ 0/S121 96.00 PC
2	Rear absorbers	\$ 536.00 ?
1	Engine mounting bracket	\$ 280.00 ?
1	Fairing cover set	\$ C17 C17 985.00 —
1	Main stand	\$ 11 145.00 X
1	Side stand	\$ 11 95.00 X
1	Rear rim	\$ 320.00 ?
1	Rear rim bracket	\$ C17 322.00 —
		\$ 6,351.00
	Less 10%	\$ 635.10
		\$ 5,715.90

NOT Afford
L2L
d/s
19/7/19
the phib Afford
S12

c/f: \$ 5,715.90

Special Nett Items

- | | |
|---|-------------------------|
| 1 | Number plate (1 set) |
| 1 | Rear box |
| 1 | Rear box bracket |
| 2 | Fork oils |
| 2 | Fork oil seals |
| 1 | Steering cone (1 set) |

ref \$	Bar	28.00	20
\$	11	250.00	200
\$	12	100.00	x
\$	11	30.00	x
\$	11	56.00	x
\$	11	120.00	x
\$		584.00	

S/No. **Labour**

- | | |
|---|---|
| 1 | To provide towing service. |
| 2 | To check wiring and reset headlamp focusing |
| 3 | To provide labour. |
| 4 | To respray painting. |

\$	35	50.00
\$	11x	80.00
\$	300	380.00
\$	450	800.00
\$		1,310.00

Grand Total

\$ 7,609.90



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: