

15/5/2010

INS. CASE OWNER:

CC 4/LPC1901 2837, Uda

LKK:

IDAC:

Surveyor:

marins

DOI:

ASSIGNMENT

W/T/L

Date / Time:

W/T/L

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

YP 1319U

Name of Insured:

GOK SIN GURU MANT BH

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

1/7/10

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

SEVUGAN PURPANO

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

19/10/10/VL05/02W05

Policy No.:

219VL05101743

Make / Model:

MITSUBISHI

Place of Accident:

WOODBURN RD 28 MAR 5

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

FBL 3809A



INSRS:

WSP:

Tel:

Liability:

RMKS:

Enfia



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

PRL 4259A-X

YP 1319U-X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 30/11/19

Confirm with Lee Lee

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 1600.00

Loss of Rental (LOR):

S\$ -

(

days)

Loss of Use (LOU):

S\$ 120.00

(\$

20 x 6 days)

Loss of Income (LOI):

S\$ -

(\$

x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GLA/LTA Search

S\$ -

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 1720.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 1720.00

Name 1:

Enfia Motor Trading Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$400

COPY SENT 2/1/2020

22/03/2002

ASS. REC. BY:

REF:

CS/LPC19012837/uvf3

Special Instruction:

Surveyor: Macus

ASSIGNMENT (Office)

From (Person): Gerald Poh of ConpacDate/Time: 22.19 8.58a.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: FBC 3809A

Insured: _____

at Workshop m/s erofia MotorTel: 67527740

of _____

Policy No: _____

Claim No: 19/19/19/VCO5/022005

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. _____

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 22/7/19 1035HRSPerson Contacted: Lee Lee TanVehicle IN OUT

Date/Time Action/Instruction (✓) Estimate

FBC3809A X

108/11/13 wef

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From:

Date:

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBC 3809A

at Workshop m/s

Entire

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$4200

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L7A2466

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

net 1734

coe 21-2-2023 3yrs 7m.

L/S \$1600 (red \$4131.40 / 224.)

Veh No:

FBC 3809A

Yr Regn:

208

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha T135

c.c 135

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

78000

T/Radio: Insured / Std / NI / NA

Eng/No:

54P 720 639

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

70/90-17

R:

70/90-17 maxxis

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

1/7/19

D.O.I.

22/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & O/S Body.

The U/C / Chassis frame / Body Structure affected due to collision.

MV: \$4200

LIA Rebate: \$2466

NV: \$1734

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐
☐
☐
☐

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

) S + RS, \$

) Photos

) Others

)

Report Format:

Lump Sum / I.B.I: (\$

TOTAL

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	900I
Vehicle Details	
Vehicle No.:	FBC3809A
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jul 2019
Vehicle Make:	YAMAHA
Vehicle Model:	T135
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	5YP720639
Chassis No.:	5YP720639
Maximum Power Output:	-
Open Market Value:	\$1,818.00
Original Registration Date:	22 Feb 2008
First Registration Date:	22 Feb 2008
Transfer Count:	7
Actual ARF Paid:	\$273.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Feb 2023
COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$3,438.00
COE Rebate Amount:	\$2,466.00
Total Rebate Amount:	\$2,466.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 22 Jul 2019

OK



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC19012837/Udb3

Date: 23.07.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.


FBC3809A

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22.07.2019 at the premises of M/s Erofia Motor Trading Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	5,731.40
Revised Estimate Amount	: S\$	1,600.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
Rear Portion & O/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Owner : Fong Kim Yew

Accident Date : 1-Jul-19

Vehicle No : FBC 3809 A

Vehicle Model : Yamaha T135

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
2	Front fork tube assy	\$ 17 640.00 X
1	Front wheel rim	\$ 17 280.00 X
1	Fork under bracket	\$ 17 185.00 X
1	Front rim shaft	\$ 17 45.00 X
1	Front rim bearing	\$ 17 38.00 X
1	Front brake disc	\$ 17 155.00 X
1	Handle-bar	\$ 3rd 88.00
1	Handle-bar end	\$ 4th 32.00
1	Hand grip (1 set)	\$ 2nd 55.00
1	Side mirror -R/H	\$ 4th 55.00
1	Brake lever	\$ 5th 32.00
2	Front signals	\$ 0/5th 140.00 12C
1	Headlamp	\$ 17 185.00 X
1	Fairing assy (1 set)	\$ 4th 495.00
1	Radiator	\$ 17 458.00 X
1	Front footrest bracket	\$ 3rd 65.00
1	Front footrest rubber	\$ 1st 35.00
1	Brake pedal	\$ 2nd 42.00 X
1	Rear footrest	\$ 5th 40.00 X
1	Rear footrest bracket	\$ 1st 78.00 X
1	Exhaust assy	\$ 2nd 485.00 X
1	Exhaust protector - chrome	\$ 4th 60.00
1	Exhaust protector- black	\$ 4th 45.00
1	Rear absorber (1 set)	\$ 5th 350.00 X
1	Side stand	\$ 2nd 75.00 X
1	Main stand	\$ 2nd 95.00 X
1	Rear taillamp	\$ 4th 135.00
1	Rear fender	\$ 4th 120.00
1	Rear rim	\$ 3rd 150.00 2
1	Rear rim shaft	\$ 2nd 45.00 2
1	Rear rim bearing	\$ 2nd 38.00 2
1	Swing-arm	\$ 4th 425.00 2
		\$ 5,166.00
	Less 10%	\$ 516.60
		\$ 4,649.40

1945

c/f: \$ 4,649.40

Special Nett Items


1	Number plate (1 set)	\$ 54	28.00	10
2	Fork oils	\$ 11	30.00	4
2	Fork oil seals	\$ 11	56.00	X
1	Steering cone (1 set)	\$ 11	90.00	X
1	Coolant	\$ 11	18.00	X
		\$	222.00	

S/No. Labour

1	To provide towing service.	\$ 35	50.00
2	To check wiring and reset headlamp focusing	\$ 11 X	80.00
3	To provide labour.	\$ 300	380.00
4	To repair body frame.	\$ 200	350.00
		\$	860.00

Grand Total \$ 5,731.40 X


EROFIA MOTOR TRADING PTE LTD



Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 22 July 2019 8:58 AM
To: assignments@lkkauto.com
Cc: MT_Claim_SG; Accident@kscgp.com
Subject: FW: PRE-REPAIR SURVEY OF FBC3809A [External Confidential]

Lonpac External - Confidential

Our Ref : 19/19/19/VC05/022005

Dear Nivitha,

Kindly proceed as arranged.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Erofia Motor - LeeLee Tan [mailto:erofia@singnet.com.sg]
Sent: Friday, 19 July, 2019 7:05 PM
To: GERALD POH WEE BIN
Subject: RE: PRE-REPAIR SURVEY OF FBC3809A [External General]

Dear Gerald

Kindly arrange Marcus Chua

Thank you

Regards

LeeLee Tan

Erofia Motor Trading Pte Ltd

Tel: 67527740

Fax: 67528669

From: GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]
Sent: 19 July, 2019 2:08 PM
To: erofia@singnet.com.sg
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: PRE-REPAIR SURVEY OF FBC3809A [External General]

Lonpac External - General

WITHOUT PREJUDICE

Our Ref : 18/19/19/VC05/022005

Dear Sirs,

Your fax of 19 July 2019 refers.

We append the list our motor surveyors below:-

1	Sharan Bin Sharif
2	Jackson Quek
3	Paul Thanapal
4	Aw Po Huat (Andrew)
5	Ng Chun Wei (Adam)
6	Mohd Taufik
7	Nicholas Tey
8	Marcus Chua
9	Kenneth Kong
10	Steve Chen

Please let us hear from you.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

Shu Pei (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 24 July 2019 8:49 AM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG; Jia Le (LKK Auto)
Subject: RE: PRE-REPAIR SURVEY OF FBC3809A [External Confidential]
Attachments: 24072019084248.pdf

Lonpac External - Confidential

Dear Shu Pei,

Attached copy of insured's report for your attention.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, 23 July, 2019 6:29 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; Admin A; Jia Le (LKK Auto)
Subject: RE: PRE-REPAIR SURVEY OF FBC3809A [External Confidential]

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle FBC 3809A at M/s Erofia Motor Trading Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Jia Le and she can be contacted at DID: 6749 5792.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Sent: Monday, 22 July 2019 10:08 AM

To: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>; assignments <assignments@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: PRE-REPAIR SURVEY OF FBC3809A [External Confidential]

Dear Gerald,

Thank you for the assignment.

Best Regards

Celine Fong

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]

Sent: Monday, 22 July 2019 8:58 AM

To: assignments@lkkauto.com

Cc: MT_Claim_SG <mt_claim@lonpac.com>; Accident@kscgp.com

Subject: FW: PRE-REPAIR SURVEY OF FBC3809A [External Confidential]

Lonpac External - Confidential

Our Ref : 19/19/19/VC05/022005

Dear Nivitha,

Kindly proceed as arranged.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Erofia Motor - LeeLee Tan [<mailto:erofia@singnet.com.sg>]
Sent: Friday, 19 July, 2019 7:05 PM
To: GERALD POH WEE BIN
Subject: RE: PRE-REPAIR SURVEY OF FBC3809A [External General]

Dear Gerald

Kindly arrange Marcus Chua

Thank you

Regards
LeeLee Tan
Erofia Motor Trading Pte Ltd
Tel: 67527740
Fax: 67528669

From: GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]
Sent: 19 July, 2019 2:08 PM
To: erofia@singnet.com.sg
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: PRE-REPAIR SURVEY OF FBC3809A [External General]

Lonpac External - General
WITHOUT PREJUDICE

Our Ref : 18/19/19/VC05/022005

Dear Sirs,

Your fax of 19 July 2019 refers.

We append the list our motor surveyors below:-

1	Sharan Bin Sharif
2	Jackson Quek
3	Paul Thanapal
4	Aw Po Huat (Andrew)
5	Ng Chun Wei (Adam)
6	Mohd Taufik
7	Nicholas Tey

8	Marcus Chua
9	Kenneth Kong
10	Steve Chen

Please let us hear from you.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

This email has been checked for viruses by AVG antivirus software.
www.avg.com

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19012837/Uda3s2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 10-01-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 1319U	Veh. Inspected	FBC 3809A
Policy No.	Z19VC05001743	Coverage (\$)	0.00
Claim No.	19/19/19/VC05/022005	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	22/07/2019

2. Vehicle Particulars & Condition

Make & Model	YAMAHA T135	c.c	135
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	5YP720639	Colour	BLUE
Odometer	78000	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	70/90-17	DUNLOP	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90-17	MAXXIS	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/07/2019	Inspection Date	22/07/2019
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBC 3809A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	FRONT FORK TUBE ASSY	NOT NECESSARY	640.00	-
1	FRONT WHEEL RIM	NOT NECESSARY	280.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	185.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	45.00	-
1	FRONT RIM BEARING	NOT NECESSARY	38.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	155.00	-
1	HANDLE-BAR	BENT	88.00	88.00
1	HANDLE - BAR END	CUT	32.00	32.00
1	SET HAND GRIP	NECESSARY	55.00	55.00
1	SIDE MIRROR - R/H	CUT	55.00	55.00
1	BRAKE LEVER	SCRATCHED	32.00	32.00
2	FRONT SIGNALS	O/S CUT	140.00	70.00
1	HEADLAMP	NOT NECESSARY	185.00	-
1	SET FAIRING ASSY	CUT	495.00	495.00
1	RADIATOR	NOT NECESSARY	458.00	-
1	FRONT FOOTREST BRACKET	BENT	65.00	65.00
1	FRONT FOOTREST RUBBER	TORN	35.00	35.00
1	BRAKE PEDAL	TO REPAIR SEE LABOUR	42.00	-
1	REAR FOOTREST	SERVICEABLE	40.00	-
1	REAR FOOTREST BRACKET	NOT NECESSARY	78.00	-
1	EXHAUST ASSY	TO REPAIR SEE LABOUR	485.00	-
1	EXHAUST PROTECTOR - CHROME	CUT	60.00	60.00
1	EXHAUST PROTECTOR - BLACK	CUT	45.00	45.00
1	SET REAR ABSORBER	SERVICEABLE	350.00	-
1	SIDE STAND	TO REPAIR SEE LABOUR	75.00	-
1	MAIN STAND	TO REPAIR SEE LABOUR	95.00	-
1	REAR TAILLAMP	CRACKED	135.00	135.00
1	REAR FENDER	CRACKED	120.00	120.00

Report Ref No. CC4/LPC19012837/Uda3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR RIM	DENTED / BENT	150.00	150.00
1	REAR RIM SHAFT	NECESSARY	45.00	45.00
1	REAR RIM BEARING	NECESSARY	38.00	38.00
1	SWING - ARM	BENT / TWISTED	425.00	425.00
	LESS 10% DISCOUNT		-516.60	-194.50
			4,649.40	1,750.50
	SPECIAL NETT ITEMS			
1	SET NUMBER PLATE (SN)	BENT	28.00	10.00
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	90.00	-
1	COOLANT (SN)	NOT NECESSARY	18.00	-
			222.00	10.00
	LABOUR			
	TO PROVIDE TOWING SERVICE.		50.00	35.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF BRAKE PEDAL, EXHAUST ASSY, SIDE STAND AND MAIN STAND.		380.00	300.00
	TO REPAIR BODY FRAME.		350.00	200.00
			860.00	535.00
	GRAND TOTAL		5,731.40	2,295.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00

Report Ref No. CC4/LPC19012837/Uda3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.