

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Owner : Fong Kim Yew

Accident Date : 1-Jul-19

Vehicle No : FBC 3809 A

Vehicle Model : Yamaha T135

Estimated Repair Costs

Qty	Description	Amount S(\$)
	List Items	
2	Front fork tube assy	\$ 11 640.00 X
1	Front wheel rim	\$ 11 280.00 X
1	Fork under bracket	\$ 11 185.00 X
1	Front rim shaft	\$ 11 45.00 X
1	Front rim bearing	\$ 11 38.00 X
1	Front brake disc	\$ 11 155.00 X
1	Handle-bar	\$ 3rd 88.00
1	Handle-bar end	\$ 11 32.00
1	Hand grip (1 set)	\$ 11 55.00
1	Side mirror -R/H	\$ 11 55.00
1	Brake lever	\$ 11 32.00
2	Front signals	\$ 0/5 140.00 120
1	Headlamp	\$ 11 185.00 X
1	Fairing assy (1 set)	\$ 11 495.00
1	Radiator	\$ 11 458.00 X
1	Front footrest bracket	\$ 11 65.00
1	Front footrest rubber	\$ 11 35.00
1	Brake pedal	\$ 11 42.00 X
1	Rear footrest	\$ 11 40.00 X
1	Rear footrest bracket	\$ 11 78.00 X
1	Exhaust assy	\$ 11 485.00 X
1	Exhaust protector - chrome	\$ 11 60.00
1	Exhaust protector- black	\$ 11 45.00
1	Rear absorber (1 set)	\$ 11 350.00 X
1	Side stand	\$ 11 75.00 X
1	Main stand	\$ 11 95.00 X
1	Rear taillamp	\$ 11 135.00
1	Rear fender	\$ 11 120.00
1	Rear rim	\$ 11 150.00
1	Rear rim shaft	\$ 11 45.00
1	Rear rim bearing	\$ 11 38.00
1	Swing-arm	\$ 11 425.00
		\$ 5,166.00
	Less 10%	\$ 516.60
		\$ 4,649.40

c/f: \$ 4,649.40

Special Nett Items

1	Number plate (1 set)	\$ 54	28.00	10
2	Fork oils	\$ 11	30.00	X
2	Fork oil seals	\$ 11	56.00	X
1	Steering cone (1 set)	\$ 11	90.00	X
1	Coolant	\$ 17	18.00	X
		\$	222.00	

S/No. **Labour**

1	To provide towing service.	\$ 35	50.00
2	To check wiring and reset headlamp focusing	\$ 11 X	80.00
3	To provide labour.	\$ 300	380.00
4	To repair body frame.	\$ 200	350.00
		\$	860.00

Grand Total **\$ 5,731.40**


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: