

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ After-Paint: _____
 Contacts : _____

Vehicle Nos : **SGM 1897X**
 Model : Mitsubishi Colt Plus
 Year : _____
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Tailgate	1	\$ 938.00	\$ 938.00
2	Tailgate logo	1	\$ 48.00	\$ 48.00
3	Tailgate emblem "Colt"	1	\$ 42.00	\$ 42.00
4	Tailgate emblem "Plus"	1	\$ 42.00	\$ 42.00
5	Tailgate weatherstrip	1	\$ 181.00	\$ 181.00
6	Tailgate outer moulding	1	\$ 185.00	\$ 185.00
7	Tailgate outer handle	1	\$ 78.00	\$ 78.00
8	Tailgate inner handle	1	\$ 78.00	\$ 78.00
9	Tailgate inner lock actuator motor	1	\$ 880.00	\$ 880.00
10	Tailgate inner lock	1	\$ 372.00	\$ 372.00
11	Tailgate reflector	2	\$ 187.00	\$ 374.00
12	Tailgate inner trim board	1	\$ 449.00	\$ 449.00
13	Tailgate inner board	1	\$ 220.00	\$ 220.00
14	Tailgate windscreen moulding top	1	\$ 147.00	\$ 147.00
15	Tailgate windscreen moulding bottom	1	\$ 79.00	\$ 79.00
16	Tailgate inner top garnish	1	\$ 98.10	\$ 98.10
17	Tailgate inner side garnish	2	\$ 78.90	\$ 157.80
18	Tailgate open/close sensor	1	\$ 168.00	\$ 168.00
19	Rear bumper	1	\$ 861.00	\$ 861.00
20	Rear bumper side retainer	2	\$ 61.00	\$ 122.00
21	Rear bumper bracket	2	\$ 63.00	\$ 126.00
22	Rear bumper side reflector	2	\$ 25.00 68.00	\$ 50.00 136.00
23	Rear bumper beam	1	\$ 188.20	\$ 188.20
24	Rear end panel inner	1	\$ 296.00	\$ 296.00
25	Rear end panel outer	1	\$ 268.00	\$ 268.00
26	Rear end panel top garnish	1	\$ 184.00	\$ 184.00
27	Rear end panel air vent	1	\$ 64.00	\$ 64.00
28	Spare tyre panel	1	\$ 945.00	\$ 945.00
29	Spare tyre panel top cover	1	\$ 385.00	\$ 385.00
30	Spare tyre panel tray	1	\$ 465.00	\$ 465.00
31	Taillamp	2	\$ 386.00	\$ 772.00
32	Exhaust silencer	1	\$ 362.00	\$ 362.00
33	Exhaust mounting	2	\$ 46.00	\$ 92.00
			Parts Sub Total :	\$ 9,803.10
			Discount 10%	\$ 980.31
			PARTS TOTAL :	\$ 8,822.79

7903.00
 790.30
 7,112.00

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 50.00	\$ 50.00
2	Tailgate outer moulding clips	1	\$ 50.00	\$ 50.00
3	Tailgate inner trim board clips	1	\$ 50.00	\$ 50.00
4	Tailgate reflector clips	2	\$ 50.00	\$ 100.00
5	Tailgate reflector inner seal	2	\$ 40.00	\$ 80.00

6	Taillamp clips	2	\$	50.00	\$ 60.00	100.00	?NECV
7	Taillamp inner seal	2	\$	60.00	\$	120.00	NNX
8	Rear bumper clips	1	\$	50.00	\$ 30.00	50.00	/NECV
9	Rear end panel top garnish clips	1	\$	50.00	\$ 30.00	50.00	/NECV
10	Rear windscreen inner seal	1	\$	80.00	\$ 60.00	80.00	NECV
11	Rear windscreen sealant	1	\$	100.00	\$ 60.00	100.00	NECV
12	Rear end panel sealant	1	\$	100.00	\$ 30.00	100.00	?NECV
13	Spare tyre panel sealant	1	\$	100.00	\$ 30.00	100.00	?NECV
14	Reverse sensor	2	\$	200.00	\$ 200.00	400.00	DLV
15	Tailgate garnish clips top	1	\$	50.00	\$	50.00	?NNX
16	Tailgate garnish clips side	2	\$	50.00	\$	100.00	?NNX
SPECIAL NETT TOTAL :					\$ 620.00	1,580.00	

Nos.	LABOUR	S\$	
1	R&R wire harness and check function	\$ 50.00	80.00
2	R&R exhaust pipe assy	\$ 120.00	250.00
3	R&R upholstery	\$ 80.00	150.00
4	R&R rear windscreen	\$ 150.00	300.00
5	R&R reverse sensor	\$ 60.00	100.00
6	R&R tailgate component	\$ 50.00	100.00
7	Mount bench work	\$ 150.00	300.00
8	Panel beat	\$ 1000.00	1,600.00
9	Rust proofing	\$ 60.00	150.00
10	Spray painting	\$ 1000.00	1,600.00
LABOUR TOTAL :		\$ 2720.00	4,630.00

PARTS TOTAL : \$ 8,822.79
 SPECIAL NETT TOTAL : \$ 1,580.00
 LABOUR TOTAL : \$ 4,630.00
GRAND TOTAL : \$ 15,032.79

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Resurvey on 23/7/19
 1510 hrs
 TGLim Min

? photo
 Lump sum repair
 Repair days ? 7

TGLim Min
 22/7/19
 1510 hrs

Parts 7,112.00
 SN 620.00
 Labour 2720.00
 10452.00
 @20% 2090.40
 8361.60

L/S 8,350 1/2

TGLim Min
 30/7/19