

REF: C1/TPD 19012881/Nc Special Instruction:

ASS. REC. BY:

SUNNY

ASSIGNMENT (Office)

From (Person): Kamalish Kamle of SPF Date/Time: 3/7/2019

Estimated Cost: Bill to:

OD+TP+WS+TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: PND 8131 Insured:

at Workshop m/s Tel:

of

Policy No: MHASPF060000207471 Claim No: TP/IP 38627/2019

Sum Insured: Excess:

Make of Veh: D.O.A. 11/6/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	PND 8131-X

450K8

- ✓ e) Case IAFP-IB-20190621 - Mechanical Inspection of Motorcycle, PNQ8131 (TP/IP/38627/2019)
- ✓ f) Case IAFP-IB-20190621 - Mechanical Inspection of Motorcycle, FW3550S (TP/IP/38627/2019)
- g) Case IAFP-IB-20190621 - Mechanical Inspection of Motor Bus, PZ1144K (TP/IP/38627/2019)

On 19 June 2019 (Wednesday) sometime before 7.15 a.m., the accused was riding on the first lane from right of 4-lanes along AYE towards MCE. Somewhere before Exit 17, the accused switched lanes into lane 2 and encroached into the path of the potential defendant's bus, causing the bus to collide onto the accused's motorcycle. The bus then veered to the right into lane 1 and while coming to a stop, the deceased motorcycle suddenly collided onto the rear of the potential defendant's bus. Deceased landed on the right side of the motor bus and was pronounced dead at scene at 7.15 a.m. by Paramedic Salbiah.

Vehicles to be inspected: PNQ8131 - Rider (Slightly Injured)
FW3550S - Rider (Deceased) ✓
PZ1144K - Driver (Defendant)

IO In-Charge: SIO Adrian

- h) Case IAFP-IB-20190621 - Mechanical Inspection of Motor Bus, SBS3551T (TP/IP/37529/2019)
- ✓ i) Case IAFP-IB-20190621 - Mechanical Inspection of Motorcycle, FBG8685K (TP/IP/37529/2019)

On 15 June 2019 (Saturday) sometime before 12.41 p.m., the motor bus was travelling straight along Corporation Rd towards the direction of Jurong Port Rd on lane 3 of the 3-lanes road. Upon reaching the signalised cross junction of Jln Ahmad Ibrahim, traffic light in favour of the motor bus was green light only thus the motor bus proceeded straight. Halfway through, the motorcycle made a right turn from the motor bus' opposite direction and collided into the frontal right portion of the motor bus. Due to the accident, the motorcyclist was conveyed to NUH by an ambulance in an unconscious state. Subsequently, the motorcyclist succumbed to his injuries and he was pronounced dead in the said hospital on the same day at 3.39 p.m.

Vehicles to be inspected: SBS3551T - Driver (Involved Party)
FBG8685K - Rider (Deceased)

IO In-Charge: SIO Kamaliah

2. These request has been approved by my management.
3. Thank you Sirs.

cc: FAIT Team, SIO Raziz & IO Hidayu, fyip

Best regards,

Kamaliah Kamis (Miss)
Senior Investigation Officer | Fatal Accident Investigation Team
Traffic Police Department | Singapore Police Force
DID: (65) 6547 6435 | FAX: (65) 6547 6352