Estimated C		a	Bill to:	Date	Time:	219	. 1
To Inspect \	VS/TP RES/OD I /chicle No:	SFR 89	196H	Insured	50	£ 6804P	
of Westghop of	in/n	Premiu	М	Tel:	6768	9828 9828	
Policy No: Sum insured		175830180	// Claim No				
Make of Vel Client's Recon			Excess:			386 cor 517/19	
	/ REP. / REV 24	HRS W	11000000		D. Endyrener		
Date/Time	Action/Instruction	i technicit	10				-
4/12/190	9 11. Am con	offmed o	with Jia yee	final fly	8 5041.1	0, 6 days	hyen

TOTAL

270

### Nivitha (LKK Auto)

From:

Chong Boon Sen <boonsen.chong@sq.cntaiping.com>

Sent:

Monday, 22 July 2019 4:26 PM

To:

Claims

Cc:

'Admin-D (LKKAuto)'; 'assignments'

Subject:

RE: OUR REF: SNM19D203356/CHONGBS - FW: ACCIDENT INVOLVING SFR 8996 H

AND YOUR INSURED SLE 6804 P DATED ON 16/07/2019

### WITHOUT PREJUDICE

Dear Sir.

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

### Chong Boon Sen

Claims Executive Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909 DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG 3 Anson

Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims [mailto:claims@premiumauto.com.sg]

Sent: Monday, 22 July, 2019 4:10 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Cc: 'Claims Dept' <claims@premiumauto.com.sg>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>; 'assignments'

<assignments@lkkauto.com>

Subject: RE: OUR REF: SNM19D203356/CHONGBS - FW: ACCIDENT INVOLVING SFR 8996 H AND YOUR INSURED SLE

6804 P DATED ON 16/07/2019

Dear Mr. Chong,

I would like to assign to LKK to survey this case.

Aside to LKK.

Please arrange for the survey on 24/7/2019@Wednesday,10.30am, owner waiting.

Thanks

Best Regards,

TRoy Goh

#### · Claims Advisor'

Premium Automobiles Pte Ltd (Reg No 10-122210)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims a premiumanto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

"It comes in blue,"
The new Audi A7 Sportback. Do you really need a reason?

Find out more

Email Disclaimer

This entail, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you,

From: Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]

Sent: Monday, 22 July 2019 1:28 PM To: claims@premiumauto.com.sq

Subject: RE: OUR REF: SNM19D203356/CHONGBS - FW: ACCIDENT INVOLVING SFR 8996 H AND YOUR INSURED

SLE 6804 P DATED ON 16/07/2019

#### WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

### Chong Boon Sen

Claims Executive Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG 3 Anson

Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Monday, 22 July, 2019 11:45 AM

To: Chong Boon Sen <br/>
<br/>
boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So

Chow <sochow.chee@sg.cntaiping.com>; claims@premiumauto.com.sg

Subject: OUR REF: SNM19D203356/CHONGBS - FW: ACCIDENT INVOLVING SFR 8996 H AND YOUR INSURED SLE

6804 P DATED ON 16/07/2019

Dear Boon Sen,

Please conduct PRS for SFR8996H.

Note: officer in charge - Bonn Sen 63896171.

Thanks, shumin

From: Claims [mailto:claims@premiumauto.com.sg]

Sent: Saturday, 20 July, 2019 9:16 AM

To: Claims Dept of CTI < claimsdept@sg.cntaiping.com > Cc: 'Claims Dept' < claims@premiumauto.com.sg >

Subject: RE: ACCIDENT INVOLVING SFR 8996 H AND YOUR INSURED SLE 6804 P DATED ON 16/07/2019

Dear all,

Herein attached with the GIA Report for your information.

Thanks

Best Regards, TRoy Goh Claims Advisor

Premium Automobiles Pte Ltd (Reg No presentation)

55 Ubi Road I Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e, claims a premiumanto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



#### Email Disclaimer

This arnall, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply small and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you,

From: Claims [mailto:claims@premiumauto.com.sg]

Sent: Friday, 19 July 2019 8:07 PM To: claimsdept@sg.cntaiping.com

Cc: 'Claims Dept'

Subject: RE: ACCIDENT INVOLVING SFR 8996 H AND YOUR INSURED SLE 6804 P DATED ON 16/07/2019

Dear all,

Please do take note that for the arrangement of survey will be arrange on 24/7/2019, Wednesday@10.30am, 55 Ubi Road 1, owner waiting.

Thanks

Best Regards, TRoy Goh Claims Advisor

Premium Automobiles Pte Ltd (Rug No 199003271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims a premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



#### **Email Disclaimer**

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Claims [mailto:claims@premiumauto.com.sq]

Sent: Friday, 19 July 2019 8:04 PM To: 'claimsdept@sg.cntaiping.com' · Cc: 'Claims Dept'

Subject: ACCIDENT INVOLVING SFR 8996 H AND YOUR INSURED SLE 6804 P DATED ON 16/07/2019

Dear all,

Kindly assist to register this case mentioned. We propose for 100% direct settlement in our clients favour. Herein attached with the video footage front and rear for your reference.

We will forward you the GIA Report and estimate repair once is ready.

#### Thanks

Best Regards, TRoy Goh Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199402221W) 55 Ubi Road 1 Road Singapore 408699 p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims a premiumanto.com sg w. www.andi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Emall Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply small and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit <a href="http://www.symanteccloud.com">http://www.symanteccloud.com</a>

### Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Wednesday, 4 December 2019 11:27 AM

To:

jiayee.yap@premiumauto.com.sg; Adrian Ling (LKKAuto); SUR; Admin A; CS A Team

Cc:

Subject:

RE: FINAL REVISION - SFR8996H - TP CHINA - SURVEYED 24 JUL 19

'Boo seng yak'; 'Carrine Leong'; 'Chang Chee Sing'

Dear Jia Yee,

WITHOUT PREJUDICE

Confirm final fig \$8041.10 before GST and 6 repair days.

Kindly send the relevant documents to China Taiping Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jiayee.yap@premiumauto.com.sg < jiayee.yap@premiumauto.com.sg >

Sent: Tuesday, 3 December 2019 4:07 PM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>;

CS A Team <cs-a@lkkauto.com>

Cc: 'Boo seng yak' <boojohnny@gmail.com>; 'Carrine Leong' <carrine.leong@premiumauto.com.sg>; 'Chang Chee

Sing' <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SFR8996H - TP CHINA - SURVEYED 24 JUL 19

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$8041.10 @ 6 days of repairs.

Your early closure is well appreciated.

Thanks & Best Regard

JiaYee Yap

Claims Administrator

Premium Automobiles Pte Ltd (Reg No. 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. jiayee.yap@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 20/07/2019 09:08

#### SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

NAME OF THE OWNER, WHEN	ACCIDENT STATEMENT
Date Of Report	19/07/2019 19:27
Date Of Accident	16/07/2019 18:10
Exact Location Of Accident	PIE TOWARDS JURONG BETWEEN EUNOS & PAYA LEBAR EXIT
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SFR8996H
Insured/Policyholder	
Name Of Registered Owner	KE CHOON LIN
NRIC No	S2565301G
Email Address	KECL.2007@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96709796
Alternative Phone No	OTHERS-96709796
Vehicle Particulars	
Manufacturer	AUDI
Model	A4 SEDAN 2.0 TFSI 8W
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V09139/VPC/R00
Cover Note Number	
Driver	
Name of Driver	KE CHOON LIN
NRIC No	\$2565301G
Date Of Birth	03/03/1958
Occupation	INDOOR
Date Of Driving Pass	03/12/1987
Driving Experience	31 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96709796
Fax Number	

OTHERS-96709796

KECL.2007@GMAIL.COM

Address

516 SIXTH AVENUE

Postcode

276600

OWNER

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

2

NO

Was any body injured in the Accident? Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

### Circumstances of Accident

WHILE DRIVING ON PIE, THE VEHICLE IN FRONT OF ME MADE AN EMERGENCY BRAKE & STOPPED. I STOPPED IN TIME, BUT THE VEHICLE BEHIND (SLE 6804 P), WHICH HIT THE REAR OF MY CAR.

### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLE6804P

Vehicle Make/Model/Colour

VOLKSWAGEN JETTA

**Details Of Properties** 

Vehicle Category

PRIVATE CAR

Name of Driver

LIM JUN CEN

NRIC/Passport Number

S8607332C

Contact Number

Address

BLK 676B PUNGGUL DRIVE

#04-712

Postcode

822676

Insurance Company Name

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

#### Sketch Plan

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as <u>truthful</u> and accurate as possible. Any willul misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (ii) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (iii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about nie to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling anti/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured webschi(s) involved in this accident and the insurers, lawyers/law firms, may are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GA to their third party service providers or agents/including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (ii) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (c) the information so collected under (d) above may be shared 7 disclosed:
  - to all insurers ent/or any other third parties that assist in evaluating, investigating, controlling or managing found, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Plant telling a Signature

Driver's Signature (If driver is not the policynoline)

Date & Time.

Name (1st di- No. 162) Name (1st di- No. 162)

### Sketch Plan #2

221222		
SKETCH PLAN	CAR	
157.4	PILL	
	BAL.	
1	Front	
HER BURNETICE		
The state of the s	1804P	
SU	>65 041	
DESCRIBE CIRCUMSTANCES OF	THE ACCIDENT	
while anim	on PIE, the veh	icle in front of me
gode an ok	organa, brake & st	erred I Styped in
time, but	The vekele	Gehind (SLEGGOGP)
Which hit	my back the r	an y ay on.
		* *
DECLARATION  TWO declare the too going particular.	see tour in Asses seemed	
Al .	ALL TONCO CHEST TOURISME	6
Mono		
old/folder's Signature	Driver's Signature	Reporting Centre Forsprine's Senature Name (cl.), No. 160, [63-]
were time July 19, 2019	(If driver is not the parcynolities)	Name Cold No. 1987 Dear







# Certificate of Insurance

www.libertyinsurance.com.sg

Motor Vehicles (Third-Party Risks And Compensation) Act (Chapter 189); Motor Vehicles (Third-Party Risks And Compensation) Rules, 1960; Road Transport Act, 1987 (Malaysia); Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Name of Policyholder:		Certificate No.:	
KE CHOON LIN		SD18V09139/ VPC / R00	
Date of Issue:	Effective Date of Commencement:	Date of Expiry:	
29 Aug 2018	06 Aug 2018 00:00	05 Aug 2019 23:59	
Registration No.:	Chassis No.:	Type of Certificate:	
SFR8996H	WAUZZZF42JA205453	MX1	

### Persons or Classes of Persons entitled to drive\*:

- A) The Policyholder.
- B) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

#### Limitations as to use:

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

#### The Policy does not cover:

- A) Use for hire or reward.
- B) Use for racing, pace-making, reliability trials or speed-testing.
- C) Use for the carriage of goods (other than samples) in connection with any trade or business.
- D) Use for any purpose in connection with the Motor Trade.

\*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

For and on behalf of LIBERTY INSURANCE PTE LTD Approved Insurers

For Information Only:

Coverage(s):

Comprehensive, Unlimited Windscreen, NCD Protection

Sum Insured:

MARKET VALUE AT THE TIME OF LOSS

Excess

Section I \$\$800,Additional Excess for Young & Inexperienced Drivers \$\$3000,Windscreen Excess

S\$100

Name of Finance Company:

DBS BANK LTD

Name of Producer:

PREMIUM LEASING PTE LTD (A1704-2)



### GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

### Third Party Insurer Enquiry

Our Ref No:

GR-19-117296

Date of Request:

19/07/2019

Your Ref No:

Online Purchase

Premium Automobiles Pte Ltd

55 Ubi Road 1 Singapore 408699

Dear Sir/Madam,

**Enquiry Date** 

19/07/2019

Enquiry By

Tony Foong Chin Fong

TP Vehicle No.

SLE6804P

Accident Date

16/07/2019

**Enquiry Result** 

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLE6804P	China Taiping Insurance (Singapore) Pte. Ltd.	30/09/2018-29/09/2019	6389 6111
SLE6804P	China Taiping Insurance (Singapore) Pte. Ltd.	30/09/2018-29/09/2019	6389 6111

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



### GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

### TAX INVOICE

Our Ref No:

GR-19-117296

Date of Request:

19/07/2019

Your Ref No:

Online Purchase

Premium Automobiles Pte Ltd

55 Ubi Road 1 Singapore 408699

Dear Sir/Madam,

**Enquiry Date** 

19/07/2019

Enquiry By

Tony Foong Chin Fong

TP Vehicle No.

SLE6804P

Accident Date

16/07/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khal@premiumauto.com.sg / claims@premiumauto.com.sg

#### Telefax

 Estimate
 Accident Repairs

 Workshop
 Ubi Road 1

 Contact No
 6366 2323

 Fax No
 6841 1183

Reference : PA/TP/0887/2019/NS

Date : 23-Jul-19

Vehicle not IN workshop. Kindly arrange for survey.

Your insured vehicle is : SLE 6804 P

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street #19-00 The Octagon Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Mr. Ke Choon Lin Address : 516 Sixth Avenue

Singapore 276600

Telephone : (HP) 96709796

Type of Claim : Third Party Claims
Policy No. : SD18V09139/VPC/R00

Vehicle No : SFR 8996 H

Vehicle No : SFR 8996 H

Model Code : A4 Sedan 2.0 TFSI 8W

Model / Year : Aug-18
Engine No : CVK 065677

Chassis No : WAUZZZF42]A205453

Mileage :

Date In

Liability : Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 16-Jul-19

Place of Accident : PIE Towards Jurong Between Euros & Paya Lebar Exit

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

### Estimated Labour Charges for Accident Vehicle SFR 8996 H

5/N	Nature of Jobs			Estimated Charges	Surveyor's Recommendation		
1	To remove and transfer rear parking aid and rear lid kick sensor. Check fucntion and renew according to damage.	S/N	\$	360.00	1		
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N	s	280.00	+.		
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N	\$	480.00	×		
4	To dismantle and renew bumper and rear lid. Cut out and reweld end panelling. Re-organise rear crash management components. Reinstall all parts removed.		s	4,209.00	1050	700×1.5°	
5	To respray rear bumper, rear lid end panelling. To carry out joint sealer works and stone chip treatment.		\$	2,800.00	. 1400		
6	To renew lhs rear exhaust silencer and centre exhaust silencer. To align to position.	S/N	s	480.00	V		
7	To carry out diagnostic check	S/N	\$	192.00	1		
	TOTAL LABOUR CHARGES	:	\$	8,792.00			

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

### Material List for Accident Vehicle Regn No. SFR 8996 H

		Damage Parts & Prices			
S/N	Parts Description		S/Nett	Remarks	
1	REAR BUMPER COVER Dela	s	2,015.00		
2	REAR BUMPER FIXING PARTS	S	- Additional Control	+	
3		c s	203.00	A 3.X	
4	REAR BUMPER SPOILER LAT	5		10650	
5		2 S	227.00		
6	REAR BUMPER CARRIER But	2 5			
		2.50			
7	BUMPER SEAL ALL	5	25.00 +	39.50	
. 8	REAR BUMPER GUIDE SECTION - LH	\$			
9	REAR BUMPER GUIDE SECTION - RH	\$	41.00		
10	THE THE PARTY OF T	2 \$	40.00 4		
11	AERIAL RETAINER	\$	23.00 2	+	
12	TELEPHONE AERIAL THE NAME	S	164.00	X	
13	BOOT LID CONTROL UNIT NEW	\$	381.00 ₺		
14		3 \$	693.00 7	31-	
15	a big at all the	4 \$	12.00 3	X	
16	BUMPER WIRING SET ***	S	618.00	e:	
17	REAR LID Ryv	5	2,470.00 +		
18	LID LOCK Men	s	210.00 4		
19	REAR LID ATTACHMENT PARTS ALL	\$	131.00+		
20	FLAP GASKET Ne M	\$	185.00 <sup>2</sup>		
	SUB TOTAL SPARE PARTS	: \$	8,254.00		
	All charges are not inclusive of CST				

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

pholo

### Material List for Accident Vehicle Regn No SFR 8996 H

5/N	Parts Description			S/Nett Remarks	
21	ADHESIVE PACKING 7	NEC	S	18.00 - 17.40	
22	AUDI EMBLEM	NEC	\$	113.00 - 112.50	
23	A4' INSCRIPTION NEL	NEC	\$	87.00 - \$2.60	
24	TFSI' INSCRIPTION	NEC	\$	87.00 84.40	
25	LED TAIL LIGHT - LH / RH 2		\$	1,862.00 ₺	
26	TAIL LIGHT TRIM - LH / RH JOE	2	\$	54.00	
27	LED LICENSE PLATE LIGHT	2	s	191.00 -	
28	REINFORCEMENT CROSS PANEL R		\$	461.00 +	
29	REAR CROSS PANEL TRIM		\$	154.00	
30	REAR SILENCER Develd		\$	813.00 2 812.50	
31	DUAL CLIP THE NEC		\$	45.00 3 X	
32	EXHAUST SILENCER BRACKET Pod.		\$	38.00 ? 3790	
33	CENTRE SILENCER gode in		\$	825.00 +	
34	EXHAUST SILENCER BRACKET 2 Not NEL		\$	19.00 ₹ ×	
35	EXHAUST SILENCER BRACKET		\$	45.00 * <	
36	MUFFLER CLAMP 1000		5	45.00 7 44.30	
37	REAR NO. PLATE ALL	S/N	\$	40.00 ₺	
38	ARYCLIX SEALANT 2	S/N	s	180.00 +	
39	CAVITY WAX	S/N	S	140.00	
40	STONE CHIP	S/N	s	180.00 1	
41	SUNDRIES Nec		s	400.00 - 30	
	TOTAL SPARE PARTS	:	\$	14,051.00	
	TOTAL LABOUR CHARGE	:	\$	8,792.00	
	GRAND TOTAL	:	\$	22,843.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

24028

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before latter spray painting
- To display damaged partis) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.

: Not Authorised, 06 Pays.

Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

### Telefax

Estimate

Accident Repairs

Workshop

: Ubi Road 1

Contact No

6366 2323

Fax No

6841 1183

Reference

PA/TP/0887/2019/NS

Date

23-Jul-19

Vehicle not IN workshop. Kindly arrange for survey.

Your insured vehicle is

**SLE 6804 P** 

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street #19-00 The Octagon Singapore 069534

Attn: Ms Angle - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name

Mr. Ke Choon Lin

Address

516 Sixth Avenue

Audios

Singapore 276600

Telephone

(HP) 96709796

Type of Claim

Third Party Claims

Policy No.

SD18V09139/VPC/R00

Vehicle No

SFR 8996 H

Model Code

A4 Sedan 2.0 TFSI 8W

Model / Year

Aug-18

Engine No

CLU OCCCTT

Eligino ito

CVK 065677

Chassis No

WAUZZZF42JA205453

Johnny Boo / Allan Wu

Mileage

Date In

.

Liability

.

**Excess Cost** 

.

Estimated By Accident Date

16-Jul-19

Place of Accident

: PIE Towards Jurong Between Eunos & Paya Lebar Exit

HI Adrian.

6 days - ok - Jy - 03 Dec 2019

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

### Estimated Labour Charges for Accident Vehicle SFR 8996 H

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation		
1	To remove and transfer rear parking aid and rear lid kick sensor. Check fucntion and renew according to damage.	S/N	\$	360.00	s	360.00
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N	\$	280.00		
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N	\$	480.00		
4	To dismantle and renew bumper and rear lid. Cut out and reweld end panelling. Re-organise rear crash management components. Reinstall all parts removed.		s	4,200.00	s	1,050.00
5	To respray rear bumper, rear lid end panelling. To carry out joint sealer works and stone chip treatment.		\$	2,800.00	s	1,400.00
6	To renew lhs rear exhaust silencer and centre exhaust silencer. To align to position.	S/N	\$	480.00	\$	480.00
7	To carry out diagnostic check	S/N	\$	192.00	\$	192.00
	TOTAL LABOUR CHARGES	:	\$	8,792.00	\$	3,482.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

### Material List for Accident Vehicle Regn NoJ SFR 8996 H

				Damage Pa	arts 8	Prices	
S/N	Parts Description			S/Nett		Remarks	
	DEAD BUMDED COVER		\$	2,015.00	S	2,015.00	
1	REAR BUMPER COVER REAR BUMPER FIXING PARTS		s	66.00	3	2,075.00	
2		NEC	s	203.00			
3	REAR BUMPER SECURING STRIP	NEC		227.00		202.50	
4	REAR BUMPER SPOILER	2	\$		\$	226.50	
5	REAR LIGHT REFLECTOR - LH / RH	2	\$	76.00			
6	REAR BUMPER CARRIER		\$	819.00	\$	819.00	
7	BUMPER SEAL		\$	25.00			
8	REAR BUMPER GUIDE SECTION - LH		\$	40.00	\$	39.80	
9	REAR BUMPER GUIDE SECTION - RH		\$	41.00			
10	REAR BUMPER GUIDE SECTION - UPPER LH / RH	2	\$	40.00			
11	AERIAL RETAINER		\$	23.00			
12	TELEPHONE AERIAL		\$	164.00			
13	BOOT LID CONTROL UNIT		\$	381.00			
14	PARKING AID SENSOR	3	\$	231.00	\$	231.00	
15	SEAL RING	4	\$	12.00			
16	BUMPER WIRING SET		5	618.00			
17	REAR LID		\$	2,470.00			
18	LID LOCK		\$	210.00			
19	REAR LID ATTACHMENT PARTS		\$	131.00			
20	FLAP GASKET		\$	185.00			
-55	SUB TOTAL SPARE PARTS		\$	7,792.00	\$	3,331.30	
			=				

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

### Material List for Accident Vehicle Regn No SFR 8996 H

				Damage Pa	arts & Prices		
S/N	Parts Description			S/Nett	F	Remarks	
					\$	3,331.30	
21	ADHESIVE PACKING	NEC	\$	18.00	\$	17.40	
22	AUDI EMBLEM	NEC	\$	113.00	\$	112.50	
23	A4' INSCRIPTION	NEC	\$	87.00	\$	86.60	
24	TFSI' INSCRIPTION	NEC	\$	87.00	\$	86.60	
25	LED TAIL LIGHT - LH / RH		\$	1,862.00			
26	TAIL LIGHT TRIM - LH / RH	2	\$	54.00			
27	LED LICENSE PLATE LIGHT	2	\$	191.00			
28	REINFORCEMENT CROSS PANEL		\$	461.00			
29	REAR CROSS PANEL TRIM		\$	154.00			
30	REAR SILENCER		\$	813.00	\$	812.50	
31	DUAL CLIP		\$	45.00			
32	EXHAUST SILENCER BRACKET	NEC	\$	38.00	\$	37.90	
33	CENTRE SILENCER		\$	825.00			
34	EXHAUST SILENCER BRACKET		\$	19.00			
35	EXHAUST SILENCER BRACKET		\$	45.00			
36	MUFFLER CLAMP	NEC	\$	45.00	5	44.30	
37	REAR NO. PLATE	S/N	s	40.00			
38	ARYCLIX SEALANT	S/N	\$	180.00			
39	CAVITY WAX	S/N	\$	140.00			
40	STONE CHIP	S/N	\$	180.00			
41	SUNDRIES		\$	400.00	\$	30.00	
	TOTAL SPARE PARTS	1	\$	13,589.00	\$	4,559.10	
	TOTAL LABOUR CHARGE		\$	8,792.00	\$	3,482.00	
	GRAND TOTAL	:	\$	22,381.00	\$	8,041.10	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

Name : Surveyed Date 223 **Authorised Date** : Excess Cost : Liability ; Remarks

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager

Allan Wu

Claims Consultant

Merimen e-Claims Page 1 of 1

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRA	CKING					1	
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	12 Dec 2019		12 Dec 2019 11:28 Edit Adj Rpt	S\$8,041.10 Edit Estimates	\$\$8,041.10 View Rpt		Pending for Survey Report Cancel Case	
	Main	R	eference	Claim De	tails	Documents	Show All	
CLAIM SU	JBFOLDER DE	TAILS			[Created	by insurer]		
Insured:	-, Co. Re	g. No.: -						
Main Claimant:	KE CHOO	N LIN, ID: S25	65301G					
Vehicle Res	SFR899	6Н		Date of		9 18:00 - :59 is and <b>10</b> Days Fro	m LTA Reg Date (Man Yr)]	
Claim Type	TP / SN	M19D203356C0	)2	Policy/C Nate No		7583018011		
Vehicle Rei No. (Insured):	SLE6804	P		Policy N (Claima		SD18V09139/VPC/R00		
				Excess	5\$0.00			
Repairer:	Premium	Automobiles Pt	e Ltd (UBI) 55 Ubi	Road 1, 408599 Ubi	- Tel: 67689828/	9827/9911		
Handling Insurer:	China Tai	ping Insurance	(Singapore) Pte. L	.td. (HQ) - Tel: 638	9 6111 [Handle	d by Chong Boon	Sen)	
Claimant's Insurer:	Liberty I	Hamilton Company	(HQ) - Tel: (65) 63	Name of the Party				
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [Handle	by ADRIAN LIN	(G) [Final Rp	t due 23/12/2019]	
ASSOCIA	TED MAIL RE	CEIVED				Vie	w All Compose Case Mail	
There are	no mail for this	case						
ALL ASS	OCIATED TAS	sks <sup>E</sup>			View All	Search Tasks C	reate New Task   Complete	
Due Dat		Type Tasi	Group Subjec	ct Handler	Assigned By	Completed On	Created On Done	

### Claim Documents

\*SFR8996H (SNM19D203356C02) [SLE6804P] TP KE CHOON LIN Jul 16 2019 6:00PM [-] Premium Automobiles Pte Ltd

Vid	eo		I per pa	ge: V	Ø
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Prin
i	19/07/19 19:48	Video - Accident [Linked Accident Report Documents]	0	Load MP4	
2	19/07/19 19:48	Video - Accident [Linked Accident Report Documents]	0	Load MP4	
Ass	essment Reports		1 per pa	ge 🔽	Ø
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	-
1	20/07/19 09:08	Accident Statement		Load HTM	
				The second	
Pho	otos/Images	Process and the second	3 per pa		2
Nο	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	
1	19/07/19 19:44	Accident Photo [Linked Accident Report Documents]	8	Load JPG	1
2	19/07/19 19:44	Accident Photo [Linked Accident Report Documents]	6	Load JPG	Z
3	19/07/19 19:44	Accident Photo [Linked Accident Report Documents]	6	Load JPG	Z
4	19/07/19 19:44	Accident Photo [Linked Accident Report Documents]	0	Load JPG	Ø
5	19/07/19 19:44	Accident Photo [Linked Accident Report Documents]	8	Load 3PG	2
6	19/07/19 19:44	Accident Photo [Linked Accident Report Documents]	8	Load JPG	12
7	19/07/19 19:44	Accident Photo [Linked Accident Report Documents]	0	Load JPG	120
8	19/07/19 19:44	Accident Photo [Linked Accident Report Documents]	0	Load JPG	Ø
9	19/07/19 19:44	Accident Photo [Linked Accident Report Documents]	6	Load JPG	12
10	19/07/19 19:44	Accident Photo [Linked Accident Report Documents]	0	Load JPG	82
11	19/07/19 19:44	Accident Photo [Linked Accident Report Documents]	0	Load JPG	2
12	19/07/19 19:44	Accident Photo [Linked Accident Report Documents]	6	Load JPG	2
13	19/07/19 19:44	Accident Photo [Linked Accident Report Documents]	0	Load JPG	2
14	19/07/19 19:44	Accident Photo [Linked Accident Report Documents]	0	Load JPG	Ø
15	19/07/19 19:44	Accident Photo [Linked Accident Report Documents]	0	Load JPG	2
16	19/07/19 19:44	Accident Photo [Linked Accident Report Documents]	8	Load JPG	82
17	19/07/19 19:44	Accident Photo [Linked Accident Report Documents]	0	Load JPG	Ø
18	19/07/19 19:44	Accident Photo [Linked Accident Report Documents]	0	Load JPG	Ø
19	19/07/19 19:44	Accident Photo [Linked Accident Report Documents]	0	Load JPG	Ø
20	19/07/19 19:44	Accident Photo [Limited Accident Report Documents]	0	Load JPG	Ø
21	19/07/19 19:44	Accident Photo [Linked Accident Report Documents]	0	Load JPG	Ø
22	19/07/19 19:44	Accident Photo [Linked Accident Report Occuments]	0	Load JPG	Ø
Nα	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
1	12/12/19 12:06	General View	0	Load JPG	V
2	12/12/19 12:06	Chassis Number	0	Load JPG	Ø
3	12/12/19 12:06	General View	0	Load JPG	V
4	12/12/19 12:06	General View	0	Load JPG	V

Page 2 of 3

Vid	/ideo		1 per s	page v	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	1	Thumbnail	Print
5	12/12/19 12:06	General View	0	Load JPG	V
6	12/12/19 12:06	General View	0	Load JPG	☑
7	12/12/19 12:06	General View	0	Load 3PG	$\nabla$
8	12/12/19 12:06	General View	0	Load 3PG	8
9	12/12/19 12:06	General View	0	Load JPG	2
10	12/12/19 12:06	General View	0	Load JPG	M
11	12/12/19 12:06	General View	0	Load JPG	
12	12/12/19 12:06	General View	8	Load JPG	2
13	12/12/19 12:06	General View	0	Load JPG	
14	12/12/19 12:06	General View	0	Load JPG	
15	12/12/19 12:06	General View	0	Load JPG	12
16	12/12/19 12:06	General View	0	Load JPG	V
17	12/12/19 12:06	General View	0	Load JPG	Ø
18	12/12/19 12:06	General View	0	Load JPG	12
19	12/12/19 12:06	BEFORE PAINT PHOTOS	8	Load JPG	Ø
20	12/12/19 12:06	BEFORE PAINT PHOTOS	0	Load JPG	W
21	12/12/19 12:06	BEFORE PAINT PHOTOS	0	Load JPG	Ø
22	12/12/19 12:06	BEFORE PAINT PHOTOS	0	Load JPG	2
23	12/12/19 12:06	BEFORE PAINT PHOTOS	0	Load JPG	Z
24	12/12/19 12:06	BEFORE PAINT PHOTOS	0	Load 3PG	Z
25	12/12/19 12:06	BEFORE PAINT PHOTOS	0	Load JPG	~
26	12/12/19 12:06	BEFORE PAINT PHOTOS	0	Load JPG	2
27	12/12/19 12:06	BEFORE PAINT PHOTOS	8	Load JPG	2
28	12/12/19 12:06	BEFORE PAINT PHOTOS	8	Load JPG	Z
29	12/12/19 12:06	BEFORE PAINT PHOTOS	0	Load JPG	R
30	12/12/19 15:56	BEFORE PAINT PHOTOS	0	Load JPG	V
Doc	cumentation		1 per	page 💟	2
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	19/07/19 19:46	Sketch Plan [Linked Accident Report Documents]	0	Load JPG	$\overline{\mathbf{Z}}$
2	19/07/19 19:46	Sketch Plan #2 [Linked Accident Report Documents]	0	Load JPG	Ø

### **Linked Accident Report Documents**

			View	View in Brown	ser v
Vid	eo		1 per i	page V	V
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	19/07/19 19:48	Video - Accident	0	Load MP4	
2	19/07/19 19:48	Video - Accident MEAN VIDEO RECORD	0	Load MP4	
Ass	essment Reports		1 per s	page.	<b>2</b>
Nα	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	20/07/19 09:08	Accident Statement	0	Load HTM	
Pho	tos/Images		3 per	page 🔽	V
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	19/07/19 19:44	Accident Photo	0	Load JPG	$\overline{\mathbf{v}}$
2	19/07/19 19:44	Accident Photo	0	Load JPG	2
3	19/07/19 19:44	Accident Photo	0	Load JPG	
4	19/07/19 19:44	Accident Photo	0	Load JPG	Ø
5	19/07/19 19:44	Accident Photo	0	Load JPG	Ø
6	19/07/19 19:44	Accident Photo	0	Load JPG	<b>M</b>
7	19/07/19 19:44	Accident Photo	0	Load JPG	V
8	19/07/19 19:44	Accident Photo	0	Load JPG	Ø
9	19/07/19 19:44	Accident Photo	0	Load 3PG	Ø
10	19/07/19 19:44	Accident Photo	0	Load JPG	120
11	19/07/19 19:44	Accident Photo	0	Load JPG	

Vide	eo		1 per p	age 🔍	2
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	di Taninahani
	1				80
12	19/07/19 19:44	Accident Photo	0	Load JPG	☑
13	19/07/19 19:44	Accident Photo	6	Load JPG	82
14	19/07/19 19:44	Accident Photo	0	Load JPG	N
15	19/07/19 19:44	Accident Photo	0	Load 3PG	2
16	19/07/19 19:44	Accident Photo	0	Load JPG	N
17	19/07/19 19:44	Accident Photo	0	Load 3PG	V
18	19/07/19 19:44	Accident Photo	0	Load 3PG	Z
19	19/07/19 19:44	Accident Photo	6	Load JPG	N
20	19/07/19 19:44	Accident Photo	0	Load JPG	M
21	19/07/19 19:44	Accident Photo	0	Load JPG	10
22	19/07/19 19:44	Accident Photo	0	Load JPG	Ø
Doc	cumentation		1 per s	age 🔻	Ø
No:	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	1
1	19/07/19 19:46	Sketch Plan	0	Load JPG	100
2	19/07/19 19:46	Sketch Plan #2	0	Load JPG	V

### **Documents Checklist**

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			1
			3
Show Remarks To: Handling Insurer  Note: Remarks are private unless you show it to other parties.			

Page 1 of 4 Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19012892/AQF3E2

Date:

19/12/2019

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: Insured

DMPCSN17583018011

Claimant Vehicle No:

SFR8996H

Vehicle No:

SLE6804P

Date of Loss:

16/07/2019

Nature of Claim: TP

Claim No:

SNM19D203356C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SFR8996H

Make & Model:

AUDI A4, 2.0 (A)

06/08/2018 (Man. Year: 2018)

Engine No: Chassis No: Odometer:

WAUZZZF42JA205453

CVK065677

16979 km

Reg. Date: Colour:

Black

Engine Capacity: Market Value/New Car 1984 cc

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Yes Engine Modification:

No

Front Tyre Size: Front Left Side:

205/60 R16

Rear Tyre Size: Rear Left Side:

205/60 R16 Continental 6 mm

Front Right Side:

Continental 6 mm Continental 6 mm

Rear Right Side:

Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,236.00	4,559.10	9,676.90	67.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,792.00	3,482.00	5,310.00	60.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,028.00	8,041.10	14,986.90	65.08
+ GST 7.00/7.00% (S\$)	1,611.96	562.88	1,049.08	65.08
Nett Amount (S\$)	24,639.96	8,603.98	16,035.98	65.08

INSPECTION

Date of Assignment:

12/12/2019

Date Inspected:

24/07/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair:

6.0 days

Manager: SHIAU CHAN Adjuster: ADRIAN LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

Reference
Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Dec 2019)

Parts: 143 AUDI A4 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFR8996H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Deformed	2,015.00 FS	2,015.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	66.00 FS	*-FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	203.00 FS	*-FS
4	1		*REAR BUMPER SPOILER	Cut	227.00 FS	*226.50 FS
5	2		*REAR LIGHT REFLECTOR - LH / RH	Not Necessary	76.00 FS	*-FS
6	1		*REAR BUMPER CARRIER	Bent	819.00 FS	*819.00FS
7	1		*BUMPER SEAL	Not Necessary	25.00 FS	*-FS
8	1		*REAR BUMPER GUIDE SECTION - LH	Damaged	40.00 FS	*39.80 FS
9	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	41.00 FS	*-FS
10	2		*REAR BUMPER GUIDE SECTION - UPPER LH / RH	Not Necessary	40.00 FS	*-FS
11	1		*AERIAL RETAINER	Not Necessary	23.00 FS	*-FS
12	1		*TELEPHONE AERIAL	Not Necessary	164.00 FS	*-FS
13	1		*BOOT LID CONTROL UNIT	Not Necessary	381.00 FS	*-FS
14	1		*PARKING AID SENSOR (3PCS)	Damaged (1Pc Only)	693.00 FS	*231.00 FS
15	4		*SEAL RING	Not Necessary	12.00 FS	*-FS
16	1		*SET BUMPER WIRING	Not Necessary	618.00 FS	*-FS
17	1		*REAR LID	Repair	2,470.00 FS	*-FS
18	1		*LID LOCK	Not Necessary	210.00 FS	*-FS
19	1		*REAR LID ATTACHMENT PARTS	Not Necessary	131.00 FS	*-FS
20	1		*FLAP GASKET	Not Necessary	185.00 FS	*-FS
21	1		*ADHESIVE PACKING	Necessary	18.00 FS	*17.40 FS
22	1		*AUDI EMBLEM	Necessary	113.00 FS	*112.50 FS
23	1		*A4 INSCRIPTION	Necessary	87.00 FS	*86.60 FS
24	1		*TFSI INSCRIPTION	Necessary	87.00 FS	*86.60 FS
25	1		*LED TAIL LIGHT - LH / RH	Not Necessary	1,862.00 FS	*-FS
26	2		*TAIL LIGHT TRIM - LH / RH	Not Necessary	54.00 FS	*-FS
27	2		*LED LICENSE PLATE LIGHT	Not Necessary	191.00 FS	*-FS
28	1		*REINFORCEMENT CROSS PANEL	Repair	461.00 FS	*-FS
29	1		*REAR CROSS PANEL TRIM	Not Necessary	154.00 FS	*-FS
30	1		*REAR SILENCER	Dented	813.00 FS	*812.50 FS
31	1		*DUAL CLIP	Not Necessary	45.00 FS	*-FS
32	1		*EXHAUST SILENCER BRACKET	Damaged	38.00 FS	*37.90 FS
33	1		*CENTRE SILENCER	Not Necessary	825.00 FS	*-FS
34	1		*EXHAUST SILENCER BRACKET	Not Necessary	19.00 FS	*-FS
35	1		*EXHAUST SILENCER BRACKET	Not Necessary	45.00 FS	*-FS
36	1		*MUFFLER CLAMP	Damaged	45.00 FS	*44.30 FS
37	1		*REAR NO. PLATE	Not Necessary	40.00 FS	*-FS
38	1		*ARYCLIX SEALANT	Not Necessary	180.00 FS	*-FS
39	1		*CAVITY WAX	Not Necessary	140.00 FS	*-FS
40	1		*STONE CHIP	Not Necessary	180.00 FS	*-FS
41	1		*SUNDRIES	Necessary	400.00 FS	*30.00 FS
			Report was unsubmitted during th	is print-out		

Adjuster Report Page 3 of 4

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Fra	nchise	part. S=5	SpcNett.	Total Parts (S\$)	4,559.10	
			Report was u	nsubmitted during this print-out.		

Adjuster Report Page 4 of 4

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	0.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO COMPONENTS	New	480.00	0.00
4	TO DISMANTLE AND RENEW BUMPER AND REAR LID. CUT OUT AND REWELD END PANELLING. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED		4,200.00	1,050.00
5	TO RESPRAY REAR BUMPER, REAR LID END PANELLING. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	2,800.00	1,400.00
6	TO RENEW LHS REAR EXHAUST SILENCER AND CENTRE EXHAUST SILENCER. TO ALIGN TO POSITION	New	480.00	480.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labou	r Cost (S\$)	8,792.00	3,482.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >