

Adrian

Merimen

Front:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

1900004016

Claims No.

Sum Insured:

Excess:


1600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

170K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

18/6

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

ASSIGNMENT

Veh No:

SMH1239B.

Yr Regn:

2019, Jan.

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Andi AS SB.

c.c

1984.

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

6919.

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAU22F58KA009883

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 245/40R18-

R:

245/40R18-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

18/7/19

D.O.I.

22/07/19.

Survey held at

Premium.

Des. of Damages: Frt / Rear / O/S / NS / U/C / Rooftop or

Front O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD AIG.

SMH1239B-X

23/7/19

Revert via merimen

24/7/19

Rece approved \$17,939 from victor by merimen

24/7/19

Informed Tony CIA ex \$1600 by email

30/8/19

Final fig \$15,697.52 (Red 23,894.48, 60% confirmed by email

RECEIVED 10 SEP 2019

Date/Time, File Pass to?

Date/Time, File Return to?

1) 14/9 - typist

2)

3)

4)

5)

6)

Preli. report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 24 July 2019 12:38 PM
To: Claims Dept; SUR
Cc: (nora.khai@premiumauto.com.sg)
Subject: RE: OD CLAIM FOR SMH 1239 B - VEHICLE IN (DOA: 18/7/2019)

Dear Tony,

As instructed by our client, please proceed to repair the **insured vehicle SMH 1239B (Excess \$1600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 24 July 2019 11:54 AM
To: Claims Dept <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: OD CLAIM FOR SMH 1239 B - VEHICLE IN (DOA: 18/7/2019)

Dear Tony,

Still pending approval from AIG.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Wednesday, 24 July 2019 11:46 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Claims Dept' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIM FOR SMH 1239 B - VEHICLE IN (DOA: 18/7/2019)

Dear Veron,

Any update? Owner call in Aig and they mention have approve the claim.

Thank you.

Best Regards,
Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Singapore 408699

p. +65 6366 2323, d. +65 67689911

e.<mailto:claims@premiumauto.com.sg> w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]

Sent: Tuesday, 23 July 2019 12:37 PM

To: Claims Dept; SUR

Subject: RE: OD CLAIM FOR SMH 1239 B - VEHICLE IN (DOA: 18/7/2019)

Dear Tony,

Pending approval from AIG.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>

Sent: Tuesday, 23 July 2019 9:44 AM

To: SUR <sur@lkkauto.com>

Cc: 'Claims' <claims@premiumauto.com.sg>

Subject: OD CLAIM FOR SMH 1239 B - VEHICLE IN

Dear all,

Kindly assist follow up repair approval. Owner will call in to AIG for follow up.

Thank you.

Best Regards,
Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Singapore 408699

p. +65 6366 2323, d. +65 67689911

e.<mailto:claims@premiumauto.com.sg> w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

View Received Message

This mail is associated with :

***SMH1239B (9191504728SG)**

OD

Jul 18 2019 9:00AM

[TAN KIM YIAN]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 24/07/2019 11:59 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$17939.00) - SMH1239B - Claim Handler: Mithoo Singh, Aashweenjeet Kaur

Approved:17939.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 23 Jul 2019

Preliminary Advice

Vehicle No	: SMH1239B	Accident Date	: 22/07/2019
Make	: AUDI A5	Policy No.	: 1900004016
Assignment Date	: 23/07/2019	Excess	: S\$0.00
Date of Inspection	: 22/07/2019	Est. Duration of Repair	: 6.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	39,592.00
Revised Amount	:S\$	17,939.00
Check Items (Estimated)	:S\$	2,481.00
Total	:S\$	20,420.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	170,000.00
COE / PARF Rebate	:S\$	65,568.00
Salvage Value	:S\$	
Margin for Repair	:S\$	104,432.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/07/2019 10:27
Date Of Accident	18/07/2019 09:00
Exact Location Of Accident	EXIT OF SHENTON HOUSE CAR PARK ENTRANCE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMH1239B
Insured/Policyholder	
Name Of Registered Owner	TAN KIM YIAW
NRIC No	S7203546A
Email Address	CHERIETANKY@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96730553
Alternative Phone No	OFFICE-96730553

Vehicle Particulars

Manufacturer	AUDI
Model	A5-2.0 SPORTBACK (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900004016
Cover Note Number	

Driver

Name of Driver	TAN KIM YIAW
NRIC No	S7203546A
Date Of Birth	23/01/1972
Occupation	INDOOR
Date Of Driving Pass	12/06/2003
Driving Experience	16 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-96730553
Fax Number	
Contact Number	OFFICE-96730553
Email Address	CHERIETANKY@GMAIL.COM

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN

A = SMH1239B

B = SHB8932C



Stationary while
traffic light was Red.
When traffic light
turn to green.
The taxi move forward
& hit vehicle A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My Car SMH1239B exited from Shenton House Carpark and was driving into Shenton Road. The first lane is a bus lane and 2nd & 3rd lane are yellow box. As the traffic light is turning red, all cars are slowing down to a stop.

The car on the 4th lane saw my signal light to keep right and had stopped to give way for me. So my car was stopped at the 4th lane. Vehicle SHB 8932C was on the 5th lane and stopping slightly behind me.

As there is a good distance for me to enter my car into the 5th lane, I signal my intention and turned on my Right Signal light. Vehicle SHB8932C has full visibility my car is already entering the 5th lane as all cars are not moving. Looking at the photo taken at the scene, My car SMH1239B can be clearly seen in a position where it has just travelled straight out from the left and it is not on a moving lane trying to filter right.

When the traffic light turned Green I moved my vehicle slowly out and was shocked the taxi SHB8932C just banged onto me.

The taxi driver did not display his identity label inside the car and

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 19/7/2019

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: Loay Fary

NRIC/FIN No: 620401611



Driving License



[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	546A
Vehicle Details	
Vehicle No.:	SMH1239B
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jul 2019
Vehicle Make:	AUDI
Vehicle Model:	A5 SB 2.0 TFSI S TRONIC (DESIGN)
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	CVK073197
Chassis No.:	WAUZZZF58KA009883
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$39,101.00
Original Registration Date:	11 Jan 2019
First Registration Date:	11 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$46,742.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Jan 2029
PARF Rebate Amount:	\$35,056.00
Intended COE Rebate Details	
COE Expiry Date:	10 Jan 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,200.00
COE Rebate Amount:	\$30,512.00
Total Rebate Amount:	\$65,568.00

The information contained herein is correct as at 19 Jul 2019

OK

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Policy No. : 1900004016

Period of Insurance : 11 Jan 2019 to 10 Jan 2020

Issued Date : 12 Jan 2019

ABOUT THE POLICYHOLDER

Name of Policyholder : TAN KIM YIAN (CHEN JINYAN)

Address : 47 JALAN TIGA
09-46
SINGAPORE 390047

Occupation/Nature of Business : Manager/Director/Management

ABOUT THE VEHICLE

Registration No. : SMH1239B

Chassis No. : WAUZZZF58KA009883

Seating Capacity : 5 First Year of Registration : 2019

Make/Model : AUDI A5 Sportback 2.0TFSI S Tronic (Design)

Hire Purchase Company/Employer's Loan : DBS BANK LTD

Engine Capacity/Tonnage : 1,984.00 CC

Engine No. : CVK073197

Body Type : Sedan

ABOUT THE COVER

Sum Insured : Market Value

Driver Restriction : NA

Off Peak Car : No

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive :

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Other Key Policy Benefits :

Act of God, Strike, Riots and Civil Commotions, PA to Authorised Driver / Unnamed Passengers- \$10000, Dealer + AIG Authorised Workshops, PA Insured- \$100000, Fixture and Accessories (Cosmetic)- \$5000, Solar Film- \$1150, New For Old (36 months), Loss of Use 1800cc - 2000cc Optional, In-Car Camera Excess Waiver, Glass Roof/ Moon Roof/ Sun Roof/ Panoramic Glass Roof

EXCESS

Section 1

Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver

TAN KIM YIAN (CHEN JINYAN) - \$1600 (Own Damage)

PREMIUM

Premium : \$ 2,959.24

GST (7%) : \$ 207.15

Total : \$ 3,166.39

Your Premium includes the following discount(s):

No Claim Discount - 0%

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7203546A



Name
**TAN KIM YIAN
(CHEN JINYAN)**

Race
CHINESE
Date of Birth
23-01-1972 Sex
F
Country of Birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S7203546A**
Name

**TAN KIM YIAN
(CHEN JINYAN)**

Birth Date: **23 Jan 1972**
Issue Date: **12 Jun 2003**



2211455

NRIC No: **S7203546A**



Blood Group
AB+ Date of issue
21-07-1994


**APT BLK 47 JALAN TIGA #09-46
SINGAPORE 390047**

NRIC No: **S7203546A** Date: **26/06/2014**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms 24 Jun 1992



NP 428A

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0879/2019/NS
Date	:	22-Jul-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms. Tan Kim Yian
Address	:	Blk 47 Jalan Tiga #09-46 Singapore 390047
Telephone	:	(HP)+65 96730553
Type of Claim	:	Own Damage Claims
Policy No.	:	1900004016
Vehicle No	:	SMH 1239 B
Model Code	:	Audi A5 SB 2.0 TFSI Quattro (A)
Model / Year	:	11/1/2019
Engine No	:	CVK 073197
Chassis No	:	WAUZZZF58KA009883
Mileage	:	6918
Date In	:	19-Jul-19
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	18-Jul-19
Place of Accident	:	Exit Of Shenton House Carpark Entrance

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMH 1239 B

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
2	To remove and reinstall additional radiator and aircon condensor. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	X
3	To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$ 300.00	✓
4	To dismantle and renew front bumper, bonnet, rhs front fender and rhs headlight. To repair rhs front door. To remove and renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 6,400.00	1250 ✓
5	To respray front bumper, bonnet, rhs front fender and rhs front door	\$ 4,400.00	1650 ✓
6	To renew rhs front rim and carry out wheel alignment	S/N \$ 280.00	X
7	To carry out diagnostic check	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 13,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 1239 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>distorted</i>	\$ 2,073.00	✓ 1655.40
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 368.00	+
3	FRONT BUMPER SECURING STRIP <i>Not New</i>	\$ 32.00	? X
4	FRONT BUMPER GRILLE - CENTER <i>new distorted</i>	\$ 178.00	x. 142.40
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>embled</i>	\$ 207.00	? 165.60
6	FRONT BUMPER SPOILER <i>for new</i>	\$ 489.00	x
8	FRONT BUMPER AIR GUIDE - RH <i>distorted</i>	\$ 56.00	✓ 44.40
9	RADIATOR GRILLE <i>embled</i>	\$ 2,131.00	✓ 1704.80
10	ULTRA SOUND SENSOR SUPPORT - LH / RH <i>new</i>	2 \$ 96.00	✓ 75.52
11	RADIATOR GRILLE COVER - UPPER <i>Not New</i>	\$ 174.00	? X
12	FRONT BUMPER AIR GUIDE GRILLE - RH <i>distorted</i>	\$ 431.00	✓ 344.40
13	FRONT BUMPER CARRIER <i>Not New</i>	\$ 733.00	? X
14	FRONT BUMPER FOAM FILLER PIECE <i>embled</i>	\$ 113.00	✓ 90.40
15	FRONT BUMPER TOP COVER <i>new embled</i>	\$ 116.00	? 92.40
16	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	\$ 33.00	✓ 26.08
17	FRONT BUMPER FOAM FILLER PIECE - RHS <i>Not new</i>	\$ 16.00	? X
18	FRONT BUMPER BRACKET FOR LOCK CARRIER <i>embled</i>	\$ 125.00	✓ 100
19	REINFORCEMENT BEAM SUPPORT - LH / RH <i>new</i>	2 \$ 52.00	x
20	FRONT PARKING AID SENSOR - FRONT OUTER <i>new</i>	2 \$ 231.00	x.
SUB-TOTAL SPARE PARTS		\$ 7,654.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 1239 B

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
21	FRONT PARKING AID SENSOR - FRONT INNER	new	\$ 231.00	+
22	FRONT PARKING AID SENSOR SEAL RING	new 4	\$ 12.00	✓
23	BUMPER WIRING SET	new	\$ 470.00	+
24	HORN - LOW TONE RIGHT	new	\$ 262.00	+
25	HORN BRACKET - RH	new	\$ 26.00	+
26	FRONT BUMPER BRACKET - RHS	new	\$ 195.00	? X
27	FRONT FENDER - RH	Dented	\$ 968.00	✓ 77440
28	FRONT FENDER ATTACHMENT PARTS	new	\$ 48.00	? X
29	FRONT FENDER CLOSING ELEMENT - RH	Dented	\$ 68.00	? 53.76
30	FRONT FENDER BRACKET - RH	new	\$ 32.00	+
31	POP RIVET	new 5	\$ 15.00	✓ 1440
32	FRONT FENDER BRACKET - RH	new	\$ 32.00	? X
33	FRONT FENDER BRACE - RIGHT FRONT	Dented	\$ 107.00	? 85.60
34	DEFORMATION ELEMENT BRACKET - RH	new	\$ 45.00	✓ 35.60
35	WHEEL HOUSING LINER - RH	to in	\$ 256.00	✓ 204.80
36	WHEEL HOUSING LINER ATTACHMENT PARTS FRONT AND RE	new	\$ 82.00	? X
37	WHEEL SPOILER	new	\$ 66.00	✓ 50.32
38	SPOILER - RH	new	\$ 33.00	✓ 25.84
39	STONE CHIP GUARD - RH	new	\$ 46.00	✓ 36.64
40	FRONT FENDER TRIM - RH	new	\$ 145.00	✓ 115.60
SUB TOTAL SPARE PARTS			NEC \$	
			: \$	<u>3,139.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 1239 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	FRONT DOOR TRIM - RH <i>new</i>	\$ 145.00	✓ 115.60
42	FENDER TOP LEDGE COVER - LONG RH <i>new</i>	\$ 32.00	✓ 25.44
43	FENDER TOP LEDGE COVER - SHORT RH <i>new</i>	\$ 14.00	✓ 11.04
44	BONNET <i>new</i>	\$ 2,602.00	+
45	IMPACT PROTECTION - CENTRE <i>new</i>	NEC \$ 25.00	+
46	IMPACT PROTECTION - LEFT <i>new</i>	NEC \$ 25.00	+
47	IMPACT PROTECTION - RIGHT <i>new</i>	NEC \$ 25.00	+
48	LED HEADLIGHT - RH <i>cat</i>	\$ 7,204.00	✓ 5763.20
49	MAIN LIGHT ELECTRONICS POWER MODULE <i>new</i>	\$ 693.00	+
50	LIGHT CONTROL SYSTEM CONTROL UNIT <i>new</i>	\$ 685.00	+
51	LED HEATS <i>new</i>	\$ 1,053.00	+
52	HEADLIGHT HOSE - RH <i>new</i>	\$ 32.00	+
53	LIFT CYLINDER - RH <i>new</i>	\$ 181.00	? X
54	LIFT CYLINDER BRACKET <i>new</i>	\$ 13.00	? X
55	LIFT CYLINDER HOSE LONG <i>new</i>	\$ 78.00	+
56	LIFT CYLINDER HOSE <i>new</i>	\$ 35.00	+
57	CAUTION SIGN <i>new</i>	NEC \$ 132.00	+
58	AIR COND STICKER <i>new</i>	NEC \$ 7.00	5.12
59	RADIATOR AIR GUIDE - RH <i>new</i>	\$ 28.00	? X
60	RADIATOR AIR GUIDE - RH <i>new</i>	\$ 15.00	? X
SUB TOTAL SPARE PARTS		\$ 13,024.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 1239 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
61	RADIATOR AIR GUIDE - UPPER <i>{ New</i>	\$ 15.00	? X
62	RADIATOR AIR GUIDE - LOWER	\$ 19.00	? X
63	LOCK CARRIER <i>New</i>	\$ 928.00	+
64	RADIATOR COOLANT <i>New</i>	4 \$ 165.00	+
65	ALUMINIUM RIM - RH <i>{ New</i>	\$ 943.00	+
66	RUBBER VALVE	4 \$ 13.00	+
67	FRONT NO. PLATE <i>New</i>	S/N \$ 40.00	✓ 40
68	SUNDRIES <i>New</i>	\$ 400.00	? 51.76
TOTAL SPARE PARTS		\$ 26,340.00	
TOTAL LABOUR CHARGES		\$ 13,252.00	
GRAND TOTAL		\$ 39,592.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adam L
: 22/07/19

:
:
: Not Authorised, 06 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0879/2019/NS
Date : 22-Jul-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

6 days - ok - jb - 24 Aug 19

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Tan Kim Yian
Address : Blk 47 Jalan Tiga
#09-46
Singapore 390047
Telephone : (HP)+65 96730553
Type of Claim : Own Damage Claims
Policy No. : 1900004016
Vehicle No : **SMH 1239 B**
Model Code : Audi A5 SB 2.0 TFSI Quattro (A)
Model / Year : 11/1/2019
Engine No : CVK 073197
Chassis No : WAUZZZF58KA009883
Mileage : 6918
Date In : 19-Jul-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 18-Jul-19
Place of Accident : Exit Of Shenton House Carpark Entrance

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMH 1239 B

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00	\$ 480.00
2	To remove and reinstall additional radiator and aircon condensor. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$ 1,200.00	na
3	To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N	\$ 300.00	\$ 300.00
4	To dismantle and renew front bumper, bonnet, rhs front fender and rhs headlight. To repair rhs front door. To remove and renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.		\$ 6,400.00	\$ 1,250.00
5	To respray front bumper, bonnet, rhs front fender and rhs front door		\$ 4,400.00	\$ 1,650.00
6	To renew rhs front rim and carry out wheel alignment	S/N	\$ 280.00	
7	To carry out diagnostic check	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 13,252.00	\$ 3,872.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMH 1239 B

S/N	Parts Description		<u>Damaged Parts & Prices</u>	
			<u>S/Nett</u>	<u>Remark</u>
1	FRONT BUMPER		\$ 2,073.00	\$ 1,658.40
2	FRONT BUMPER FIXING PARTS		\$ 368.00	
3	FRONT BUMPER SECURING STRIP		\$ 32.00	
4	FRONT BUMPER GRILLE - CENTER		\$ 178.00	\$ 142.40
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 207.00	\$ 165.60
6	FRONT BUMPER SPOILER		\$ 489.00	
8	FRONT BUMPER AIR GUIDE - RH		\$ 56.00	\$ 44.40
9	RADIATOR GRILLE		\$ 2,131.00	\$ 1,704.80
10	ULTRA SOUND SENSOR SUPPORT - LH / RH	2	\$ 96.00	\$ 75.52
11	RADIATOR GRILLE COVER - UPPER		\$ 174.00	
12	FRONT BUMPER AIR GUIDE GRILLE - RH		\$ 431.00	\$ 344.40
13	FRONT BUMPER CARRIER		\$ 733.00	
14	FRONT BUMPER FOAM FILLER PIECE		\$ 113.00	\$ 90.40
15	FRONT BUMPER TOP COVER		\$ 116.00	\$ 92.40
16	FRONT BUMPER GUIDE SECTION - RH		\$ 33.00	\$ 26.08
17	FRONT BUMPER FOAM FILLER PIECE - RHS		\$ 16.00	
18	FRONT BUMPER BRACKET FOR LOCK CARRIER		\$ 125.00	\$ 100.00
19	REINFORCEMENT BEAM SUPPORT - LH / RH	2	\$ 52.00	
20	FRONT PARKING AID SENSOR - FRONT OUTER	2	\$ 231.00	
SUB-TOTAL SPARE PARTS		:	\$ 7,654.00	\$ 4,444.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.