

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS FIRST CAPITAL INSURANCE LTD			Ref: CS/FCI19012994/Eyd3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date: 09-04-2020 Code: FCI2		
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 7250H	Veh. Inspected	SMJ 4854U	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	D19004771MFSH	Excess (\$)	0.00	
	Assign From	MAY CHUA	Assign Date	23/07/2019	
2.	2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE HYBRID	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	GP72003534	Colour	RED	
	Odometer	48167	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	185/60 R15	FIRENZA	5 mm	
	L/H Front Tyre	185/60 R15	FIRENZA	5 mm	
	R/H Rear Tyre	185/60 R15	FIRENZA	5 mm	
	L/H Rear Tyre	185/60 R15	FIRENZA	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	20/07/2019	Inspection Date	08/10/2019	
	Survey held at	HUA HONG PTE LTD			
	25D SUNGEI KADUT STREET 1 SINGAPORE 729332				
5a.	Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	4 Working Days		