

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : GBJ 2804 H Case Owner : JOHARI

Make & Model : NISSAN URVAN NV350 Year Manufacture : 2018

Chassis No : JN1MC2E26Z0030859 Engine No : YD25042597B

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : OD

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	RAD GRILLE	1	\$ 360.00				
2	GRILLE LOGO	1	\$ 45.00				
3	F BUMPER SIDE BKT RH	1	\$ 70.00				
4	F BUMPER BKT LH	1	\$ 70.00				
5	FRT BUMPER	1	\$ 280.00				
6	FRT BUMPER CLIPS	10	\$ 15.00				
7	FRT BUMPER GRILLE	1	\$ 350.00				
8	FOG LAMP COVER LH	1	\$ 75.00				
9	INTER COOLER	1	\$ 1,500.00				
10	TAIL LAMP RH	1	\$ 110.00				
11	RR BUMPER	1	\$ 280.00				
12	RR BUMPER CLIPS	6	\$ 9.00				
13	F MUD FLAP RH	1	\$ 70.00				
14	RR AIR DUCT	1	\$ 35.00				
15	ROAD WHEEL	1	\$ 185.00				
16	HUB CAP	2	\$ 210.00				
17	FRT DOOR HINGE LWR RH	1	\$ 38.00				
18	OIL COOLER AIR GUIDE LH	1	\$ 95.00				
19	FENDER & UNDER COVER CLIPS <i>new</i>	3	\$ 4.50	✓			
20	INTER COOLER GUIDE <i>new</i>	1	\$ 75.00	✓			
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

387650

Spark Car Care

ComfortDelGro Engineering Pte Ltd

16/09/2019

4:35 PM

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
Tel: 68438723/68438736 Fax:67436072

Supplementary 1

Vehicle No : <u>GBJ2804H</u>	Case Owner : <u>JOHARI</u>
Make & Model : <u>NISSAN NV 350</u>	Year Manufacture : <u>2018</u>
Chassis No : <u>JA1MC2E26Z0030859</u>	Engine No : <u>YD25042597</u>
Sales Order : _____	Supplier : _____
Order By : _____	Type of Claim : <u>OD</u>

S/No	Part Description	QTY	Cost Price	List Price	Nett Item	S/N	Disposition By Surveyor
1	RADIATOR ASSY	1	\$ 500.00				
2	COOLANT	1	\$ 30.00				
3	HEADLAMP RH	1	\$ 210.00				
4	HEADLAMPH	1	\$ 210.00				
5	FRONT NUMBER PLATE	1				\$ 45.00	
6	70kmH sticker	1		see		\$ 10.00	(A) —
7							
8							
9							
10							
11							
12							
13							
14	PO 4500816868						
15							
16							
17	PO 4500816050						
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

\$950

Spark Car Care