

## SMRT Accident Vehicle Repair Estimates

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672



Date Generated : 23/07/2019

User ID : TuckFoo

## Section A - Accident Details

Registration Number	SHB5506U
Case Reference Number	TAX/07/19/2080
Registration Date	11/1/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	CHEW CHOON KEE ( JIANG JUNQI )
Type of Accident	Side Swipe
Accident Date and Time	7/20/2019 8:30 PM
Accident Reported Date and Time	7/22/2019 11:30 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	7/20/2019 9:45 PM
Replacement Vehicle issued?	No
Job Card Number	24102498
Special Instruction to ARC, if any	TP/TOWED \$40
Prepared Date and Time	7/23/2019 2:23 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

## Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$0.00	\$0.00
Total Spray Cost	\$180.00	\$80.00
Total Spare Part Cost	\$1,222.64	\$0.00
Total Other Cost	\$256.00	\$80.00
<b>TOTAL COST</b>	<b>\$1,658.64</b>	<b>\$160.00</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	2.0	1.0
Prepared / Adjusted By	Tuck Foo Kok	STEVE CHEN
ARC / Surveyor Sign Off Date	23/07/2019 2:36 PM	23/07/2019 4:16 PM
Signature		
Remarks		P/P repair, finalize sent to stevechen@lkkauto.com

## Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

## Section D - Details of Repair Estimates

## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 23/07/2019

User ID : TuckFoo

### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
Total Labour		

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY VIEW MIRROR	\$180.00	\$80.00
Total Spray Painting & Panel Beating	\$180.00	\$80.00

### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$60.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TOWING CHARGE	\$56.00	\$0.00
Total Other Costs	\$256.00	\$80.00

### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		8794047440	MIRROR ASSY, OUTER REAR VIEW, LH	0.00	\$1,283.90	0.00	\$0.00	Replace	Not Given
		8794547060A1	COVER, OUTER MIRROR, LH	0.00	\$89.50	0.00	\$0.00	Replace	Not Given
Total					\$1,373.40		\$0.00		

### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: