

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To: _____

Accident Date : 16.07.2019

Heavy After Pains

5 day, _____

Date: 24.07.2019

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Nissan NV350" Reg. No. GBF6358Z Claiming Against Your Insured Reg. No. SMD2051P		
1pc	Front Bumper		514.70 N
10pcs	Front Bumper Clips	5.00	50.00 N
1pc	Front Bumper Top Retainer LH		147.00 N X
1pc	Front Bumper Corner Holder LH		104.70 N X
1pc	Front Bumper Fog Lamp		323.70 N X
1pc	Front Bumper Fog Lamp Cover		130.10 N X
1pc	Headlamp LH		403.00 N
1pc	Front Door Lower Step Board		72.50 N
1pc	Front Door Lower Rubber Seal		75.00 N X
1pc	Front Wheel Cap LH		162.80 N
1pc	Front Mudflap LH		155.00 N
1pc	Sliding Door LH		1,777.00 N
	Less 10%		3,915.50
			391.55
			3,523.95
1pc	Front Door Reg Label LH		45.00 SN
	Sliding Door Body Sticker (Customised)		550.00 SN ?
	Rear Fender Body Sticker (Customised)		550.00 SN X
	To Conduct Electrical Check, Focus Headlamp		30.00
	To Dismantle / Transfer Sliding Door Fittings and Accessories		120.00
	To Apply Rust Proofing / Reseal Tuff Coating		60.00
	To Conduct Computerize Wheel Alignment Test		80.00
	Labour Charge - Panel Beating, Repairing Of Front Door , Step Panel, Door 'B' Pillar, Rear Fender and Parts Replacement		700.00
	To Respray Affected Areas		1,200.00
			6,858.95