



Mercedes-Benz

Cycle & Carriage Industries Pte Limited  
Authorised Dealer  
Company No. 198400357W  
GST Reg No. MR-8000111-X

SUPPLEMENTARY

ESTIMATE FOR SGH1645H\*RA

CHINA TAIPING INSURANCE (S) PTE LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

Vehicle & Document Information  
WIP No 23270  
Reg No/Reg Date SGH1645H\*RA / 01/02/2012  
Date In/Mileage 16/05/2018/ 66725  
Chassis No WBD21204824536253  
Engine No 27186030369411  
Make/Model MB/E 200 CGI SEDAN (W212)  
Colour/Trim 024 497 Cuprite Bro/ 042 201 Black

SGH1645H\*RA

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	28/05/2018/ 13:28	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

<p>M. BPNSUN            POLICY NO/ACC. DATE : 8099559808 // 26/04/2018            DRIVE IN EXCESS : 27/04/2018 // TP VEH NO S140398 CHINA TAIPING            DATE IN/DATE SURVEY: 14/05/2018 @ 1315 // BEH LKK            BY/AUTHORIZED ON : DIRECT SETTLEMENT // ALFRED CHINA TAIPING</p>				
A BPILAB ADDITIONAL LABOUR TO REPAIR REAR END PANEL				1440.00
A BPIRES ADDITIONAL LABOUR TO RESPRAY REAR END PANEL				600.00
A BPILAB ADDITIONAL LABOR TO REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHES AND SEATS FOR NEC. REPAIRS.				480.00
X RIVETED NUT	4.00	3.66	00.00	14.64
X PLUG	3.00	0.92	00.00	2.76
X LEFT TAIL LAMP	1.00	611.59	00.00	611.59
M TS TWO-COMPONENT ADHESIVE	1.00	755.31	00.00	755.31

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Yik Chan Hoe  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272  
Email: chanhoe.yik@cyclccarriage.com.sg

Confirmed & accepted by

	Nett	3,904.30
7% GST on	3904.30	273.30
<b>Total Payable</b>		<b>4,177.60</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg