

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: GNOH PAU LOONG

Date: 26 Jul 2019

## **Preliminary Advice**

Insured Vehicle No	: SLH1266J	Accident Date	: 22/07/2019
TP Vehicle No	: SMG6533Z	Assignment Date	: 24/07/2019
Make	: HONDA FIT	Est. Duration of Repair	: 4 days
Date of Inspection	: 25/07/2019		
Inspection At	: Cartimes Autolution (HQ) 160 Sin Ming Drive #02-04 Autocity Singapore 575722		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,713.00
Revised Amount	:S\$	2,394.00
Check Items (Estimated)	:S\$	464.00
Total	:S\$	2,858.00

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : TP : WP