

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0895/2019/NS
Date : 25-Jul-19

Vehicle IN workshop.

Your Insured Vehicle : **SKM 336 H**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Lim Hui Fang Ira
Address : 41 Hume Avenue
#09-02
Singapore 598738
Telephone : HP +65 98770808
Type of Claim : Third Party Claim
Policy No. : 1700090242-01
Vehicle No : **SJY 8869 H**
Model Code : Audi A3 SEDAN 1.0 TFSI
Model / Year : Dec-17
Engine No : CHZ 575944
Chassis No : WAUZZZ8V7J1022748
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Jul-19
Place of Accident : Telok Blangah Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJY 8869 H

S/N	Nature of Jobs	Estimated Charges
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
2	To dismantle and renew front bumper, rhs fender, bonnet and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 3,150.00 1250 .
3	To respray front bumper, bonnet and rhs front fender.	\$ 2,800.00 1850
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
SUB-TOTAL LABOUR CHARGES		: <u><u>\$ 6,502.00</u></u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJY 8869 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER COVER <i>Rehd.</i>	\$ 1,830.00	✓
2	FRONT BUMPER FIXING PARTS <i>see n</i>	\$ 170.00	+
3	FRONT BUMPER GUIDE SECTION - RH <i>Rehd.</i>	\$ 35.00	✓
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>see n</i>	\$ 488.00	+
5	FRONT BUMPER CLOSING ELEMENT - RH ?	\$ 270.00	?
6	FRONT BUMPER COVER TRIM - RH <i>see n</i>	\$ 148.00	+
7	FRONT BUMPER ADAPTER - RH <i>see n</i>	\$ 34.00	+
8	AIR GUIDE GRILLE - RH <i>see n</i>	\$ 171.00	+
9	SIDE REINFORCEMENT <i>see n</i>	\$ 660.00	+
10	FOAM FILLER PIECE <i>see n</i>	\$ 172.00	+
11	FRONT BUMPER COVER <i>see n</i>	\$ 111.00	+
12	SIGNAL HORN - LOW TONE RH ?	\$ 182.00	?
13	FENDER - RH <i>Dented</i>	\$ 778.00	✓
14	POP RIVET <i>m</i>	NEC \$ 15.00	✓
15	FENDER BRACKET - RH <i>Bent</i>	\$ 35.00	✓
16	FENDER SUPPORT ?	\$ 88.00	?
17	WHEEL HOUSING LINER - RH <i>see n</i>	\$ 158.00	+
18	WHEEL HOUSING LINER ATTACHMENT PARTS <i>see n</i>	\$ 81.00	+
19	BONNET <i>Repair</i>	\$ 2,898.00	+
20	BONNET ATTACHMENT PARTS <i>see n</i>	\$ 149.00	+
SUB TOTAL SPARE PARTS :		<u>\$ 8,473.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJY 8869 H

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
41	EDGE PROTECTION <i>neu</i>	NEC \$ 25.00	+
42	LED HEADLIGHT - RH <i>lut</i>	\$ 5,029.00	✓
43	LIFT CYLINDER ?	\$ 128.00	?
44	AIR GUIDE - RH ?	\$ 22.00	?
45	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		: \$ 13,977.00	
TOTAL LABOUR CHARGES		: \$ 6,502.00	
GRAND TOTAL		: \$ 20,479.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 26/07/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant