


Repair Estimate

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model: KIA CARENS 1.7 CRDI
Engine/Chassis No.: KNAHU815VJ7211506
Date of accident:
Damaged area: O/S

Date: 24/07/2019
Claim Type: TP
VRN: SMC7382G



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front door o/s	1	\$ 1,525.00	\$ 1,525.00
2	Front door upper hinge o/s	1	\$ 62.00	\$ 62.00
3	Front door lower hinge o/s	1	\$ 62.00	\$ 62.00
4	Front door weatherstrip o/s	1	\$ 189.00	\$ 189.00
5	Front door inner lock o/s	1	\$ 296.00	\$ 296.00
6	Front door window channel o/s	1	\$ 124.00	\$ 124.00
7	Front door window channel chrome moulding o/s	1	\$ 95.00	\$ 95.00
8	Front door stopper o/s	4	\$ 12.00	\$ 48.00
9	Front door checker o/s	1	\$ 59.00	\$ 59.00
10	Front door rocker panel step garnish o/s	1	\$ 78.00	\$ 78.00
11	Rocker panel o/s ✓ TN	1	\$ 1,269.00	\$ 1,269.00
Subtotal				\$ 3,807.00
List discount				10.00%
Total				\$ 3,426.30

x repair
x nn
x nn
x nn
x nn
x nn
x nn
x nn
x nn
x nn
867

780.3

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front door inner trim board clips o/s	10	\$ 5.50	\$ 55.00
2	Rocker panel sealant o/s	1	\$ 100.00	\$ 100.00
3	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 205.00

x nn
x nn
x nn

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	5	\$ 1,000.00
2	To disconnect o/s front door wire harness and electrical component to facilitate repairs, reconnect and check functions of power windows.	0.25	\$ 50.00

400
x nn

Repair Estimate

3	Supply spray paint material and necessary items to respray o/s front door, o/s rocker panel and other affected area / panel.	5	\$ 1,000.00
4	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,150.00
Estimate Grand Total			\$ 5,781.30

250

60

710

1490.3
20%: 1200

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: