

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

25-Jul-19

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6306 T

1 pc	Front n/s tie rod end	— <i>Boat</i>	\$	61.00
1 pc	Front n/s tie rod	— <i>Boat</i>	\$	96.00
1 pc	front n/s insulator assy strut	— <i>Boat</i>	\$	105.00
			\$	262.00
			Less 10%	\$ 26.20
			\$	235.80

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

