

LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719
Workshop: 24, Sungei Kadut Street 4 Singapore 729050
Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712
Business Reg. No: 36463500B

M/s: AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-10
Singapore 068811

Date : 27.07.2015

Motor Claim Dept

Vehicle number : XD 4304 S
Make/Model : HINO FS1ELKD
Date of accident : 25.07.2015
Claim Type : TP Claim

Accident involving XD 4304 S & YN 4383 Z along Roundabout in Jalan Buroh on 25.07.2015.

Re: Estimate

1.	1 pc	Front bumper	\$	1,957.28	107	✓
2.	1 pc	Front bumper top corner panel RH	\$	210.29	✓	✓
3.	1 pc	Front bumper cover RH	\$	675.09	mis	✓
4.	1 pc	Front bumper side garnish RH	\$	245.62	mis	✓
5.	1 pc	Front no plate	\$	28.00	Xm	✓
6.	1 pc	Front bumper top grille RH	\$	130.64	BR	✓
7.	1 pc	Front bumper top center panel	\$	5,639.61	563.96	✓
8.	1 pc	Front bumper center cover RH	\$	213.03	mis	✓
9.	1 pc	Front door outer garnish RH	\$	211.29	mis	✓
10.	1 pc	Front door inner panel RH	\$	220.05	mis	✓
11.	1 pc	Front step mudguard (top) RH	\$	436.20	W	✓
12.	1 pc	Front step aloy (centre) RH	\$	238.33	Xm	✓
13.	1 pc	Front headlamp RH	\$	2,141.11	mis	✓
14.	1 pc	Front headlamp bracket RH	\$	315.45	mis	✓
15.	1 pc	Front bumper beam RH	\$	1,244.28	mis	✓
16.	1 pc	Front step panel RH	\$	876.70	Xm	✓
17.	1 pc	Front step aloy (lower) RH	\$	238.33	Xm	✓
18.	1 pc	Front step aloy cover (lower) RH	\$	241.00	mis	✓
19.	1 pc	Front reflexor RH	\$	23.20	Xm	✓
20.	1 pc	Front step garnish cover RH	\$	440.55	Xm	✓
21.	1 pc	Front step garnish lamp RH	\$	125.00	Xm	✓
22.	1 pc	Front step water panel RH	\$	130.21	mis	✓
23.	1 pc	Front mudflat RH	\$	40.12	Xm	✓
24.	1 pc	Front moonshape mudguard	\$	1,283.21	mis	✓
25.	1 pc	Front moonshape mudguard side rubber	\$	372.67	W	✓
26.	2 pcs	Front bumper lower garnish	\$	300.00	W	✓
				\$	17,977.26	

LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719
Workshop: 24, Sungei Kadut Street 4 Singapore 729050.
Tel: 6269 9192, 6764 5002 Fax: 6269 2239 H/P: 9631 1712
Business Reg. No: 36463500B

M/s: AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-10
Singapore 068811

Date : 27.07.2015

Motor Claim Dept

Vehicle number : XD 4304 S
Make/Model : HINO FS1ELKD
Date of accident : 25.07.2015
Claim Type : TP Claim

Accident involving XD 4304 S & YN 4383 Z along Roundabout in Jalan Buroh on 25.07.2015 .

Re: Estimate

	\$ 17,977.26
To Towing Service	\$ 160.00 <i>80</i>
To Wiring Service	\$ 120.00 <i>80</i>
To Replace & Repair Labour Charge	\$ 1,300.00 <i>800</i>
To Putty & Spray Painting	\$ 800.00 <i>600</i>
Total	\$ 20,357.26

Yours Faithfully,

李光華 摩哆燒焊

LEE KUAN HWA MOTOR SERVICE
39, Westwood Avenue, Singapore 648719
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712

Not Auth John Poo 8/200/1- Lsm

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

dy

Acknowledged by Repairer

Signature:

Date:

1.1. 62562581