

NEW HOCK TECK MOTOR PTE LTD

Our Ref : GBC8512Y
Your Ref : SLL2494P
Date : 26/7/2019

1 Kaki Bukit Ave 6
Blk C @ Autobay, #01-43
Singapore 417883
Tel : (65) 6747 9241
Fax : (65) 6741 7276

FWD SINGAPORE PTE LTD

BY EMAIL

motorclaims.sg@fwd.com

Attn : Motor Claims Department

Dear Sirs,

DATE OF ACCIDENT : **25 JUL 2019 @ 18:15 hours**

**NOTICE OF INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES**

We act for **SALLEH EXPRESS** who has appointed the undermentioned workshop
to repair motor vehicle no. **GBC8512Y**

Please be informed that the said vehicle can be inspected at :

**NEW HOCK TECK MOTOR PTE LTD
1 KAKI BUKIT AVE 6
#01-43 BLK C @ AUTOBAY
SINGAPORE 417883**

Contact Person : Office @ 6747 9241 (Reena / Sukyi)

If you failed to conduct the pre-repair inspection within the next 2 working days excluding
any intervening Saturday, Sunday or Public Holiday. The said workshop will commence
repairs thereafter without further reference to you.

Yours Faithfully



New Hock Teck Motor Pte Ltd

For Surveyor.

Please initial here after completion of
Pre-repair inspection. Thank you

Surveyor Name :
& signature

Date&Time :