

ASS. REC. BY:

REF: CS/CT19013294/99f3n2 Special Instruction:

Surveyor: GA

ASSIGNMENT (Office)

From (Person): Chong Boon sen of CTIDate/Time: 29/7/19 @ 3:20 pm

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDW 8802GInsured: SMK 7378Cat Workshop in/s Trans EurokarsTel: 9127 7928of S ubi closePolicy No: hmpcsn 30299119000Claim No: SNM19D203454 cov

Sum Insured: _____

Excess: _____

Make of Veh:
(Client's Record)

D.O.A.

2/7/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 4:20pm @ 29/7/19 Person Contacted: RonaldVehicle- IN OUT

Date/Time	Action/Instruction	Volunt? <input checked="" type="checkbox"/>
	SDW 8802G	CS/FCI15011377/Kgy3d1 DOA = 4/7/15
	SMK 7378C	X

ASS. REC. BY:

GR.

REF:

CTI

ASSIGNMENT

From:

Date:

1/8/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMK 7378C

at Workshop m/s

Trans Eurokars

of

Subi Close

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

2pm

Ronald 9127 7928

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SDW 8802 G

Yr Regn:

27 Jul 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 6

C.C

1998

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

111393

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6GJ1072G 0209649

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

225/55 R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

01-08-19

Survey held at

w/s

2:30 pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Finalized \$ 3082.72 with Catherine.
(Ref # 6018.61, 66%)

RECEIVED 13 SEP 2019

Date/Time, File Pass to?



: Preli. Report

1/13/19 10:15 AM



: Final Report

Date/Time, File Return to?

3

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: West end (\$)

Survey Fee:

Transportation:

S + PS: \$

P/loss

Others

TOTAL

220

Report Format:

web-tp

Lump Sum / L.B.R (%)

3082.72

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 29 July 2019 3:20 PM
To: ronald.yap@eurokars.com.sg
Cc: assignments
Subject: RE: OUR REF: SNM19D203454 - SMK7378C - CBS - FW: ARRANGE FOR SURVEY /
YOUR REF: SMK7378C / OUR REF: SDW8802G

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: ronald.yap@eurokars.com.sg [mailto:ronald.yap@eurokars.com.sg]
Sent: Monday, 29 July, 2019 3:18 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D203454 - SMK7378C - CBS - FW: ARRANGE FOR SURVEY / YOUR REF: SMK7378C /
OUR REF: SDW8802G

Hi Boon Sen

Please assign to Marcus Chua.

Thank you

Ronald Yap
Insurance Claims
9127 7928

Sent from my Smartphone.

----- Original message -----

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Date: 7/29/19 15:15 (GMT+08:00)
To: Ronald Yap <ronald.yap@eurokars.com.sg>
Subject: RE: OUR REF: SNM19D203454 - SMK7378C - CBS - FW: ARRANGE FOR SURVEY / YOUR REF: SMK7378C / OUR REF: SDW8802G

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.
You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Monday, 29 July, 2019 2:58 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; ronald.yap@eurokars.com.sg

Subject: OUR REF: SNM19D203454 - SMK7378C - CBS - FW: ARRANGE FOR SURVEY / YOUR REF: SMK7378C / OUR REF: SDW8802G

Dear Boon Sen,

Please conduct PRS for SDW8802G.

Note : Officer in charge – Boon Sen 63896171.

Thanks,
shumin

From: ronald.yap@eurokars.com.sg [mailto:ronald.yap@eurokars.com.sg]
Sent: Friday, 26 July, 2019 7:23 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: jess.francis@eurokars.com.sg; samuel.ng@eurokars.com.sg; tommywoon@eurokars.com.sg
Subject: ARRANGE FOR SURVEY / YOUR REF: SMK7378C / OUR REF: SDW8802G

Dear Claims,

As attached / subject, let us have your appointed surveyor for the arrangements.

Thank You,

Ronald Yap
Insurance Claims

Trans Eurokars Pte Ltd
5 Ubi Close, Singapore 408605
T: 6395 8899 H: 9127 7928
ronald.yap@eurokars.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacanon@mazda.com.sg <transeurokars@eurokars.com.sg>
Sent: 26 July 2019 19:42
To: Ronald Yap <ronald.yap@eurokars.com.sg>
Subject: Attached Image

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-118974

Date of Request: 23/07/2019

Your Ref No: Online Purchase

Trans Eurokars Pte Ltd
12 Sungei Kadut Ave
Singapore 729648

Dear Sir/Madam,

Enquiry Date 23/07/2019

Enquiry By Ronald Yap

TP Vehicle No. SMK7378C

Accident Date 22/07/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SMK7378C	China Taiping Insurance (Singapore) Pte. Ltd.	23/04/2019-22/04/2020	6389 6111

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-118974

Date of Request: 23/07/2019

Your Ref No: Online Purchase

Trans Eurokars Pte Ltd
12 Sungei Kadut Ave
Singapore 729648

Dear Sir/Madam,

Enquiry Date 23/07/2019
Enquiry By Ronald Yap
TP Vehicle No. SMK7378C
Accident Date 22/07/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	522I
Vehicle Details	
Vehicle No.:	SDW8802G
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Aug 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	PE20659383
Chassis No.:	JM6GJ1072G0209649
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$19,187.00
Original Registration Date:	27 Jul 2015
First Registration Date:	27 Jul 2015
Transfer Count:	0
Actual ARF Paid:	\$19,187.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jul 2025
PARF Rebate Amount:	\$14,390.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jul 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$65,501.00
COE Rebate Amount:	\$39,177.00
Total Rebate Amount:	\$53,567.00

The information contained herein is correct as at 02 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/07/2019 15:52
Date Of Accident	22/07/2019 14:50
Exact Location Of Accident	CASHEW ROAD TURNING OUT INTO UPP BT TIMAH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDW8802G
Insured/Policyholder	
Name Of Registered Owner	MR TAN TAU CHIN VINCENT
NRIC No	S7110522I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93698802
Alternative Phone No	OFFICE-93698802

Vehicle Particulars

Manufacturer	MAZDA
Model	6-2.0 4-DOOR SEDAN (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	MICHIKO NAOMI TAN ABIGAIL
NRIC No	S9623858D
Date Of Birth	04/07/1996
Occupation	INDOOR
Date Of Driving Pass	29/01/2016
Driving Experience	3 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90662882
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 561 CHOA CHU KANG NORTH 6 #08-82
Postcode	680561
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : AKIKO JACQUELINE GENDER: : FEMALE
Passenger 2	NAME: : AQUILA MICHIRYU GENDER: : MALE
Passenger 3	NAME: : APOLLOS MICHIO GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMK7378C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.


Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

OWN VEHICLE NUMBER (A): SDW 8802 G

OTHER VEHICLE/S NUMBER (B): SMK 7378 C



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT (Between Cashew MRT and Assumption English School)

LOCATION OF ACCIDENT: Cashew Road turning out into Upper Bukit Timah Road

DATE OF ACCIDENT: 22/7/19

TIME OF ACCIDENT: 14 50 - 1500

PASSENGER/S NAME AND GENDER (IF ANY): AKIKO Jacqueline, Female; Aquila Michinyu, Male;

DESCRIPTION OF WHAT HAPPENED: Apollis Michio, Male

I was driving along Cashew Road and slowed down as I approached the sliproad leading to Upper Bukit Timah Road. The main road's traffic light was still green and I saw cars approaching along the main road so I came to a stop and waited.

Around 2-4 seconds later, I felt a jerk originating from the back of the car and I realised a car from behind had knocked into our car. Right after, the driver of that car behind (SMK 7378 C) immediately reversed before my mum (AKIKO Jacqueline) and I got the chance to alight and see the bump.

ACCIDENT VIDEO CAPTURED?: YES / NO

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 23/7/19
14:15

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Tan Tau Chin Vincent ADDRESS : Blk 561 Choa Chu Kang North 6 #08-82 Singapore 680561 TEL : 93698802		WIP : 58362 EXCESS : DATE: 23-Jul-19	
VEH NO :	SDW8802G	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6GJ1072G0209649	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA6	DATE REG.:	27-Jul-15	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER / <i>Re</i>	1	MGJR9-50-221ABB		\$ 1,231.50 ✓
2	BRACKET CENTER <i>X NN</i>	1	MKD53-50-251		\$ 5.40 X
3	TOWING COVER LHS <i>X Mis</i>	1	MG4YL-50-EL1 64		\$ 24.90 ✓
4	TOWING COVER RHS <i>X NN</i>	1	MG4YL-50-EK1 64		\$ 24.90 X
5	REAR REINFORCEMENT <i>X NN</i>	1	MGHK1-50-260		\$ 538.30 X
6	GROMMET, REAR BUMPER <i>/</i>	6	MH260-50-841		\$ 18.00 ✓
7	GROMMET, REAR BUMPER <i>/</i>	2	M9991-00-501		\$ 6.00 ✓
8	FASTENER, REAR BUMPER <i>/</i>	6	MB45A-56-146A		\$ 18.00 ✓
9	CLIP, REAR BUMPER <i>/</i>	4	MC274-50-133		\$ 14.80 ✓
10	GROMMET, REAR BUMPER <i>/</i>	2	MGA7B-51-146		\$ 6.60 ✓
11	GASKET LHS, BOOTLID <i>X</i>	1	MG45F-51-3J8		\$ 52.50 X
12	GASKET RHS, BOOTLID <i>X NN</i>	1	MG45F-51-3H8A		\$ 52.50 X
13	GASKET LHS, TAILLAMP <i>/</i>	1	MGJA1-51-163		\$ 27.70 ✓
14	GASKET RHS, TAILLAMP <i>/</i>	1	MGJA1-51-153		\$ 27.70 ✓
15	CLIP, FINISHER <i>/</i>	2	MB25F-50-714		\$ 5.60 ✓
16	ORNAMENT, MAZDA <i>X</i>	1	MGHK1-51-711		\$ 28.90 X
17	ORNAMENT, 6 <i>X</i>	1	MGHK1-51-721		\$ 16.50 X
18	MASCOT, REAR <i>X</i>	1	MGHK1-51-730		\$ 49.20 X
19	ORNAMENT, SKYACTIVE <i>X</i>	1	MGHK1-51-771		\$ 74.70 X
TOTAL PARTS					\$ 2,223.70
LESS 10%					\$ 222.37
TOTAL PARTS COST					\$ 2,001.33
Labour Description					
1	MZ-BR-REAR03	TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND BOOT LID. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.			<i>660</i> \$ 2,640.00

2	MZ-SP-SREARS	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID.	630	\$ 2,520.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)	200	NETT \$ 660.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	NN {	\$ 330.00
5	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
6	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
7	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
8		TO SUPPLY BODY COATING.	NN X	NETT TBA
9	MZ-BR-SUNDRI	SUNDRIES.	20	NETT \$ 100.00

TOTAL LABOUR	\$ -	\$ 7,100.00
TOTAL PARTS	\$ -	\$ 2,001.33
TOTAL	\$ -	\$ 9,101.33
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

2/8/19 *3 Days.*
before paint photos.
Eric Qian - 82880282
01/8/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

CHINA TAIPING INSURANCE P/L		NAME : Mr Tan Tau Chin Vincent		WIP : 58362	
3 ANSON ROAD		ADDRESS : Blk 561 Choa Chu Kang North 6		EXCESS :	
#16-00 SPRINGLEAF TOWER		#08-82		DATE: 23-Jul-19	
SINGAPORE 079909		Singapore 680561			
ATTN. : MOTOR CLAIMS		TEL : 93698802			
FAX :					
VEH NO :	SDW8802G	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6GJ1072G0209649	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA6	DATE REG.:	27-Jul-15	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MGJR9-50-221ABB	\$ 1,231.50	\$ 1,231.50
2	BRACKET CENTER	1	MKD53-50-251		\$ 5.40
3	TOWING COVER LHS	1	MG4YL-50-EL1 64	\$ 24.90	\$ 24.90
4	TOWING COVER RHS	1	MG4YL-50-EK1 64		\$ 24.90
5	REAR REINFORCEMENT	1	MGHK1-50-260		\$ 538.30
6	GROMMET, REAR BUMPER	6	MH260-50-841	\$ 18.00	\$ 18.00
7	GROMMET, REAR BUMPER	2	M9991-00-501	\$ 6.00	\$ 6.00
8	FASTENER, REAR BUMPER	6	MB45A-56-146A	\$ 18.00	\$ 18.00
9	CLIP, REAR BUMPER	4	MC274-50-133	\$ 14.80	\$ 14.80
10	GROMMET, REAR BUMPER	2	MGA7B-51-146	\$ 6.60	\$ 6.60
11	GASKET LHS, BOOTLID	1	MG45F-51-3J8		\$ 52.50
12	GASKET RHS, BOOTLID	1	MG45F-51-3H8A		\$ 52.50
13	GASKET LHS, TAILLAMP	1	MGJA1-51-163	\$ 27.70	\$ 27.70
14	GASKET RHS, TAILLAMP	1	MGJA1-51-153	\$ 27.70	\$ 27.70
15	CLIP, FINISHER	2	MB25F-50-714	\$ 5.60	\$ 5.60
16	ORNAMENT, MAZDA	1	MGHK1-51-711		\$ 28.90
17	ORNAMENT, 6	1	MGHK1-51-721		\$ 16.50
18	MASCOT, REAR	1	MGHK1-51-730		\$ 49.20
19	ORNAMENT, SKYACTIVE	1	MGHK1-51-771		\$ 74.70
TOTAL PARTS				\$ 1,380.80	\$ 2,223.70
LESS 10%				\$ 138.08	\$ 222.37
TOTAL PARTS COST				\$ 1,242.72	\$ 2,001.33
Labour Description					
1	MZ-BR-REAR03	TO REPLACE REAR BUMPER. TO REPAIR AREAS AFFECTED BY THE ACCIDENT.		\$ 660.00	\$ 2,640.00
2	MZ-SP-SREAR1	TO RESPRAY REAR BUMPER.		\$ 630.00	\$ 2,520.00

3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)	\$ 200.00	\$ 660.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.		\$ 330.00
5	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
6	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
7	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
8		TO SUPPLY BODY COATING.		TBA
9	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
TOTAL LABOUR			\$ 1,840.00	\$ 7,100.00
TOTAL PARTS			\$ 1,242.72	\$ 2,001.33
TOTAL			\$ 3,082.72	\$ 9,101.33
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ 3,082.72	
GST 7%			\$ 215.79	\$ -
GRAND TOTAL			\$ 3,298.51	\$ -

REMARKS:

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119013294/GQF3N2

Date: 16/09/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30299119000
Claimant Vehicle No :	SDW8802G	Insured Vehicle No :	SMK7378C
Date of Loss:	22/07/2019	Nature of Claim:	TP
		Claim No:	SNM19D203454C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDW8802G	Engine No:	PE20659383
Make & Model:	MAZDA 6, 2.0 4-DOOR SEDAN (A)	Chassis No:	JM6GJ1072G0209649
Reg. Date:	27/07/2015 (Man. Year: 2015)	Odometer:	111393 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,101.33	1,262.72	838.61	39.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,000.00	1,820.00	5,180.00	74.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	9,101.33	3,082.72	6,018.61	66.13
+ GST 7.00/7.00% (\$\$)	637.09	215.79	421.30	66.13
Nett Amount (\$\$)	9,738.42	3,298.51	6,439.91	66.13

INSPECTION

Date of Assignment:	13/09/2019	
Date Inspected:	01/08/2019	Inspected At:
		No 5 Ubi Close
		Singapore 408605
		Repairer: Trans Eurokars Pte Ltd
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Sep 2019)
Parts: 143	MAZDA 6 2.0 4-DOOR SEDAN (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDW8802G)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,231.50 FL	*1,231.50 FL
2	1		*BRACKET CENTER	Not Necessary	5.40 FL	*- FL
3	1		*TOWING COVER LHS	Missing	24.90 FL	*24.90 FL
4	1		*TOWING COVER RHS	Not Necessary	24.90 FL	*- FL
5	1		*REAR REINFORCEMENT	Not Necessary	538.30 FL	*- FL
6	6		*GROMMET,REAR BUMPER	Necessary	18.00 FL	*18.00 FL
7	2		*GROMMET,REAR BUMPER	Necessary	6.00 FL	*6.00 FL
8	6		*FASTENER,REAR BUMPER	Necessary	18.00 FL	*18.00 FL
9	4		*CLIP,REAR BUMPER	Necessary	14.80 FL	*14.80 FL
10	2		*GROMMET,REAR BUMPER	Necessary	6.60 FL	*6.60 FL
11	1		*GASKET LHS,BOOTLID	Not Necessary	52.50 FL	*- FL
12	1		*GASKET RHS,BOOTLID	Not Necessary	52.50 FL	*- FL
13	1		*GASKET LHS,TAILLAMP	Necessary	27.70 FL	*27.70 FL
14	2		*CLIP,FINISHER	Necessary	5.60 FL	*5.60 FL
15	1		*ORNAMENT,MAZDA	Not Necessary	28.90 FL	*- FL
16	1		*ORNAMENT,6	Not Necessary	16.50 FL	*- FL
17	1		*MASCOT,REAR	Not Necessary	49.20 FL	*- FL
18	1		*ORNAMENT,SKYACTIVE	Not Necessary	74.70 FL	*- FL
19	1		*GASKET RHS,TAILLAMP	Necessary	27.70 FL	*27.70 FL
20	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpocNett. L=ListItemDisc.

Sub Total (\$\$)	2,323.70	1,400.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	222.37	138.08
Total Parts (\$\$)	2,101.33	1,262.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER,REAR REINFORCEMENT AND BOOT LID.TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT	New	2,640.00	660.00
2	TO RESPRAY REAR BUMPER,REAR REINFORCEMENT,REAR END PANEL AND BOOT LID	New	2,520.00	630.00
3	TO TRANSFER REVERSE SENSORS.(WITH REVERSE SENSOR)	New	660.00	200.00
4	TO TRANSFER REVERSE CAMERA	New	330.00	0.00
5	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	0.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
8	TO SUPPLY BODY COATING (NPA)	New	0.00	0.00
Gross Labour Cost (\$\$)			7,000.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >