



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC19007937/R1td3s2-1

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 15-08-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 3471Z	Veh. Inspected	SJL 6711K
Policy No.	Z/19/VC00/103239	Coverage (\$)	0.00
Claim No.	19/19/19/VC00/021753	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	30/07/2019

2. Vehicle Particulars & Condition

Make & Model	KIA RIO 1.4 AT	c.c	1399
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	KNADE241396479965	Colour	RED
Odometer	96962	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/50 R15	HANKOOK	5 mm
L/H Front Tyre	195/50 R15	HANKOOK	5 mm
R/H Rear Tyre	195/50 R15	HANKOOK	5 mm
L/H Rear Tyre	195/50 R15	HANKOOK	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/05/2019	Inspection Date	13/05/2019
Survey held at	WAH YU AUTOMOTIVE BODY WORK 176 SIN MING DRIVE #05-09 SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**