

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom Vehicle
Inspection Centre (575718)

Insurer Reference: SLU8911R
Repairer Reference: 011930
Date calculated: 04/10/2019 3:44 PM

Full Report
Registration: SLS7534M
Printed: 04/10/2019 3:44 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AIG Asia Pacific Insurance Pte Ltd
Printed by:	Carmen SG	Currency:	SGD
Claim Reference:	SLU8911R	Date of Incident:	27/07/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	PRIUS IV
Sub Model:	BASE MODEL
Model Sheet Number:	70 P5 01
Registration:	SLS7534M
VIN number:	
Odometer:	

Model Specs

TWO COAT METALLIC


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
B410	R + R REAR BUMPER		5.0	25.00
NO NUMBER	R + R REAR BUMPER COVER		1.0	5.00
NO NUMBER	R + R REAR BUMPER COVERING CAP		1.0	5.00
NO NUMBER	R + R RIGHT REAR BUMPER CORNER		1.0	5.00
1001	R&R REVERSE SENSOR REMOVE&REFIT			
2583	REAR BUMPER REPAIR		20.0*	100.00
Labour Cost			Hrs	WU
Panel / Mechanical Labour			2.80	28.0
Total of Labour				140.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	REAR BUMPER REPAIR PAINT PLASTIC		15.0	

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER REPAIR PAINT PLASTIC	45.36

Labour Cost - Paint		Hrs	WU	Price SGD
Factor		50.00 SGD/h		
Time Paint			15.0	
Preparation Comp. Work Plastic		2.10	21.0	105.00
Total		3.60	36.0	180.00

Material Cost - Paint		Price SGD
Repair Painting Plastic		45.36
Material-constant Plastic		18.10
Total		63.46

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	
				Price SGD	
2622	RIGHT RETAINER	90467 09237			0.00
2636	R/R BUMPER CORNER	52565 47900			0.00
1000	REAR BUMP CLIP	REAR BUMP CLIP			0.00
f: OEM Parts		Savings			0.00
n: Non-OEM Parts		Subtotal			
u: Used parts					

Total 0.00

Final Calculation

	SGD	SGD
Labour Time Base 10 WU/h		
Total 28.0 WU X 50.00 SGD/h	140.00	140.00
Total of Labour		
Paint Work Time Base 10 WU/h		
Labour Cost 36.0 WU X 50.00 SGD/h	180.00	
Material Cost	63.46	243.46
Total Paint Including Material		
		383.46
Repair Cost Excludes GST		26.84
GST (+7.0%)		410.30
Repair Cost Included GST		

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.