



潘發展私人有限公司
A. S. PHOON PTE LTD
'cos no one else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FBE2254X YAMAHA T135 REPAIR ESTIMATE (10JULY 2019)

ITEM	DESCRIPTION	AMOUNT SGD
1	REAR FENDER	\$58.00
2	REAR EXHAUST	\$390.00
3	GASKET X1	\$6.00
4	HEAT PROTECTION	\$48.00
5	REAR LICENCE PLATE	\$15.00
6	REAR TOP BOX	\$250.00
7	REAR TOP BOX BRACKET	\$80.00
8	REAR FOOTREST BRACKET RH	\$75.00
9	REAR ARM	\$120.00
10	ARM BUSH X2	\$40.00
11	FRONT SIDE FAIRING RH	\$80.00
12	BACK SHIELD	\$120.00
13	HORN COVER	\$85.00
14	HANDLEBAR COVER.FRONT	\$58.00
15	HANDLEBAR COVER.REAR	\$45.00
16	FRONT FENDER	\$68.00
17	FRONT FORK ASSY RH & LH @ \$180	\$360.00
18	STEM.STEERING	\$145.00
19	CONE BEARING SET	\$60.00
20	FRONT WHEEL AXLE	\$22.00
21	RADIATOR	\$206.00
22	COOLANT	\$20.00
23	BASKET	\$25.00
24	HANDLE BAR	\$68.00
25	MIRROR	\$50.00
26	HANDLE GRIP	\$25.00
27	FRONT FOOTREST BAR	\$68.00
28	FRONT FOOTREST RUBBER	\$16.00
29	CLUTCH LEVER	\$15.00
30	WORKMANSHIP	\$350.00
31	TRANSPORTAION TP-IDAC-BIKESHOP @\$50	\$100.00
32	BODY CHASSIS REPAIR	\$350.00
33	TRANSPORT 2 WAY TO REPAIR CHASSIS	\$100.00
TOTAL		\$3,518.00