

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40
WCEGA PLAZA SINGAPORE 658064

ATTN: AXA INSURANCE

DATE: 31/07/2019
VEHICLE NO: SFM4981C
MODEL: TOYOTA CAMRY
YEAR: 2010
ACCIDENT DATE: 30/07/2019
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
BONNET	1	\$956.40 <i>Rx</i>
FRONT GRILLE	1	\$329.10 <i>?</i>
FRONT EMBLEM	1	\$65.30 <i>?</i>
FRONT BUMPER	1	\$779.60 <i>de</i>
FRONT BUMPER RETAINER	2	<i>@ 50.7</i> \$101.40 <i>LH-de, RHX</i>
FRONT BUMPER BRACKET	2	<i>@ 77.9</i> \$155.80 <i>LH-nw-, RHX</i>
FRONT BUMPER CENTRE LOWER GRILLE	1	\$196.40 <i>?</i>
FRONT BUMPER SPONGE	1	\$165.70 <i>?</i>
FRONT REINFORCEMENT	1	\$395.20 <i>?</i>
SUPPORT PANEL		
FRONT NUMBER PLATE GARNISH	1	\$178.40 <i>de-</i>
HEADLAMP	1	\$1,032.20 <i>ona-</i>
LH FOGLAMP	1	\$387.50 <i>X</i>
LH FOGLAMP COVER	1	\$178.40 <i>?</i>
LH FOGLAMP CHROME LINING	1	\$167.40 <i>?</i>
LH FRONT FENDER	1	\$497.40 <i>Rx</i>
LH FRONT FENDER INNER PANEL	1	RESTORE

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: AXA INSURANCE

DATE: 31/07/2019
VEHICLE NO: **SFM4981C**
MODEL: TOYOTA CAMRY
YEAR: 2010
ACCIDENT DATE: 30/07/2019
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

LH FRONT FENDER INNER SHIELD	1	\$197.80 X
LH FRONT FENDER LOGO	1	\$55.60 <i>new</i>
LH FRONT DOOR	1	RESTORE
		TOTAL: \$5,839.60
		DISCOUNT 25%: <u>\$1,459.90</u>
		<u>\$4,379.70</u>

S/NET

FRONT NUMBER PLATE	1	\$100.00 ?
FRONT BUMPER CLIPS	10	\$30.00 <i>new</i>
FRONT GRILLE CLIPS	10	\$30.00 ?
RH FRONT FENDER INNER SHIELD CLIPS	10	\$30.00 X
		TOTAL: <u>\$190.00</u>

LABOUR

PRICE

LABOUR FOR FACILITATE REPAIR	\$1,200.00	<i>500.</i>
TO RESPRAY AFFECTED AREAS - BONNET	\$300.00	<i>200</i>
TO RESPRAY AFFECTED AREAS - FRONT BUMPER	\$300.00	<i>200</i>
TO RESPRAY AFFECTED AREAS - LH FRONT FENDER AND INNER PANEL	\$300.00	<i>200</i>
TO RESPRAY AFFECTED AREAS - LH FRONT DOOR	\$300.00	X

AUTOWHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT #02-40

WCEGA PLAZA SINGAPORE 658064

ATTN: AXA INSURANCE

DATE: 31/07/2019
VEHICLE NO: SFM4981C
MODEL: TOYOTA CAMRY
YEAR: 2010
ACCIDENT DATE: 30/07/2019
TYPE OF CLAIM: TP
CLAIM ADVISOR: LOUIS (91928963)
EMAIL: louisongautowheels@yahoo.com

ESTIMATION

TO RESPRAY AFFECTED AREAS - SUPPORT PANEL	\$250.00	X
TO CHECK AND RECONNECT ALL NECESSARY WIRING	\$100.00	30
SUNDARIES	\$80.00	20
RUST PROOFING	\$100.00	30
TOTAL:	\$2,930.00	

TOTAL:	\$7,499.70
7% GST:	\$524.98
	\$8,024.68

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
WP'

6/8/19 R 1045

Lumpsum
Resurvey after repair

4 days.

sure lkkauto.com