

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0930/2019/NS
Date : 01-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR ONG PENG SIN
Address : Blk 527C Pasir Ris Street 51
#13-715
Singapore 513527
Telephone : HP +65 97375132
Type of Claim : Own Damage Claims
Policy No. : 2100491907-02
Vehicle No : **SLJ 905 U**
Model Code : A4 Sedan 1.4 TFSI S
Model / Year : Nov-16
Engine No : CVN 021223
Chassis No : WAUZZZF45HA052092
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Jul-19
Place of Accident : ENTERING CTE BEFORE CEMENCEAU EXIT

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLJ 905 U

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$360.00 /	
2	To remove and transfer rhs front door and rhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 560.00 280	
3	To dismantle rear bumper, rhs front door and rhs rear door. To repair rhs rear fender. To renew rhs wing mirror assy, rhs front door and rhs rear door. Re-organise crash management components. Reinstall all parts removed.	\$ 3,500.00 1750	
4	To respray rear bumper, rhs rear fender, rhs rear door, rhs front door, rhs wing mirror cover, door handle, rhs front fender and rhs upper a-pillar.	\$ 5,700.00 2475	
5	To install solar film for rhs front door glass	S/N \$ 400.00 X	
6	To carry out diagnostic check.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: <u>\$10,712.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 905 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT DOOR - RH <i>bt</i>	\$	2,152.00
2	OUTER DOOR SEAL - RH <i>re</i>	NEC \$	185.00
3	BONDING AGENT <i>re</i>	NEC \$	45.00
4	CLEANING SOLUTION <i>re</i>	NEC \$	65.00
5	DOOR ATTACHMENT PARTS <i>?</i>	\$	488.00
6	DOOR CATCH <i>X</i>	\$	96.00
7	TYRE PRESSURE DATA PLATE <i>re</i>	NEC \$	35.00
8	EXTERIOR MIRROR MOUNTING - RH <i>re</i>	\$	824.00
9	MIRROR CAP - RH <i>re</i>	\$	220.00
10	MIRROR GLASS WITH PLATE - RH <i>?</i>	\$	1,553.00
11	CORNER TRIM - RH <i>re</i>	\$	41.00
12	WINDOW GUIDE TRIM STRIP - RH <i>X</i>	\$	235.00
13	WINDOW SLOT SEAL WITH TRIM STRIP <i>X</i>	\$	280.00
14	FRONT DOOR WINDOW - RH <i>X</i>	\$	265.00
15	REAR DOOR - RH <i>repair</i>	\$	2,152.00
16	OUTER DOOR SEAL - RH <i>X</i>	NEC \$	185.00
17	BONDING AGENT <i>X</i>	NEC \$	45.00
18	CLEANING SOLUTION <i>X</i>	NEC \$	65.00
19	DOOR ATTACHMENTG PARTS <i>X</i>	\$	515.00
20	DOOR CATCH <i>X</i>	\$	109.00
21	STONE CHIP <i>X</i>	S/N \$	180.00
22	SUNDRIES <i>?</i>	\$	300.00
TOTAL SPARE PARTS CHARGES		:	\$ 10,035.00
TOTAL LABOUR CHARGES			\$ 10,712.00
GRAND TOTAL			<u>\$ 20,747.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: RASUL - 4p 900 100 60

: 8 days

: 01/08/19 @ 1340

: Reay before print
EXCESS: TBC
REVERT

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant