

INSURANCE

INS. CASE OWNER:

CC 4/1111901 2462, U ph 9

LKK

IDAC

Surveyor:

MARCUS

DOI:

ASSIGNMENT

2/8/19

Date / Time:

2/8/19

Registered in Merimen:

2/8/19

Pre-assign / CCU / FTE



Insured Vehicle No. : SHC 17050

Name of Insured : LTR

Insured Tel No. : HP:

Excess Sec II : S\$ D.O.A. : 1/8/19

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : MEHA BOOB Hussain

Driver Tel No. : (V/L: YES / NO)

Claim No. : MCT19080002

Policy No. : MUW0015

Make / Model : HYUNDAI

Place of Accident : DURING TURN WITH RED CROSS

DURING FIRST TURN

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SMA 91690



INSRS:
WSP:
Tel:
Liability:
RMKS:

Kah motor



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

URGENT

Date/ Time

SMA 91690 - X

STAGE

DATE / PIC

Non-Reporting 1st (1st)

Non-Reporting 1st (2nd)

Non-Reporting 1st (Final)

Notification 1st (if non-pickup)

Call OI

After call 1st to OI

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA

Medical Bill

PIR

Mandate/Reject Instruction

LOI

Payment Breakdown Form

Post-Repair Photos

Others

8/8/19 - TP turned with green arrow.

14/8/19 - File -> Marcus to finalise

28/8/19 - File -> type minutes

27/11/19 - File -> close

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Agreed) BOLA S/N No. : NIL

If NO or B 28, Ass. Lia :

Repair Cost:

S\$

17339.07

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

8W-W (5 x 16 days)

Loss of Income (LOI):

S\$

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost:

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

18139.07

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

18139.07

Name 1:

Kah Motor Co. Sdn. Bhd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASS. REC. BY: Marcus

REF: 1111

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SMA 9169D
at Workshop m/s Koh
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SMA 9169D Yr Regn: 6.18
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: Honda Jazz C.O. 1318
Colour: Red A/C: Insured / Std / NI / NA
Sp. Reading: 22447 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JHMAK 380JX 22287
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175 / 65-215
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal.	<u>0</u> mm	R/Bal.	<u>0</u> mm
L/Bal.	<u>0</u> mm	L/Bal.	<u>0</u> mm
D.O.A.	<u>1/8/19</u>	D.O.I.	<u>2/8/19</u>

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rt n/s &
The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)



Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 60
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 14 days Res.: Yes or No
Lum Sum: 151 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: LTA 28345 Vehicle: IN / OUT

Date / Time Action / Instruction

have v. des of folder net 21655
new car 72k agree Not more than 21k.

26/8/19 confirm final by 16204.74 with Any.
(Red \$ 8231.24/340)

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1)

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____) ☐ : S + RS \$ _____
☐ : Interview (\$ _____) ☐ : Photos
☐ : Tech. Invs (\$ _____) ☐ : Others
☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ _____)

TOTAL



QUOTATION

KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
 64 CECIL STREET
 #04-00 & #05-00 IOB BUILDING
 SINGAPORE 049711
 Registration No : SMA9169D
 Chassis No : JHMGK3850JX222851
 Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
 Owner's Name : CHEN WEE KEONG
 Ins Policy No. :
 Date of Accident : 1/8/2019

Document No. : SQT19003373 Page 2
 Date : 1. Aug 2019
 Customer No. : WZI007
 Svc Advisor : ARY CHUA WAI NGEE
 Engine No : L13B11030797
 Date | Time : 1. Aug 2019 8:48:33 AM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
74120-T5A-J01	LOCK ASSYHOOD	su 1	42.60	X 25	31.95	2.24	34.19
74141-T5B-000	INSULATORHOOD	11 1	87.70	X 25	65.77	4.60	70.37
74147-T5A-000	GARNISH ASSYHOOD	11 1	41.40	X 25	31.05	2.17	33.22
74198-T5A-000	GARNISH ASSYL HOOD	11 1	14.50	X 25	10.87	0.76	11.63
80100-T5B-003	CONDENSER ASSY	121 1	704.40	/ 25	528.30	36.98	565.28
80311-T5A-003	HOSE COMPSUCTION	11 1	124.00	X 25	93.00	6.51	99.51
80315-T5B-003	HOSE COMPDISCHARGE	11 1	144.80	X 25	108.60	7.60	116.20
80341-T5A-003	PIPE COMPRECEIVER	11 1	111.90	X 25	83.92	5.87	89.79
19010-5R1-901	RADIATOR COMP	Sub/sum 1	1211.20	/ 25	908.40	63.59	971.99
19015-5R1-003	SHROUD COMP	11 1	89.30	X 25	66.97	4.69	71.66
19020-5R1-003	FANCOOLING	11 1	26.30	X 25	19.72	1.38	21.10
38611-5R1-003	FANCOOLING	11 1	49.20	X 25	36.90	2.58	39.48
38615-5R1-003	SHROUD COMP	11 1	46.30	X 25	34.72	2.43	37.15
33100-T5A-J81	HEADLIGHT ASSY,R.	11 1	479.70	X 25	359.77	25.18	384.95
33150-T5A-J81	HEADLIGHT ASSY,L.	110 1	479.70	/ 25	359.77	25.18	384.95
17249-5R0-J00	SEPARATOR,SPLASH INTAKE	11 1	31.00	X 25	23.25	1.63	24.88
17252-5V5-M00	DUCT ASSY,AIR INTAKE	11 1	21.60	X 25	16.20	1.13	17.33
17230-5R0-J01	CHAMBER ASSYRESONATOR	112 1	89.50	/ 25	67.12	4.70	71.82
17234-5R0-000	TUBERESONATOR CHAMBER	112 1	28.50	/ 25	21.37	1.50	22.87
50850-T9A-003	RUBBER ASSYTRANSMISSION MTG	112 1	111.40	/ 25	83.55	5.85	89.40
74111-T5A-900	COVER,ENG UNDER	11 1	86.00	X 25	64.50	4.52	69.02
74150-T5L-T10	FENDER ASSY,L.FR.	113 1	69.20	/ 25	51.90	3.63	55.53
74165-T5A-010	GUARDL.FR.SPLASH	112 1	23.40	/ 25	17.55	1.23	18.78
91505-TM8-003	CLIP,BUMPER	112 14	2.30	X 25	24.15	1.69	25.84
77930-T5A-J01	SENSOR ASSYFR.CRASH	112 2	63.40	/ 25	95.10	6.66	101.76
77960-T5A-W41	UNIT ASSYSRS	112 1	822.80	/ 25	617.10	43.20	660.30
77100-T5A-J10ZA	PANEL COMPINSTRUMENT	112 1	732.80	/ 25	549.60	38.47	588.07
77820-T5A-J80	MODULE ASSYPASSENGER	112 1	2236.80	/ 25	1677.60	117.43	1795.03
77810-T5A-N81ZA	MODULE ASSYDRIVER	112 1	1640.30	/ 25	1230.22	86.12	1316.34

Printed on 1/8/2019 3:26:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SMA9169D

Chassis No : JHMGK3850JX222851

Model : JAZZ 1.3LXR CVT 18YM (EURO 5)

Owner's Name : CHEN WEE KEONG

Ins Policy No. :

Date of Accident : 1/8/2019

Document No. : SQT19003373 Page 3

Date : 1. Aug 2019

Customer No. : WZI007

Svc Advisor : ARY CHUA WAI NGEE

Engine No : L13B11030797

Date | Time : 1. Aug 2019 8:48:33 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
81450-TAR-U01ZA	TONGUE ASSY,FR.SEATBELT	1	454.80	25	341.10	23.88	364.98
81850-TAR-U01ZA	TONGUE ASSYL,FR.SEATBELT	1	454.80	25	341.10	23.88	364.98
71105-T5A-J50	COVER,FR.GRILLE	1	12.60	25	9.45	0.66	10.11
71121-T5A-J50	BASE,FR.GRILLE HOOK	1	227.40	25	170.55	11.94	182.49
71122-T5A-J50	MOLDING LOWER,FR.GRILLE	1	148.90	25	111.67	7.82	119.49
71123-T5A-J50	MOLDING UPPER,FR.GRILLE	1	124.10	25	93.07	6.51	99.58
71124-T5A-J50	STAY,FR.GRILLE	1	12.70	25	9.52	0.67	10.19
71125-T5C-J50	SCREEN,R.FR.GRILLE	1	8.10	25	6.07	0.42	6.49
71126-T5A-J50	EMBLEM BASE,FR.GRILLE	1	20.30	25	15.22	1.07	16.29
75700-T5A-000	EMBLEM H	1	15.00	25	11.25	0.79	12.04
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
04711-T5A-J50ZZ	FACE,FR.BUMPER	1	504.60	25	378.45	26.49	404.94
71102-T5L-T50	LOWER GRILLE ASSY,FR.	1	137.90	25	103.42	7.24	110.66
71108-T5A-J50	GARNISH,L.FR.BUMPER	1	29.00	25	21.75	1.52	23.27
71119-T5A-J50	GARNISH,L.FR.LOWER GRILLE	1	8.70	25	6.52	0.46	6.98
71130-T5A-J50ZZ	BEAM COMP,FR.BUMPER	1	213.00	25	159.75	11.18	170.93
71140-T5A-J50	BEAM UPPER,R.FR.BUMPER	1	27.70	25	20.77	1.45	22.22
71145-TAR-T50	BASE,FR.LICENCE PLATE	1	49.00	25	36.75	2.57	39.32
71190-T5A-J50	BEAM UPPER,L.FR.BUMPER	1	27.70	25	20.77	1.45	22.22
71193-T5A-000	SPACERR,FR.BUMPER	1	10.40	25	7.80	0.55	8.35
71198-T5A-000	SPACERL,FR.BUMPER	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIP,BUMPER	10	2.30	25	17.25	1.21	18.46
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	3	23.20	25	52.20	3.65	55.85
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
YH-175/65R15-S71A	YOKOHAMA TYRE	1	108.00		108.00	7.56	115.56
Sum Item					11667.08	816.72	12,483.80
BOSUN	SUNDRIES	1	60.00	20	48.00	4.20	64.20
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00

Printed on 1/8/2019 3:26:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SMA9169D
Chassis No : JHMGK3850JX222851
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : CHEN WEE KEONG
Ins Policy No. :
Date of Accident : 1/8/2019

Document No. : SQT19003373 **Page** 1
Date : 1. Aug 2019
Customer No. : WZ1007
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L13B11030797
Date | Time : 1. Aug 2019 8:48:33 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 73170) OWNER: CHEN WEE KEONG OWNER INSURER: MSIG INSURANCE PTE LTD ACC DATE: 01/08/2019@01.55AM A:T/J JURONG T/HALL RD(L/P22)>JURONG E AVE1 (L/P42) SURVEYED BY: REF NO: TP INSURER: INDIA INTERNATIONAL INS PTE LTD TP VEH: SHC1305D - HYUNDAI/I40/BLUE/TAXI						

BO-TOW-SW	TOWING SERVICE	1	50.00		50.00	3.50	53.50
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
Sum Ext. Service					230.00	16.10	246.10

42700-T5S-M72	WHEEL_DISK AL 15X7	1	418.40	25	313.80	21.97	335.77
42700-TAR-E91	DISK ALUMINIUM WHEEL, 16X6	1	772.30	25	579.22	40.55	619.77
60400-T5B-J00ZZ	BULKHEAD COMP,FR.	1	381.70	25	286.27	20.04	306.31
60261-T5R-A00ZZ	PANELL.FR.FENDER	1	398.60	25	298.95	20.93	319.88
60690-T5A-300ZZ	BRACKET COMP,L.FR.FENDER	1	41.70	25	31.27	2.19	33.46
04684-T5A-300ZZ	EXTENSION SETL.FR.	1	94.40	25	70.80	4.96	75.76
60630-T5B-000ZZ	BASE COMP, BATTERY	1	68.70	25	51.52	3.61	55.13
60710-T5A-B00ZZ	MEMBER COMP,L.FR.WHEELHOUSE SET	1	59.00	25	44.25	3.10	47.35
60912-T5A-300ZZ	PLATEL.FR.BACK	1	107.50	25	80.62	5.64	86.26
60943-T5A-300ZZ	BRACKETL.FR.BUMPER BEAM	1	45.00	25	33.75	2.36	36.11
60944-T5A-300ZZ	PLATEL.SIDE FRAME	1	30.80	25	23.10	1.62	24.72
60945-T5A-300ZZ	GUSSETL.FR.SIDE	1	46.10	25	34.57	2.42	36.99
60100-T5A-000ZZ	HOOD COMP	1	537.50	25	403.12	28.22	431.34
60120-TAR-000ZZ	HINGE COMP,R.HOOD	1	25.70	25	19.27	1.35	20.62
60170-TAR-000ZZ	HINGE COMPL.HOOD	1	25.70	25	19.27	1.35	20.62

Printed on 1/8/2019 3:26:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SMA9169D

Chassis No : JHMGK3850JX222851

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : CHEN WEE KEONG

Ins Policy No. :

Date of Accident : 1/8/2019

Document No. : SQT19003373

Date : 1. Aug 2019

Customer No. : WZI007

Svc Advisor : ARY CHUA WAI NGEE

Engine No : L13B11030797

Date | Time : 1. Aug 2019 8:48:33 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 4

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
BOJSE	BODY JOINT SEALANT.	1	150.00	100%	150.00	10.50	160.50
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	160.00	120%	160.00	11.20	171.20
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	✓	250.00	17.50	267.50
BMC01D	REMOVE & INSTALL RADIATOR WITH FAN MOTOR	1	300.00	230%	300.00	21.00	321.00
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH AN MOTOR.	1	350.00	250%	350.00	24.50	374.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	350.00	300%	350.00	24.50	374.50
BKOT00A	PLACE VEHICLE TO BENCH FOR CHASSIS FRAME ALIGNMENT	1	1400.00	X	1400.00	98.00	1498.00
BMS00R	RENEW BOTH DRIVER & PASSENGER AIRBAG ASSY ECU &	1	1800.00	560%	1800.00	126.00	1926.00
BME00D	REMOVE & INSTALL ENGINE ASSY GEARBOX & OTHERS	1	1800.00	X	1800.00	126.00	1926.00
BKBH11M	RENEW BULKHEAD, WHEELHOUSE ASSY & ALIGN CHASSIS	1	2800.00	2240%	2800.00	196.00	2996.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2800.00	2250%	2800.00	196.00	2996.00
Sum Labor					12320.00	862.40	13,182.40

Survey By

Date & Time

Excess

Status

Signature

Total Amount 24,217.08 1,695.22 25,912.30

Total (Inclusive of GST) 25,912.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 1/8/2019 3:26:55 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0037141 / CHEN WEE
Chassis No: JHMGK3850JX222851
License No: SMA9169D
Mileage: 22448
Engine No: L13B11030797

Document No: SVO19051157
Printed By: ARYCHUA
Order Date: 8. August 2019
Order Time: 4:13:05 PM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO: 73170) OWNER: CHEN WEE KEONG OWNER INSURER: MSIG INSURANCE PTE LTD ACC DATE: 01/08/2019@01:55AM A:T/J JURONG T/HALL RD(L/P22)>JURONG E AVE1(L/P42) SURVEYED BY: MARCUS CHUA(LKK)02/08/2019@12:12PM REF NO: TP INSURER: INDIA INTERNATIONAL INS PTE LTD TP VEH: SHC1305D - HYUNDAI I40/BLUE/TAXI SUPPLIMENTARY ITERM PARTS & LABOR						
31531-T5A-003	COVERBATTERY To. 1	1	7.90	25	5.92	0.41	6.33
25560-5T0-003	WARMER COMPCVTF Bar	1	186.50	25	139.87	9.79	149.66
28660-R9L-003	SENSOR ASSYOIL PRESSURE one	1	67.30	25	50.47	3.53	54.00
90471-59C-000	PACKING10MM nee	1	2.50	25	1.87	0.13	2.00
71190-T5A-J50	BEAM UPPER,L.FR.BUMPER Bel	1	27.70	25	20.77	1.45	22.22
	SUM PARTS:				218.90	15.31	234.21
	TOTAL SGD				218.90	15.31	234.21

Total Payable (SGD)

234.21

GST Amount is calculated from individual line(s)

234.21



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0037141 / INDIA
Chassis No: JHMGK3850JX222851
License No: SMA9169D
Mileage: 22448
Engine No: L13B11030797

Document No: SVO19051157
Printed By: ARYCHUA
Order Date: 8. August 2019
Order Time: 4:13:05 PM
Service Advisor: ARY CHUA WAI NGEE

L=86420

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld	Amount	GST
	TP DIRECT SETTLEMENT (J/NO: 73170)							
	OWNER: CHEN WEE KEONG							
	OWNER INSURER: MSIG INSURANCE PTE LTD							
	ACC DATE: 01/08/2019@01:55AM							
	A-T/J JURONG T/HALL RD(L/P22)>JURONG E AVE1(L/P42)							
	SURVEYED BY: MARCUS CHUA(LKK)02/08/2019@12:12PM							
	REF NO:							
	TP INSURER: INDIA INTERNATIONAL INS PTE LTD							
	TP VEH: SHC1305D - HYUNDAI/40/BLUE/TAXI							
42700-T5S-M72	WHEEL,DISK AL 15X7	1	418.40	25	313.80	21.97	335.77	
60400-T5B-J00ZZ	BULKHEAD COMP,FR.	1	381.70	25	286.27	20.04	306.31	
60261-T5R-A00ZZ	PANELL,FR.FENDER	1	398.60	25	298.95	20.93	319.88	
60690-T5A-300ZZ	BRACKET COMP,L,FR.FENDER	1	41.70	25	31.27	2.19	33.46	
04684-T5A-300ZZ	EXTENSION SETL,FR.	1	94.40	25	70.80	4.96	75.76	
60710-T5A-800ZZ	MEMBER COMP,L,FR.WHEELHOUSE	1	59.00	25	44.25	3.10	47.35	
60912-T5A-300ZZ	PLATEL,FR.BACK	1	107.50	25	80.62	5.64	86.26	
60943-T5A-300ZZ	BRACKETL,FR.BUMPER BEAM	1	45.00	25	33.75	2.36	36.11	
60944-T5A-300ZZ	PLATEL SIDE FRAME	1	30.80	25	23.10	1.62	24.72	
60945-T5A-300ZZ	GUSSETL,FR.SIDE	1	46.10	25	34.57	2.42	36.99	
60120-TAR-000ZZ	HINGE COMP,R,HOOD	1	25.70	25	19.27	1.35	20.62	
60170-TAR-000ZZ	HINGE COMPL,HOOD	1	25.70	25	19.27	1.35	20.62	
80100-T5B-003	CONDENSER ASSY	1	704.40	25	528.30	36.98	565.28	
19010-5R1-901	RADIATOR COMP	1	1,211.20	25	908.40	63.59	971.99	
33150-T5A-J81	HEADLIGHT ASSY,L.	1	479.70	25	359.77	25.18	384.95	
17230-5R0-J01	CHAMBER ASSYRESONATOR	1	89.50	25	67.12	4.70	71.82	
17234-5R0-000	TUBERESONATOR CHAMBER	1	28.50	25	21.37	1.50	22.87	
50850-T9A-003	RUBBER ASSYTRANSMISSION MTG	1	111.40	25	83.55	5.85	89.40	
74150-T5L-T10	FENDER ASSY,L,FR	1	69.20	25	51.90	3.63	55.53	
74165-T5A-010	GUARDL,FR.SPLASH	1	23.40	25	17.55	1.23	18.78	
77930-T5A-J01	SENSOR ASSYFR.CRASH	2	63.40	25	95.10	6.66	101.76	
77960-T5A-W41	UNIT ASSYSRS	1	822.80	25	617.10	43.20	660.30	
77100-T5A-J10ZA	PANEL COMPINSTRUMENT	1	732.80	25	549.60	38.47	588.07	
77820-T5A-J80	MODULE ASSYPASSENGER	1	2,238.80	25	1,677.60	117.43	1,795.03	
77810-T5A-N81ZA	MODULE ASSYDRIVER	1	1,540.30	25	1,230.22	86.12	1,316.34	
81450-TAR-U01ZA	TONGUE ASSYR,FR.SEATBELT	1	454.80	25	341.10	23.88	364.98	
81850-TAR-U01ZA	TONGUE ASSYL,FR.SEATBELT	1	454.80	25	341.10	23.88	364.98	
71121-T5A-J50	BASE,FR.GRILLE HOOK	1	227.40	25	170.55	11.94	182.49	
71122-T5A-J50	MOLDING LOWER,FR.GRILLE	1	148.90	25	111.67	7.82	119.49	
71123-T5A-J50	MOLDING UPPER,FR.GRILLE	1	124.10	25	93.07	6.51	99.58	
71124-T5A-J50	STAY,FR.GRILLE	1	12.70	25	9.52	0.67	10.19	
71126-T5A-J50	EMBLEM BASE,FR.GRILLE	1	20.30	25	15.22	1.07	16.29	
75700-T5A-000	EMBLEM H	1	15.00	25	11.25	0.79	12.04	
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37	
04711-T5A-J50ZZ	FACE,FR.BUMPER	1	504.60	25	378.45	26.49	404.94	
71102-T5L-T50	LOWER GRILLE ASSY,FR.	1	137.90	25	103.42	7.24	110.66	
71108-T5A-J50	GARNISH,L,FR.BUMPER	1	29.00	25	21.75	1.52	23.27	
71119-T5A-J50	GARNISH,L,FR.LOWER GRILLE	1	8.70	25	6.52	0.46	6.98	
71130-T5A-J50ZZ	BEAM COMP,FR.BUMPER	1	213.00	25	159.75	11.18	170.93	
71140-T5A-J50	BEAM UPPER,R,FR.BUMPER	1	27.70	25	20.77	1.45	22.22	

WD=14



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3863 Fax: +65 6741 5022

255 Alexandra Road Singapore 159837. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0037141 / INDIA
Chassis No: JHMGK3850JX222851
License No: SMA9169D
Mileage: 22448
Engine No: L13B11030797

Document No: SVO19051157
Printed By: ARYCHUA
Order Date: 8. August 2019
Order Time: 4:13:05 PM
Service Advisor: ARY CHUA WAI NGEE

71193-T5A-000	SPACERR.FR.BUMPER	1	10.40	25	7.80	0.55	8.35
71198-T5A-000	SPACERL.FR.BUMPER	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIP.BUMPER	10	2.30	25	17.25	1.21	18.46
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	3	23.20	25	52.20	3.65	55.85
31531-T5A-003	COVERBATTERY	1	7.90	25	5.92	0.41	6.33
25560-5T0-003	WARMER COMPCVTF	1	186.50	25	139.87	9.79	149.66
28660-R9L-003	SENSOR ASSYOIL PRESSURE	1	67.30	25	50.47	3.53	54.00
90471-59C-000	PACKING10MM	1	2.50	25	1.87	0.13	2.00
71190-T5A-J50	BEAM UPPER,L.FR.BUMPER	1	27.70	25	20.77	1.45	22.22
		SUM PARTS:		9,554.74	668.86	10,223.60	
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BOBC	1864	1	100.00		100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)						
BOJSE	1864	1	100.00		100.00	7.00	107.00
	BODY JOINT SEALANT.						
BML01	0760	1	120.00		120.00	8.40	128.40
	INSPECT FR LIGHTING MECHANISMS & FOCUS						
	HEADLIGHTS.(N)						
BMC01D	1864	1	230.00		230.00	16.10	246.10
	REMOVE & INSTALL RADIATOR WITH FAN MOTOR.						
	PRESSURE TEST COOLING SYSTEM.(N)						
BMA01D	1864	1	250.00		250.00	17.50	267.50
	REMOVE & INSTALL A/C CONDENSER WITH AN MOTOR.						
	VACUUM & RECHARGE A/C GAS.(N)						
BP00R	1864	1	250.00		250.00	17.50	267.50
	APPLY BODY UNDERSIDE COATING (N).						
BC012R	0760	1	300.00		300.00	21.00	321.00
	RESET VEHICLE SMART ENTRY SYSTEM						
BMS00R	0760	1	560.00		560.00	39.20	599.20
	RENEW BOTH DRIVER & PASSENGER AIRBAG ASSY ECU & RESET SRS SYSTEM.(N)						
BKBH11M	1864	1	2,240.00		2,240.00	156.80	2,396.80
	RENEW BULKHEAD, WHEELHOUSE ASSY & ALIGN CHASSIS INCLUDING FITTINGS ON ATTACHMENT ITEMS.						
BP05R	EXT-YBH	1	2,250.00		2,250.00	157.50	2,407.50
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)						
		SUM LABOUR:		6,420.00	449.40	6,869.40	
BO-TOW-SW	TOWING SERVICE - B24466	1	50.00		50.00	3.50	53.50
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
		SUM EXT SERVICE:		230.00	16.10	246.10	
		TOTAL SGD		16,204.74	1,134.36	17,339.10	

Total Payable (SGD)

17,339.10



Bullbone Classic Diffuser - Pure Cotton (100ml)



5-Step Grooming & Detailing (4 Sessions)



Omp Seat Belt Cutter



Bullbone Polo Family Vent Clip Mayo Jasmine 4.3ml (0.15oz) + 1 Extra

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

1 owner , full agent service! Tiptop condition!



great value for this rare unit! Up to 95% loan
Car Empire StarAd

HIN LUNG AUTO
Ho Bee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars
30 years of car sale

Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

13 vehicles

honda jazz

Advanced Search ✕ Submit ▶

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	honda jazz		Any	Any	2018	Any	Any	Any	Available
	Honda Jazz	1.5A RS	\$70,800	\$7,420 /yr	09-Jan-2018	1,498 cc	33,000 km	Hatchback	Available
Don't Miss. Cheapest Unit, 5 Years Unlimited Mileage Warranty By Kah Motor, 1 Owner, Keyless Entry, Reverse Camera, Bluetooth, Accid...									
Posted: 01-Aug-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Honda Jazz	1.3A	\$61,800	\$6,840 /yr	23-Mar-2018	1,318 cc	29,137 km	Hatchback	Available
1 Owner! Maintained Only At Kah Motor With 5 Years Warranty! Immaculate Condition! High Trade In And In House Financing Available!...									
Posted: 01-Aug-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Honda Jazz	1.3A	\$64,800	\$7,070 /yr	03-May-2018	1,318 cc	9,700 km	Hatchback	Available
Full Loan Available, 5 Year Agent's Warranty By Kah Motors, Buy And Enjoy With A Peace Of Mind. Fully Maintained With Agent. Free Se...									
1axis									
Posted: 01-Aug-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Honda Jazz	1.3A	\$63,800	\$6,680 /yr	12-Sep-2018	1,318 cc	10,000 km	Hatchback	Available
High GMY At \$15803, High ARF \$5803,Price Negotiable, Lowest Depreciation, 3 Yr Servicing & 5 Yr Warranty! Pristine Condition 1 Owne...									
360 VR Cars									
Posted: 30-Jul-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Volkswagen's Touareg is a tech-laden beast Volkswagen's third generation Touareg is a massive improvement over its predecessor and is well-armed to take on the big boys. Find out more!								
	Honda Jazz	1.5A RS	\$77,988	\$7,680 /yr	20-Aug-2018	1,498 cc	8,000 km	Hatchback	Available
1 Owner. Agent Unit. Well Maintained, Very Low Mileage. Flexible Loan Scheme. Trade In Welcome. Call Now!									
Posted: 30-Jul-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Honda Jazz	1.3A	\$64,800	\$6,990 /yr	11-Jun-2018	1,318 cc	25,500 km	Hatchback	Available
100% Loan Available! Well Maintained, 5 Years Warranty With Kah Motors! Smooth And Efficient Engine. White On Black Interior! Parke...									
SKL Automobile Pte Ltd									
Posted: 29-Jul-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda									
	Honda Jazz	1.3A (OPC)	\$54,000	\$6,000 /yr	27-Feb-2018	1,318 cc	16,000 km	Hatchback	Available
OPC Unit, Very Well Maintained Unit. 1 Owner! 3 Years Free Servicing, 5 Years Unlimited Mileage Warranty Package! Conversion To Nor...									
360 VR Cars									

Compare

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

in

Reach 2M+ professionals in Singapore with LinkedIn Ads

See how

honda jazz

Price Range

Depreciation

2018

Vehicle Type

Submit

Advanced Search

Home > Used Cars > SKL Automobile Pte Ltd > Honda Jazz 1.3A

Honda Jazz 1.3A

Overview

Financial

Accessories

Similar

Research

Photos

Map

SKL

AUTOMOBILE PTE LTD

Member of:

Accredited by:

Price	\$64,800		
Depreciation	\$6,990 /yr View models with similar depre	Reg Date	11-Jun-2018 (8yrs 10mths 8days COE left)
Mileage	25,500 km (22.3k /yr)	Manufactured	2018
Road Tax	\$578 /yr	Transmission	Auto
Dereg Value	\$37,079 as of today (change)	OMV	\$15,715
COE	\$37,000	ARF	\$5,715
Engine Cap	1,318 cc	Power	73.0 kW (97 bhp)
Curb Weight	1,052 kg	No. of Owners	1
Type of Vehicle	Hatchback		

Features
1.3L DOHC I-VTEC Coupled With Earth Dreams CVT, Multi Function Steering, Cruise Control, Paddle Shifters, Traction Control, ABS And Dual SRS Airbags. View specs of the Honda Jazz (2014-2017)

Accessories
Sport Rim/Steering, Touch Screen DVR, Bluetooth, Cruise Control, Paddles Shift Control, Reverse Sensors, Retractable Side Mirror, 2 HDMI/USB Ports.

Description
100% Loan Available! Well Maintained, 5 Years Warranty With Kah Motors! Smooth And Efficient Engine, White On Black Interior! Parked Under Sheltered Parking! Call Now To View/Test Drive Today!

Category
PAP Car

Status
Available

Resources

Car Valuation - Free

Find out the market value of your existing car for free. Get started

Vehicle Evaluation

Compare



Price Chart

Summary

Price (\$20k)

70K

60K

50K

40K

30K

20K

10K

0K

Mar-18

May-18

Jul-18

Sep-18

Nov-18

Reg Date

Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

SKL Automobile Pte Ltd

» dealer's prelist

» 44 vehs sold | 27 vehs available

Address

210 Turf Club Road Lot B15

Search cars nearby this location

Location

Car Mall @ The Grandstand

Office No

64658811

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 679A

Vehicle Details

Vehicle No.: SMA9169D

Vehicle to be Exported: No

Intended Deregistration Date: 02 Aug 2019

Vehicle Make: HONDA

Vehicle Model: JAZZ 1.3 CVT

Primary Colour: Red

Manufacturing Year: 2018

Engine No.: L13B11030797

Chassis No.: JHMGK3850JX222851

Maximum Power Output: 73.0 kW (97 bhp)

Open Market Value: \$15,715.00

Original Registration Date: 07 Jun 2018

First Registration Date: 07 Jun 2018

Transfer Count: 0

Actual ARF Paid: \$5,715.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 06 Jun 2028

PARF Rebate Amount: \$4,286.00

Intended COE Rebate Details

COE Expiry Date: 06 Jun 2028

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$38,510.00

COE Rebate Amount: \$34,059.00

Total Rebate Amount: \$38,345.00

The information contained herein is correct as at 02 Aug 2019

OK

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 2 August 2019 9:42 AM
To: Ary Chua; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Liew Thye Wui; Faeaz
Subject: RE: TPDS-III: SMA9169D & SHC1305D DOA: 01/08/2019@01.55AM
Attachments: 3969_001.pdf; 1.jpg; 2.jpg; 3.jpg; 4.jpg; 5.jpg; 6.jpg; 7.jpg; 8.jpg; 9.jpg; 10.jpg; 11.jpg; 12.jpg; 13.jpg; 14.jpg; 15.jpg

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SMA9169D and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

P: Amy
T: 10-09a.m
V: In
E: ✓

From: Ary Chua [mailto:arychua@honda.com.sg]
Sent: 02 August, 2019 9:11 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>
Subject: RE: TPDS-III: SMA9169D & SHC1305D DOA: 01/08/2019@01.55AM

Dear Gabriel Wee,

Kindly Advise for this case Establish Liability? Can we do Direct Settlement.

- We Choose LKK Auto Consultants Pte Ltd

Hope to hear good news from your side.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Kah Motor Co. SDN BHD 15 Ubi Road 4 Singapore 408610

Phone: 6846 5673 Fax: 6748 0770 H/P: 81006306

Email Address : arychua@honda.com.sg

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 2 August 2019 9:00 AM
To: Ary Chua <arychua@honda.com.sg>

Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>

Subject: RE: TPDS-III: SMA9169D & SHC1305D DOA: 01/08/2019@01.55AM

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711 Tel: 6347 6100, Ext - 248

From: Ary Chua [mailto:arychua@honda.com.sg]

Sent: 01 August, 2019 4:34 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>

Subject: TPDS-III: SMA9169D & SHC1305D DOA: 01/08/2019@01.55AM

Dear OIC-III,

Kindly Establish Liability & Arrange for Car Survey on this Friday 02/08/2019@09.00am. Car is Tow In at Ubi Bodyshop today Thursday 01-08-2019@07.47am.

Survey then Proceed for Car Repair. Owner our got Front Video Footage.

Thank you.


Best Regards,

Ary Chua Wai Ngee

Kah Motor Co. SDN BHD 15 Ubi Road 4 Singapore 408610

Phone: 6846 5673 Fax: 6748 0770 H/P: 81006306

Email Address : arychua@honda.com.sg



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling

and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	02 Aug 2019 14:46	Clim Dtl Modified	Claimant's Name: -> -.	[A] Lau Shu Pei
2	02 Aug 2019 14:46	Clim Veh Model Changed	(206086) ADIVA AD1 200 190cc 3W.	[A] Lau Shu Pei
3	02 Aug 2019 14:46	Clim Created	Reg No: SMA9169D, Acct Date: 2019/08/01, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), Workshop: Kah Motor Co Sdn Bhd (Ubl)	[A] Lau Shu Pei
4	02 Aug 2019 14:46	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
5	02 Aug 2019 14:46	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/08/15	[A] Lau Shu Pei
6	02 Aug 2019 14:46	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
7	02 Aug 2019 14:46	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
8	02 Aug 2019 14:46	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Lau Shu Pei
9	02 Aug 2019 15:06	Clim Dtl Modified	Claimant's Name: - -> CHEN WEE KEONG. Claimant's ID: -> S1423679A.	[A] Lau Shu Pei
10	02 Aug 2019 15:06	Clim Veh Model Changed	(206086) -> (204368) HONDA JAZZ 1.3 (A).	[A] Lau Shu Pei
11	08 Aug 2019 12:43	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% Remarks: 3rd party making a right turn(traffic light in green arrow).	[A] CHEW HSIAO TONG
12	08 Aug 2019 14:25	Video Downloaded	Downloaded Video - Accident	[I] Lalitha Krishnan
13	08 Aug 2019 14:29	Video Downloaded	Downloaded Video - Accident	[I] Lalitha Krishnan
14	08 Aug 2019 14:38	Video Downloaded	Downloaded Video - Accident	[I] Lalitha Krishnan
15	08 Aug 2019 15:30	Video Downloaded	Downloaded Video - Accident	[I] Sherini Pillai
16	08 Aug 2019 15:31	Video Downloaded	Downloaded Video - Accident	[A] CHEW HSIAO TONG
17	08 Aug 2019 15:35	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/08/15	[I] Lalitha Krishnan
18	08 Aug 2019 15:35	Adj Mandate Set	Approved:0.00.	[I] Lalitha Krishnan
19	09 Aug 2019 13:35	Video Downloaded	Downloaded Video - Accident IV	[A] BRYAN TANI
20	13 Aug 2019 09:41	Video Downloaded	Downloaded Video - Accident	[I] Priya
21	13 Aug 2019 09:42	Video Downloaded	Downloaded Video - Accident IV	[I] Priya

Date From Date To Audit Type None Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History							
Bill Ref no	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2235756	05/08/2019 10:11	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	SMA9169D	SHC1305D	11.77
2240616	08/08/2019 14:25	Motor	India International	India International	SMA9169D	Lalitha Krishnan	xx.xx

			Insurance Pte Ltd (HQ)	Insurance Pte Ltd (HQ)			
2240929	08/08/2019 16:29	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	SMA9169D	Pool Chin Han Daniel	XX,XX

Hsiao Tong (LKKAUTO)

From: Ary Chua <arychua@honda.com.sg>
Sent: Thursday, 8 August 2019 5:22 PM
To: Hsiao Tong (LKKAUTO); Motor Claim - III; Admin-D (LKKAUTO); Manivel Priyadarshini; Mekavathanan Sarangapani
Cc: Liew Thye Wui; Faeaz; Admin A; VINCENTCHENWK@GMAIL.COM
Subject: Liability Clear: TPDS-III: SMA9169D & SHC1305D DOA: 01/08/2019@01.55AM *LKK REF: CC4/III19013562/Upb3

Dear Hsiao Tong,

We refer to the above accident and your e-mail on 08-08-2019.

We confirm that liability was clear and fully in our client's favour and he is wishing to do a direct settlement with INDIA INT Insurance regard to the above accident.

With this agreement, Kah Motor will proceed with the repairs to our client's vehicle and thereafter submit our final repair invoice and other supporting documents in relation to our client's claim. Upon receipt of the documents, INDIA INT Insurance will make payment in favour of 'Kah Motor Co. Sdn. Bhd.'

We trust the above clarifies.

Thank you.
Best Regards,

Ary Chua Wai Ngee
Kah Motor Co. SDN BHD 15 Ubi Road 4 Singapore 408610
Phone: 6846 5673 Fax: 6748 0770 H/P: 81006306
Email Address : arychua@honda.com.sg

From: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Sent: Thursday, 8 August 2019 3:58 PM
To: Ary Chua <arychua@honda.com.sg>
Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>; Sum Wai Teck <wtsum@honda.com.sg>; Admin A <admin-a@lkkauto.com>; VINCENTCHENWK@GMAIL.COM
Subject: RE: SECOND REMINDER Liability Clear: TPDS-III: SMA9169D & SHC1305D DOA: 01/08/2019@01.55AM *LKK REF: CC4/III19013562/Upb3

Without Prejudice
Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is clear subject to the BOLA guideline settlement.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle and admission of any liability to our Insured's part. The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor and approved by our principal.

Please note that all finalisation subject insurer's approval.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-

4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)

From: Ary Chua <arychua@honda.com.sg>

Sent: Thursday, 8 August 2019 12:30 PM

To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>; Motor Claim - III <motorclaim@iii.com.sg>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Manivel Priyadarshini <manivel@iii.com.sg>; VINCENTCHENWK@GMAIL.COM

Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>; Sum Wai Teck <wtsum@honda.com.sg>

Subject: SECOND REMINDER Liability Clear: TPDS-III: SMA9169D & SHC1305D DOA: 01/08/2019@01.55AM

Dear Priya,

Kindly Establish this Case Liability Issue? Can We do this case Direct Settlement? Survey already done by LKK Marcus Chua on 02/08/2019@12.12pm.

Now is waiting for III to Approval this Claim (owner wasted 7 days LOU/LOR)? Please take this as Priority Urgent case for this Approval Claim?

Car is Parking here without any repair by 7 days.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Kah Motor Co. SDN BHD 15 Ubi Road 4 Singapore 408610

Phone: 6846 5673 Fax: 6748 0770 H/P: 81006306

Email Address : arychua@honda.com.sg

From: Ary Chua

Sent: Wednesday, 7 August 2019 8:46 AM

To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>; Motor Claim - III <motorclaim@iii.com.sg>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Manivel Priyadarshini <manivel@iii.com.sg>

Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>

Subject: RE: TPDS-III: SMA9169D & SHC1305D DOA: 01/08/2019@01.55AM

Dear Priya,

Kindly Establish this Case Liability Issue? Can We do this case Direct Settlement? Survey already done by LKK Marcus Chua on 02/08/2019@12.12pm.

Now is waiting for III to Approval this Claim (owner wasted 5 days LOU/LOR)?

Thank you.

Best Regards,

Ary Chua Wai Ngee

Kah Motor Co. SDN BHD 15 Ubi Road 4 Singapore 408610

Phone: 6846 5673 Fax: 6748 0770 H/P: 81006306

Email Address : arychua@honda.com.sg

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>

Sent: Monday, 5 August 2019 12:23 PM

To: Ary Chua <arychua@honda.com.sg>

Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: TPDS-III: SMA9169D & SHC1305D DOA: 01/08/2019@01.55AM

Dear Ary,

We refer to the below email.

Please be informed that we are currently pending for our insured's report.

Kindly note that for liability, claim negotiation and settlement, please contact Hsiao Tong at DID: 6742 3197.

Our respective case handler will look into the matter and revert to you in due course.

Thank you

To check availability of the case handler , you may contact the undersigned.

Best Regards,

Shu Pei| Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ary Chua <arychua@honda.com.sg>

Sent: Friday, 2 August 2019 10:53 AM

To: Motor Claim - III <motorclaim@iii.com.sg>; SUR <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>

Subject: RE: TPDS-III: SMA9169D & SHC1305D DOA: 01/08/2019@01.55AM

Dear Priya,

Kindly Establish this Case Liability Issue? Can We do this case Direct Settlement?

Thank you.

Best Regards,

Ary Chua Wai Ngee

Kah Motor Co. SDN BHD 15 Ubi Road 4 Singapore 408610

Phone: 6846 5673 Fax: 6748 0770 H/P: 81006306

Email Address : arychua@honda.com.sg

From: Motor Claim - III <motorclaim@iii.com.sg>

Sent: Friday, 2 August 2019 9:42 AM

To: Ary Chua <arychua@honda.com.sg>; 'sur@lkkauto.com' <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>

Subject: RE: TPDS-III: SMA9169D & SHC1305D DOA: 01/08/2019@01.55AM

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SMA9169D and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711 Tel: 6347 6100, Ext - 248

From: Ary Chua [<mailto:arychua@honda.com.sg>]
Sent: 02 August, 2019 9:11 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>
Subject: RE: TPDS-III: SMA9169D & SHC1305D DOA: [01/08/2019@01.55AM](#)

Dear Gabriel Wee,
Kindly Advise for this case Establish Liability? Can we do Direct Settlement.

- We Choose LKK Auto Consultants Pte Ltd

Hope to hear good news from your side.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Kah Motor Co. SDN BHD 15 Ubi Road 4 Singapore 408610

Phone: 6846 5673 Fax: 6748 0770 H/P: 81006306

Email Address : arychua@honda.com.sg

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 2 August 2019 9:00 AM
To: Ary Chua <arychua@honda.com.sg>
Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>
Subject: RE: TPDS-III: SMA9169D & SHC1305D DOA: [01/08/2019@01.55AM](#)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711 Tel: 6347 6100, Ext - 248

From: Ary Chua [<mailto:arychua@honda.com.sg>]
Sent: 01 August, 2019 4:34 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>
Subject: TPDS-III: SMA9169D & SHC1305D DOA: [01/08/2019@01.55AM](#)

Dear OIC-III,

Kindly Establish Liability & Arrange for Car Survey on this Friday [02/08/2019@09.00am](#). Car is Tow In at Ubi Bodyshop today Thursday [01-08-2019@07.47am](#).

Survey then Proceed for Car Repair. Owner our got Front Video Footage.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Kah Motor Co. SDN BHD 15 Ubi Road 4 Singapore 408610

Phone: 6846 5673 Fax: 6748 0770 H/P: 81006306

Email Address : arychua@honda.com.sg



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	02 Aug 2019 14:46	Cim Dtl Modified	Claimant's Name: -> -.	[A] Lau Shu Pei
2	02 Aug 2019 14:46	Cim Veh Model Changed	(206086) ADIVA AD1 200 190cc 3W.	[A] Lau Shu Pei
3	02 Aug 2019 14:46	Cim Created	Reg No: SMA9169D. Acct Date: 2019/08/01. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). Workshop: Kah Motor Co Sdn Bhd (Ubl)	[A] Lau Shu Pei
4	02 Aug 2019 14:46	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
5	02 Aug 2019 14:46	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/08/15	[A] Lau Shu Pei
6	02 Aug 2019 14:46	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
7	02 Aug 2019 14:46	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
8	02 Aug 2019 14:46	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Lau Shu Pei
9	02 Aug 2019 15:06	Cim Dtl Modified	Claimant's Name: - -> CHEN WEE KEONG. Claimant's ID: -> S1423679A.	[A] Lau Shu Pei
10	02 Aug 2019 15:06	Cim Veh Model Changed	(206086) -> (204368) HONDA JAZZ 1.3 (A).	[A] Lau Shu Pei
11	08 Aug 2019 12:43	Adj Mandate Request	CurReq:0.00:PODS Liability: 100% Remarks: 3rd party making a right turn(traffic light in green arrow).	[A] CHEW HSIAO TONG
12	08 Aug 2019 14:25	Video Downloaded	Downloaded Video - Accident	[I] Lalitha Krishnan
13	08 Aug 2019 14:29	Video Downloaded	Downloaded Video - Accident	[I] Lalitha Krishnan
14	08 Aug 2019 14:38	Video Downloaded	Downloaded Video - Accident	[I] Lalitha Krishnan
15	08 Aug 2019 15:30	Video Downloaded	Downloaded Video - Accident	[I] Sherini Pillai
16	08 Aug 2019 15:31	Video Downloaded	Downloaded Video - Accident	[A] CHEW HSIAO TONG
17	08 Aug 2019 15:35	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/08/15	[I] Lalitha Krishnan
18	08 Aug 2019 15:35	Adj Mandate Set	Approved:0.00.	[I] Lalitha Krishnan
19	09 Aug 2019 13:35	Video Downloaded	Downloaded Video - Accident IV	[A] BRYAN TANI
20	13 Aug 2019 09:41	Video Downloaded	Downloaded Video - Accident	[I] Priya
21	13 Aug 2019 09:42	Video Downloaded	Downloaded Video - Accident IV	[I] Priya
22	13 Aug 2019 17:16	Video Downloaded	Downloaded Video - Accident IV	[A] CHEW HSIAO TONG
23	16 Oct 2019 10:33	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
24	16 Oct 2019 10:33	Cim Dtl Modified	Insured Name: -> -. Insured ID: -> -.	[A] JOANNE LEE KHANG MIN
25	16 Oct 2019 10:33	Cim Dtl Modified	JPJ Reg. Date: -> 2018/06/07.	[A] JOANNE LEE KHANG MIN
26	16 Oct 2019 10:33	Cim Details Notified		[A] JOANNE LEE KHANG MIN

AUDIT TRAIL

No.	On	Audit	Remarks	By
27	16 Oct 2019 12:10	Adj Mandate Request	Cur,Req:18139,07:PODS Liability: 100% *Quantum: (a)CORw/GST: \$17,339.07 + (b)L OU(16days x \$50.00): \$800.00 = Total: \$18,139.07 *Vehicle Model: Honda Jazz (1318 cc) *14 recommendation repair days + 1Sunday + 1PH = 16days *For your approval pl ease.	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2235756	05 Aug 2019 10:11:24	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	SMA9169D	SHC1305D	11.77
2240616	08 Aug 2019 14:25:21	Video Upload	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	SMA9169D	Lalitha Krishnan	XX.XX
2240929	08 Aug 2019 16:29:37	Video Upload	Motor	India International Insurance Pte Ltd (HQ)	India International Insurance Pte Ltd (HQ)	SMA9169D	Pooi Chin Han Daniel	XX.XX
2314506	16 Oct 2019 10:33:11	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMA9169D	SHC1305D	11.77

Print Received Message

This mail is associated with :

***SMA9169D (MCT19080002)**
[SHC1305D]

TP

CHEN WEE KEONG

Aug 1 2019 12:00AM

[-]

Kah Motor Co Sdn Bhd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 18/11/2019 10:28 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$18139.07) - SMA9169D - Claim Handler: Priya

Approved:18139.07:Request TP WS to issue Tax invoice for Repairs in III's favour

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Tuesday, 19 November 2019 7:53 AM
To: Faeaz
Cc: Marcus Chua (LKKAUTO); Lim Chou Siong; Admin A
Subject: RE: LKK C/O INDIA- Submission of Third Party Direct Settlement, Y/R: CC4/III19013562/UPB3 : O/R: SMA9169D
Attachments: DV_SMA9169D.pdf

Without Prejudice

Dear Sirs/Mdm,

Thank you for your patience.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$17,339.07
2. Loss of Use (16days x \$50.00)	\$ 800.00
Total	\$18,139.07

If our offer is acceptable by your client, please duly sign the DV enclosed and return the original copy to us (LKK) for our necessary action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Faeaz <faeaz@honda.com.sg>
Sent: Saturday, 16 November 2019 12:22 PM
To: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Cc: Marcus Chua (LKKAUTO) <MarcusChua@lkkauto.com>; Lim Chou Siong <cslim@honda.com.sg>; Admin A <admin-a@lkkauto.com>; Reports (LKKAUTO) <report@lkkauto.com>
Subject: RE: LKK C/O INDIA- Submission of Third Party Direct Settlement, Y/R: CC4/III19013562/UPB3 : O/R: SMA9169D



Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

15 Ubi Road 4

Singapore 408610

Tel : +65 6841 3838

Fax : +65 6748 0770

www.honda.com.sg

19 November 2019

Your ref : MCT19080002

Our ref : SMA9169D

LKK Auto Consultants Pte Ltd

Blk 51 Paya Ubi Industrial Park Ubi Ave 1

#02-25

Singapore 408933

Attn: Motor Claims Dept / Hsiao Tong

Dear Sir / Madam,

ACCIDENT INVOLVING SMA9169D AND SHC1305D ON 01.08.19

We herewith enclosed the original Express Settlement discharge voucher duly signed for your necessary action.

Kindly let us have your cheque payment of **SS\$17,339.10 (nett)** in favour of **Kah Motor Co. Sdn. Bhd.** and **SS\$800.00 (nett)** in favour of **Chen Wee Keong as soon as possible**.

Your prompt settlement would be much appreciated.

Thank you.

Yours sincerely,

Cslim

DID: 6514 5684

cslim@honda.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Aug 2019 Edit Reg		02 Aug 2019 00:00 Edit Adj Rpt	S\$16,204.74 Edit Estimates	S\$16,204.74 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	-, ID: -		
Main Claimant:	CHEN WEE KEONG, ID: S1423679A		
Vehicle Reg. No.:	SMA9169D	Date of Loss:	01/08/2019 00:00 - :59 [13 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT19080002	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHC1305D	Policy No. (Claimant):	A804780812QMY
		Excess:	
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 15/08/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- III_SG (18/11/2019): Alert - Adj Mandate Approved (S\$18139.07) - SMA9169D - Claim Handler: Priya
- III_SG (08/08/2019): Alert - Adj Mandate Approved (S\$0.00) - SMA9169D - Claim Handler: Priya

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMA9169D (MCT19080002)
[SHC1305D]
TP
CHEN WEE KEONG
Aug 1 2019 12:00AM
[-]
Kah Motor Co Sdn Bhd

Upload Documents Upload Photos Compose New Letter		View View in Browser
Video		1 per page ☐
No	Finalized On	India International Insurance Pte Ltd (HQ)
1	08/08/19 14:25	Video - Accident
2	08/08/19 16:29	Video - Accident IV
Photos/Images		3 per page ☐
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	08/08/19 12:41	General View
2	08/08/19 12:41	General View
3	08/08/19 12:41	General View
4	08/08/19 12:41	General View
5	08/08/19 12:41	General View
6	08/08/19 12:41	General View
7	08/08/19 12:41	General View
8	08/08/19 12:41	General View
9	08/08/19 12:41	General View
10	08/08/19 12:42	General View
11	08/08/19 12:42	General View
12	08/08/19 12:42	General View
13	08/08/19 12:42	General View
14	08/08/19 12:42	General View
15	08/08/19 12:42	General View
16	08/08/19 12:42	General View
17	08/08/19 12:42	General View
18	08/08/19 12:42	General View
19	08/08/19 12:42	General View
20	08/08/19 12:42	General View
21	08/08/19 12:42	General View
22	08/08/19 12:42	General View
23	08/08/19 12:42	General View
24	08/08/19 12:42	General View
25	08/08/19 12:42	General View
26	08/08/19 12:42	General View
27	08/08/19 12:42	General View
28	08/08/19 12:42	General View
29	08/08/19 12:42	General View
30	08/08/19 12:42	General View
31	08/08/19 12:42	General View
32	08/08/19 12:42	General View
33	08/08/19 12:42	General View
34	08/08/19 12:42	General View
35	08/08/19 12:42	General View
36	08/08/19 12:42	General View
37	08/08/19 12:42	General View
38	08/08/19 12:42	General View
39	08/08/19 12:42	General View

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
40	08/08/19 12:42	General View		☒
41	08/08/19 12:42	General View		☒
42	08/08/19 12:42	General View		☒
43	08/08/19 12:42	General View		☒
44	08/08/19 12:42	General View		☒
45	08/08/19 12:42	General View		☒
46	08/08/19 12:42	General View		☒
47	08/08/19 12:42	General View		☒
48	08/08/19 12:42	General View		☒
49	08/08/19 12:42	General View		☒
50	08/08/19 12:42	General View		☒
51	08/08/19 12:42	General View		☒
52	08/08/19 12:42	General View		☒
53	08/08/19 12:42	General View		☒
54	08/08/19 12:42	General View		☒
55	08/08/19 12:42	General View		☒
56	08/08/19 12:42	General View		☒
57	08/08/19 12:42	General View		☒
58	08/08/19 12:42	General View		☒
59	08/08/19 12:42	General View		☒
60	08/08/19 12:42	General View		☒
61	08/08/19 12:42	General View		☒
62	08/08/19 12:42	General View		☒
63	08/08/19 12:42	General View		☒
64	08/08/19 12:42	General View		☒
65	08/08/19 12:42	General View		☒
66	08/08/19 12:42	General View		☒
67	08/08/19 12:42	General View		☒
68	08/08/19 12:42	General View		☒
69	08/08/19 12:42	General View		☒
70	08/08/19 12:42	General View		☒
71	08/08/19 12:42	General View		☒
72	08/08/19 12:42	General View		☒
73	08/08/19 12:42	General View		☒
74	08/08/19 12:42	General View		☒
75	08/08/19 12:42	General View		☒
76	08/08/19 12:42	General View		☒
77	08/08/19 12:42	General View		☒
78	08/08/19 12:42	General View		☒
79	08/08/19 12:42	General View		☒
80	08/08/19 12:42	General View		☒
81	08/08/19 12:42	General View		☒
82	08/08/19 12:42	General View		☒
83	08/08/19 12:42	General View		☒
84	08/08/19 12:42	General View		☒
85	08/08/19 12:42	General View		☒
86	08/08/19 12:42	General View		☒
87	08/08/19 12:42	General View		☒
88	08/08/19 12:42	General View		☒
89	08/08/19 12:42	General View		☒
90	08/08/19 12:42	General View		☒
91	08/08/19 12:42	General View		☒
92	08/08/19 12:42	General View		☒
93	08/08/19 12:42	General View		☒
94	08/08/19 12:42	General View		☒
95	08/08/19 12:42	General View		☒

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
96	08/08/19 12:42	General View	 Load JPG	☒
97	08/08/19 12:42	General View	 Load JPG	☒
98	08/08/19 12:42	General View	 Load JPG	☒
99	08/08/19 12:42	General View	 Load JPG	☒
100	08/08/19 12:42	General View	 Load JPG	☒
101	08/08/19 12:42	General View	 Load JPG	☒
102	08/08/19 12:42	General View	 Load JPG	☒
103	08/08/19 12:42	General View	 Load JPG	☒
104	08/08/19 12:42	General View	 Load JPG	☒
105	16/10/19 11:43	Reinspection Photo	 Load JPG	☒
106	16/10/19 11:43	Reinspection Photo	 Load JPG	☒
107	16/10/19 11:43	Reinspection Photo	 Load JPG	☒
108	16/10/19 11:43	Reinspection Photo	 Load JPG	☒
109	16/10/19 11:43	Reinspection Photo	 Load JPG	☒
110	16/10/19 11:43	Reinspection Photo	 Load JPG	☒
111	16/10/19 11:43	Reinspection Photo	 Load JPG	☒
112	16/10/19 11:43	Reinspection Photo	 Load JPG	☒
113	16/10/19 11:43	Reinspection Photo	 Load JPG	☒
114	16/10/19 11:43	Reinspection Photo	 Load JPG	☒
115	16/10/19 11:44	Reinspection Photo	 Load JPG	☒
116	16/10/19 11:44	Reinspection Photo	 Load JPG	☒
117	16/10/19 11:44	Reinspection Photo	 Load JPG	☒
118	16/10/19 11:44	Reinspection Photo	 Load JPG	☒
119	16/10/19 11:44	Reinspection Photo	 Load JPG	☒
120	16/10/19 11:44	Reinspection Photo	 Load JPG	☒
121	16/10/19 11:44	Reinspection Photo	 Load JPG	☒
122	16/10/19 11:44	Reinspection Photo	 Load JPG	☒
123	16/10/19 11:44	Reinspection Photo	 Load JPG	☒
124	16/10/19 11:44	Reinspection Photo	 Load JPG	☒
125	16/10/19 11:44	Reinspection Photo	 Load JPG	☒
126	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
127	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
128	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
129	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
130	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
131	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
132	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
133	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
134	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
135	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
136	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
137	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
138	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
139	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
140	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
141	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
142	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
143	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
144	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
145	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
146	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
147	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
148	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
149	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
150	16/10/19 11:47	Reinspection Photo	 Load JPG	☒
151	16/10/19 11:47	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
152	16/10/19 11:47	Reinspection Photo		☒
153	16/10/19 11:47	Reinspection Photo		☒
154	16/10/19 11:47	Reinspection Photo		☒
155	16/10/19 11:47	Reinspection Photo		☒
156	16/10/19 11:47	Reinspection Photo		☒
157	16/10/19 11:47	Reinspection Photo		☒
158	16/10/19 11:47	Reinspection Photo		☒
159	16/10/19 11:47	Reinspection Photo		☒
160	16/10/19 11:47	Reinspection Photo		☒
161	16/10/19 11:47	Reinspection Photo		☒
162	16/10/19 11:47	Reinspection Photo		☒
163	16/10/19 11:47	Reinspection Photo		☒
164	16/10/19 11:47	Reinspection Photo		☒
165	16/10/19 11:47	Reinspection Photo		☒
166	16/10/19 11:47	Reinspection Photo		☒
167	16/10/19 11:47	Reinspection Photo		☒
168	16/10/19 11:47	Reinspection Photo		☒
169	16/10/19 11:47	Reinspection Photo		☒
170	16/10/19 11:47	Reinspection Photo		☒
171	16/10/19 11:47	Reinspection Photo		☒
172	16/10/19 11:47	Reinspection Photo		☒
173	16/10/19 11:47	Reinspection Photo		☒
174	16/10/19 11:47	Reinspection Photo		☒
175	16/10/19 11:47	Reinspection Photo		☒
176	16/10/19 11:47	Reinspection Photo		☒
177	16/10/19 11:47	Reinspection Photo		☒
178	16/10/19 11:47	Reinspection Photo		☒
179	16/10/19 11:47	Reinspection Photo		☒
180	16/10/19 11:47	Reinspection Photo		☒
181	16/10/19 11:47	Reinspection Photo		☒
182	16/10/19 11:47	Reinspection Photo		☒
183	16/10/19 11:47	Reinspection Photo		☒
184	16/10/19 11:47	Reinspection Photo		☒
185	16/10/19 11:47	Reinspection Photo		☒
186	16/10/19 11:47	Reinspection Photo		☒
187	16/10/19 11:47	Reinspection Photo		☒
188	16/10/19 11:47	Reinspection Photo		☒
189	16/10/19 11:47	Reinspection Photo		☒
190	16/10/19 11:47	Reinspection Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/08/19 15:07	EMAIL FROM III DD 02082019		☐
2	02/08/19 15:07	TP EST & GIA REPORT		☐
3	05/08/19 18:17	TP ESTIMATE- MARKED		☐
4	16/10/19 12:03	LOD		☐
5	16/10/19 12:03	Authorisation to Act		☐
6	16/10/19 12:03	Workshop Invoice		☐
7	29/11/19 09:30	DISCHARGE VOUCHER		☐
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	08/08/19 09:03	Singapore Accident Statement		☐
2	01/11/19 12:05	Police Report		☐

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19013562/UPB3Q2

Date: 29/11/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant: SMA9169D Insured Vehicle No: SHC1305D
 Vehicle No: SMA9169D Date of Loss: 01/08/2019 Nature of Claim: TP Claim No: MCT19080002

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMA9169D Engine No: L13B11030797
 Make & Model: HONDA JAZZ, 1.3 (A) Chassis No: JHMGK3850JX222851
 Reg. Date: 07/06/2018 (Man. Year: 2018) Odometer: 22447 km
 Colour: Red
 Engine Capacity: 1318 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/65 R15 Rear Tyre Size: 175/65 R15
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,945.98	9,574.74	2,371.24	19.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,490.00	6,630.00	5,860.00	46.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,435.98	16,204.74	8,231.24	33.68
+ GST 7.00/7.00% (S\$)	1,710.52	1,134.33	576.19	33.69
Nett Amount (S\$)	26,146.50	17,339.07	8,807.43	33.68
+ Loss of Use (16.0 x S\$50.00/day) (S\$)		800.00		
Nett Liability (S\$)		18,139.07		

INSPECTION

Date of Assignment: 02/08/2019
 Date Inspected: 02/08/2019 Inspected At: Kah Motor Co Sdn Bhd (Ubi)
 15 Ubi Road 4
 Singapore 408610
 Estimated Period of Repair: 14.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Oct 2019)
Parts:	144	HONDA JAZZ 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA9169D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WHEEL,DISK AL 15X7 N/S	Cut	313.80 FS	*313.80 FS
2	1		*DISK ALUMINIUM WHEEL,16X6	Not Necessary	579.22 FS	*- FS
3	1		*BULKHEAD COMP,FR	Bent	286.27 FS	*286.27 FS
4	1		*PANELL.FR.FENDER	Dented	298.95 FS	*298.95 FS
5	1		*BRACKET COMP,L.FR.FENDER	Bent	31.27 FS	*31.27 FS
6	1		*EXTENSION SETL.FR	Bent	70.80 FS	*70.80 FS
7	1		*BASE COMP,BATTERY	Not Necessary	51.52 FS	*- FS
8	1		*SET MEMBER COMP,L.FR.WHEELHOUSE	Bent	44.25 FS	*44.25 FS
9	1		*PLATEL.FR.BACK	Bent	80.62 FS	*80.62 FS
10	1		*BRACKETL.FR.BUMPER BEAM	Bent	33.75 FS	*33.75 FS
11	1		*PLATEL.SIDE FRAME	Bent	23.10 FS	*23.10 FS
12	1		*GUSSETL.FR.SIDE	Distorted	34.57 FS	*34.57 FS
13	1		*HOOD COMP	Repair	403.12 FS	*- FS
14	1		*HINGE COMP,R.HOOD	Bent	19.27 FS	*19.27 FS
15	1		*HINGE COMPL.HOOD	Bent	19.27 FS	*19.27 FS
16	1		*LOCK ASSY HOOD	Serviceable	31.95 FS	*- FS
17	1		*INSULATORHOOD	Not Necessary	65.77 FS	*- FS
18	1		*GARNISH ASSYHOOD	Not Necessary	31.05 FS	*- FS
19	1		*GARNISH ASSYL.HOOD	Not Necessary	10.87 FS	*- FS
20	1		*CONDENSER ASSY	Twisted	528.30 FS	*528.30 FS
21	1		*HOSE COMPSUCTION	Not Necessary	93.00 FS	*- FS
22	1		*HOSE COMPDISCHARGE	Not Necessary	108.60 FS	*- FS
23	1		*PIPE COMPRECEIVER	Not Necessary	83.92 FS	*- FS
24	1		*RADIATOR COMP	Bent / Punctured	908.40 FS	*908.40 FS
25	1		*SHROUD COMP	Not Necessary	66.97 FS	*- FS
26	1		*FANCOOLING	Not Necessary	19.72 FS	*- FS
27	1		*FANCOOLING	Not Necessary	36.90 FS	*- FS
28	1		*SHROUD COMP	Not Necessary	34.72 FS	*- FS
29	1		*HEADLIGHT ASSY,R	Not Necessary	359.77 FS	*- FS
30	1		*HEADLIGHT ASSY,L	Broken	359.77 FS	*359.77 FS
31	1		*SEPARATOR ,SPLASH INTAKE	Not Necessary	23.25 FS	*- FS
32	1		*DUCT ASSY,AIR INTAKE	Not Necessary	16.20 FS	*- FS
33	1		*CHAMBER ASSYRESONATOR	Cracked	67.12 FS	*67.12 FS
34	1		*TUBERESONATOR CHAMBER	Cracked	21.37 FS	*21.37 FS
35	1		*RUBBER ASSYTRANSMISSION MTG	Torn	83.55 FS	*83.55 FS
36	1		*COVER ,ENG UNDER	Not Necessary	64.50 FS	*- FS
37	1		*FENDER ASSY,L.FR	Distorted	51.90 FS	*51.90 FS
38	1		*GUARDL.FR.SPLASH	Torn	17.55 FS	*17.55 FS
39	14		*CLIP,BUMPER	Repeated	24.15 FS	*- FS
40	2		*SENSOR ASSYFR ,CRASH	Activated	95.10 FS	*95.10 FS
41	1		*UNIT ASSYSRS	Activated	617.10 FS	*617.10 FS
42	1		*PANEL COMPINSTRUMENT	Buckled	549.60 FS	*549.60 FS
43	1		*MODULE ASSYPASSENGER	Activated	1,677.60 FS	*1,677.60 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*MODULE ASSYDRIVER	Activated	1,230.22 FS	*1,230.22 FS
45	1		*TONGUE ASSYR.FR.SEATBELT	Activated	341.10 FS	*341.10 FS
46	1		*TONGUE ASSYL.FR.SEATBELT	Activated	341.10 FS	*341.10 FS
47	1		*COVER,FR.GRILLE	Not Necessary	9.45 FS	*- FS
48	1		*BASE ,FR.GRILLE HOOK	Cracked	170.55 FS	*170.55 FS
49	1		*MOLDING LOWER ,FR.GRILLE	Cracked	111.67 FS	*111.67 FS
50	1		*MOLDING UPPER ,FR.GRILLE	Cracked	93.07 FS	*93.07 FS
51	1		*STAY ,FR.GRILLE	Bent	9.52 FS	*9.52 FS
52	1		*SCREEN ,R.FR.GRILLE	Not Necessary	6.07 FS	*- FS
53	1		*EMBLEM BASE,FR.GRILLE	Necessary	15.22 FS	*15.22 FS
54	1		*EMBLEM H	Necessary	11.25 FS	*11.25 FS
55	1		*NUTPUSH 3MM (2 PCS)	Necessary	3.15 FS	*3.15 FS
56	1		*FACE,FR.BUMPER	Distorted	378.45 FS	*378.45 FS
57	1		*LOWER GRILLE ASSY,FR	Twisted	103.42 FS	*103.42 FS
58	1		*GARNISH,L.FR.BUMPER	Twisted	21.75 FS	*21.75 FS
59	1		*GARNISH,L.FR.LOWER GRILLE	Twisted	6.52 FS	*6.52 FS
60	1		*BEAM COMP,FR.BUMPER	Bent	159.75 FS	*159.75 FS
61	1		*BEAM UPPER ,R.FR.BUMPER	Bent	20.77 FS	*20.77 FS
62	1		*BASE,FR.LICENCE PLATE	Not Necessary	36.75 FS	*- FS
63	1		*BEAM UPPER,L.FR.BUMPER	Not Necessary	20.77 FS	*- FS
64	1		*SPACERR.FR.BUMPER	Bent	7.80 FS	*7.80 FS
65	1		*SPACERL.FR.BUMPER	Bent	7.80 FS	*7.80 FS
66	1		*CLIP,BUMPER (10 PCS)	Necessary	17.25 FS	*17.25 FS
67	3		*COOLANT ANTI-FREEZE TYRE 2	Necessary	52.20 FS	*52.20 FS
68	1		*NUMBER PLATE WITH CASING -L	Not Necessary	45.00 FS	*- FS
69	1		*YOKOHAMA TYRE	Serviceable	108.00 FS	*- FS
70	1		*SUNDRIES	Necessary	60.00 FS	*20.00 FS
71	1		*COVERBATTERY	Torn	5.92 FS	*5.92 FS
72	1		*WARMER COMPCVTF	Bent	139.87 FS	*139.87 FS
73	1		*SENSOR ASSYOIL PRESSURE	Cracked	50.47 FS	*50.47 FS
74	1		*PACKING 10MM	Necessary	1.87 FS	*1.87 FS
75	1		*BEAM UPPER ,L.FR.BUMPER	Bent	20.77 FS	*20.77 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	11,945.98	9,574.74
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	BODY UNDERSIDE COATING	New	100.00	100.00
2	BODY JOINT SEALANT	New	150.00	100.00
3	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	160.00	120.00
4	APPLY BODY UNDERSIDE COATING	New	250.00	250.00
5	REMOVE & INSTALL RADIATOR WITH FAN MOTOR	New	300.00	230.00
6	REMOVE & INSTALL A/C CONDENSER WITH AN MOTOR	New	350.00	250.00
7	RESET VEHICLE SMART ENTRY SYSTEM	New	350.00	300.00
8	PLACE VEHICLE TO BENCH FOR CHASSIS FRAME ALIGNMENT	New	1,400.00	0.00
9	RENEW BOTH DRIVER & PASSENGER AIRBAG ASSY ECU &	New	1,800.00	560.00
10	REMOVE & INSTALL ENGINE ASSY GEARBOX & OTHERS	New	1,800.00	0.00
11	RENEW BULKHEAD ,WHEELHOUSE ASSY & ALIGN CHASSIS	New	2,800.00	2,240.00
12	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	2,800.00	2,250.00
13	TOWING CHARGE	New	50.00	50.00
14	WHEEL ALIGNMENT	New	180.00	180.00
Gross Labour Cost (\$\$)			12,490.00	6,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >